2-DIST B.I.N. **51P**

STRUCTURES INSPECTION FIELD REPORT ROUTINE & SPECIAL MEMBER INSPECTION

BR. DEPT. NO. **P-10-048**

CITY/TOWN PITTSFIELD			8ST						lo. POINT	41-STATUS P:POSTED				SP. DATE
				I				 						2024
07-FACILITY CARRIED HWY PECKS RD				MEMORIAL NAME/LOCAL NAME 27-				YR BUILT 1915	106-YR REBUILT 0000	YR F		3'D (NO	ON 106)	
06-FEATURES INTERSECTED				26-FUNCTIONAL CLASS DIST. BRIDG				E INSPECTI	ON ENGINEER	L.A.	Briggs			
WATER ONOTA BR	ROOK			Urban Collector										
43-STRUCTURE TYPE				22-OWNER	21-MAI	NTAINER	TEAM	I LEAD	DER R. Manc	ari				
302 : Steel Stringer/Girder				City/ Municipal Highway A	City/ M Highw		I							
107-DECK TYPE 1 : Concrete Cast-i	n-Pla	ıce		WEATHER Sunny TEMP. (air) TEAM MEME M. RANZ										
ITEM 58	_		ITE	M 59					ITEM	60				
		SUPI	ERSTRUCTU	RE	3	」	EF	SUBST	RUCTURE		6		DEF	
1.Wearing Surface	8	-		ngers		N	7[-	1. Abut		Dive	Cur	6	<i>D2</i> ,
2. Deck Condition	4	S-A	2.Floorbeams		N		-	a. Pedes	tals	N	N		-	
3.Stay in place forms	4	S-A	3.Flo	or System Braci	ng	N		_	b. Bridge		N N	6	.	M-P
4. Curbs	7	_	4.Gird	ders or Beams		3	s	-A	c. Backw		N	6	•	M-P
	N	_	5.Tru	sses - General		N		-	e. Wingw		N	6		-
5.Median	Н		a.	Upper Chords		N		-		Paving/Rip-Rap	N	N 5	.	- M-P
6. Sidewalks		-	b.	Lower Chords		N		-	g. Pointin		N	Н	•	-
7.Parapets	N	-	c.	Web Members		N		-	i. Piles	i. Piles		N		-
8.Railing	5	S-A	d.	Lateral Bracing	N			_	j. Scour k. Settlement		N	5 7	.	M-P
9.Anti Missile Fence	7	-	е.	Sway Bracings		N		-	I.		N	N	.	
10.Drainage System	6	-	f.	Portals		N		-	m.		N	N		-
11.Lighting Standards	N	-	a	End Posts		N		-	2. Piers	or Bents			N	
12.Utilities	6	-		& Hangers		N	T		a. Pedes	tals	N N	N N	.	-
13.Deck Joints	N	-		nn Pit's, Gussets & Angles		ales N		_	b. Caps c. Colum	ıns	N	N		-
14.	N	_		er Plates		N	+	_	d. Stems/Webs/Pierwalls		N	N		-
15.			9.Bea	ring Devices		6		_	e. Pointi		N N	N N	. }	
	N	-		aphragms/Cross	s Fram		+		f. Footing. Piles	<u>g</u>	N	N		-
16.	N	-		vets & Bolts		7	+	_	h. Scour		N	N		-
ı	E	w	12. W			N			i. Settlei	ment	N	N	.	
CURB REVEAL (In millimeters)	80	Н		ember Alignmen		5	-	- I-P	j. k.		N N	N N	.	
(III IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII				int/Coating		2			3. Pile I	Bents	-		N	
APPROACHES		DEF	15.	imizcoating		N		l-P	a. Pile Ca	aps	N	N		-
a. Appr. Pavement Condition	8	-	15.			- 17		-	b. Piles		N	N	.	
b. Appr. Roadway Settlement	8	-	Year	Painted		X				nal Bracing ontal Bracing	N N	N N	. }	
c. Appr. Sidewalk Settlement	Н	-	COLLI	SION DAMAGE:	Please	explain			e. Faster		N	N		-
d. N -			None	e(X) Minor()	Modera	ate () S	evere ()	UNDERM	IINING (Y/N) If Y	ES ple	ease e	xplain	Υ
OVERHEAD SIGNS (Y/N) N					Please of Modera	explain ate()S	evere ()		ON DAMAGE:				
(Attached to bridge)			LOAD	AD VIBRATION: Please explain				None (X) Minor () Moderate () Severe ()						
DEF I ∣				one () Minor () Moderate (X) Severe ()					Please explain	1ad	t o /	٠ ٥-		
b. Condition of Bolts	N	-	Any F	Any Fracture Critical Member: (Y/N)			None () Minor (X)							
c. Condition of Signs	N		•	ny Cracks: (Y/N)				I-60 (Dive Report):		<i>I-6</i>	0 (This	Repoi	rt): 6	
			y C		N				93B-U/	W (DIVE) Insp		00/	00/0	000

CITY/	TOW	N			B.I.	N.	BR. DEPT. NO.	8STR	UCTU.	RE NO.		INSPECTIO	ON D	ATE
PITT	SFIE	ELD			51	Р	P-10-048	P100	48-51	P-MUN-BI	રા	JAN 2	2, 20	024
7(0)		_				100	TDA EELC S						<u> </u>	
	EM 61				6		TEM 36 TRAFFIC S.	AFEIY 36	COND	DEF	ACCESSII		(Y/N	
	NNE				ــــــــا	Α. Ε	Bridge Railing	0	5	S-A	l		Needed	
CHA	NNE	<i>L PROTECTIO</i>)N				Fransitions	0	5	M-P	Lift Bucket		N	N
			Dive	Cur	DEF		Approach Guardrail	0	7	_	Ladder		N	N
1 Ch	annel	Scour	N	6		11 —	Approach Guardrail Ends	0	7		Boat		N Y	N
				+ -		_			ļ		Waders		-	Y
2.Em	bankr	nent Erosion	N	7	-	WE	IGHT POSTING		pplica		Inspector 50	,	N	N
3.De	bris		N	7	-		Γ	H 3		Single	Rigging		N	N
4.Veç	getatio	n	N	6	-	Act	tual Posting	10 15	23	N	Staging		N	N
5.Uti	lities		N	6	-	Red	commended Posting	N N	N	N	Traffic Cont	rol	N	N
6 Rin	-Ran/	Slope Protection	N	7	_	wai	ved Date: 00/00/0000	EJDMT E	Date: (00/00/0000	RR Flagger		N	N
	gradat	•	N	7	_	'''	At bri	J		er Advance	Police		N	N
				+	-	Sign	ns In Place N	S	N		Other:			
8.Fer	nder S	ystem	N	N	-	(Y=`	Yes,N=No,						N	N
							=NotRequired) ibility/ 8	8	8 /	8	TOTAL HO	OURS		24
							bility 8			8 8		JUNG		24
						CLE	ARANCE POSTING	E		W	PLANS	(Y/N	J):	Υ
						No	t X	in	ft	in meter		(171	•/-	•
STRE	EAM FL	OW VELOCITY:				Actu	ual Field Measurement	0		0	(V.C.R.)	(Y/N):	N	
		n () Moderate (X) Low () No	ne ()	Pos	ted Clearance	0		0	(,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	(1/14).	.,	
	, ,		, - (, -		Sim	At bri			Advance	TAPE#: _			
ITEM 61	TEM 61 (Dive Report): N ITEM 61 (This Report): 6 Signs In Place (Y=Yes,N=No,													
	NR=Not Required) NR=Not Required) NR=Not Required													
93b-0	J/W IN	SP. DATE:	00/00	/0000)		bility				Niotoi			
RATI	NG		1							If YE	S please give p	riority:		
Rating	Repo	rt (Y/N): Y				Reco	mmend for Rating or Re	erating (Y	/N): [)	
Doto	Recommend for Rating of Rerating (17/N):													
	Date: 02/01/2019 REASON:													
	•	on data at time of b: 4 160: 6 E		•	•									
130.	• 100	7. 4 100. 0 L	vale .() 1/3C	//2016									
I							CONDITION	RATING	G GU	DE (For	Items 58, 59, 60	and 61)		
	CODE	CONDITION					DEFECT	S						
	N	NOT APPLICABL	E											
G	9	EXCELLENT	E	Excelle	nt condition.									
G	8	VERY GOOD	١	No prob	lem noted.									
G	7	GOOD	5	Some n	ninor probler	ns.								
F	6	SATISFACTORY	5	Structur	al elements	show so	ome minor deterioration.							
F	5	FAIR	A	All prima	ary structura	ıl elemer	nts are sound but may have minor	section loss,	cracking	, spalling or scour.				
P	4	POOR					rioration, spalling or scour.			· · ·				
P	3	SERIOUS	L	oss of	section, det	erioratio	n, spalling or scour have seriously	affected prin	nary struc	ctural components. I	Local failures are po	ssible. Fatigue cra	acks	
	-	SERIOUS					oncrete may be present.	oracko in at	ool or ak	oar aracka in assess	o may be present -	r coour mov have		
С	2	CRITICAL					rimary structural elements. Fatigue ort. Unless closely monitored it ma							
С	1	"IMMINENT" FAILUR					n loss present in critical structural			us vertical or horizon	tal movement affect	ing structure stab	lility.	
	<u> </u>			- 3 -			.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	iii iigiit servit	ъ.					
<u> </u>	0	FAILED		Jut of s	ervice - bey	ond corr	ective action.							
I	DEFICIENCY REPORTING GUIDE													
DEFI	DEFICIENCY: A defect in a structure that requires corrective action.													
CATE	EGORI	ES OF DEFICIE	VCIES):										
M= N	M= Minor Deficiency Sholes, Minor corrosion of steel, Minor scouring, Clogged drainage, etc.													
	S= Severe/Major Deficiency Peficiencies which are more extensive in nature and need more planning and effort to repair. Examples include but are not limited to: Moderate to major deterioration in concrete, Exposed and over the considerable settlement, Considerable scouring or undermining, Moderate to extensive corrosion to structural steel with measurable loss of section, etc.													
3= 36	cveie/	iviajoi Deliciento	corroded	l rebars,	Considerable :	settlemen	t, Considerable scouring or undermining,	Moderate to ex	tensive cor	rosion to structural stee	with measurable loss of	f section, etc.		
C-S=	Critic	al Structural Def	icienc	y Ade	ficiency in a str e bridge.	uctural el	ement of a bridge that poses an extreme	unsafe condition	n due to the	e failure or imminent fail	ure of the element which	will affect the structu	ural integ	rity
C-H=	Critic	al Hazard Defici	ency	A defici	ency in a comp	onent or	element of a bridge that poses an extremose concrete hanging down over traffic of	e hazard or uns	safe conditi	on to the public, but doe	s not impair the structur	al integrity of the bride	ge. Exam	nples
<u> </u>				etc.							,		J	-
		OF REPAIR:												
	mediate		-		-		Engineer (DBIE) to report the Deficiency a				Poporti			
A = AS $P = Pr$	SAP- ioritize-						gineer or the Responsible Party (if not a Responsible Party (if not a State owned by							
			,					J , PC						

51P

STRUCTURES INSPECTION FIELD REPORT

BR. DEPT. NO. P-10-048

CITY/TOWN		8.	-STRUCTUI	RE NO.		11-Kilo. P0	OINT	90-RO	UTINE II	NSP. DA	TE 93	8*-SPEC.	MEMB.	INSP. DATI
PITTSFIELD			P1004	210048-51P-MUN-BRI			000.000		n 22,	2024	1	Jan	22, 2	024
07-FACILITY CARRIED HWY PECKS RD		<u> </u>	MEMO	MEMORIAL NAME/LOCAL NAME			27-YR	ьшт ВИІСТ 915		R REBU	ILT *	YR REH	AB'D (NO	ON 106)
06-FEATURES INTERSECTED			26-FUN	26-FUNCTIONAL CLASS			 RIDGE II	NSPECT	ION EN	GINEER	L.	A. Brigg	s	
WATER ONOTA BRO	ΟK		Urbai	Urban Collector										
43-STRUCTURE TYPE 302: Steel Stringer/G	irder		City/ N	22-OWNER City/ Municipal Highway A 21-MAINTAINER City/ Municipal Highway A										
107-DECK TYPE 1 : Concrete Cast-in-F	Place			WEATHER TEMP. (air) TEAM MEMBERS Sunny -1°C M. RANZONI										
WEIGHT POSTING	Not Ap	plicable	X		At	bridge		Advar	nce	T				
н Actual Posting		3S2 Single		Signs In		S		N	S		LAN	S (Y	/N):	Υ
	3	N N			Required)				0 /	C	v.c.r	(Y	/N):	N
Recommended Posting N N N N Legibility/ Waived Date: 00/00/0000 EJDMT Date: 00/00/0000 Visibility			3 7	APE#	#:									
RATING	LUDINI D	00/0	0/0000							If VE	S nleas	se give p	riority:	
Rating Report (Y/N):	Date:	02/01/2		Recomm	end for Rating o	r Rerati	ng (Y/N	ı): l	N	HIGH (MEDIUM		W ()
				REAS	SON:									
Inspection data at tin			1/30/2018	3										
SPECIAL MEMBER(S):		I	I					T		INV D	ATING	OE MEME	ED	
MEMBER	MEMBER CRACK (Y/N): WELD'S CONDITION (0-9)			LOCATION OF CORROSION, SECTION LOSS (%), CRACKS, COLLISION DAMAGE, STRESS CONCENTRATION, ETC.			PREVIOUS PRESENT			NV. RATING OF MEMBER FROM RATING ANALYSIS H-20 3 3S2			ficiencies	
A Item 58.2 - Deck Condition	N		See re	marks	in commen	ts sec	tion.	4	4	Not Rated		ted S-A		
B Item 59.4 - Girders or Beams	N		See re	marks	in commen	ts sec	tion.	3	3	2	3	3 !	5	S-A
С														
D														
_														
E														
List of field tests performed.	į									_	I-58	_I-59	I-60	I-62
<u>D-Meter</u>					(Over	all Prev	ious Co	onditio	n)		4	3	6	-
					(Over	all Curre	ent Con	dition))		4	3	6	_
DEFICIENCY: A defect in a str	ucture that re	equires correct	ive action.											
CATEGORIES OF DEFICIENCE		or in nature, gene	rally do not impa	ict the structura	I integrity of the bridge and	could easily t	oe repaired.	Examples i	nclude but	are not lim	ited to: S	palled conc	ete, Minor n	oot
M= Minor Deficiency $_{\text{holes, Minor}}^{\text{Deficiencies}}$ S= Severe/Major Deficiency $_{\infty}^{\text{Deficiency}}$	corrosion of st	eel, Minor scourir	ng, Clogged drain	nage, etc.	lanning and effort to repair.	Examples inc	clude but are	not limited	to: Modera	ate to majo	r deterio	ration in con	crete, Expos	sed and
C-S= Critical Structural Defic														
C-H= Critical Hazard Deficien	A defici	ency in a compon	ent or element of	of a bridge that	poses an extreme hazard o own over traffic or pedestria	r unsafe cond	lition to the	oublic, but o	does not im	pair the st	uctural ir	ntegrity of th	e bridge. Ex	amples
URGENCY OF REPAIR:														
	-				the Deficiency and to rece le Party (if not a State owner			-	ion Report]	ļ.				
P = Prioritize- [Shall be prioritized b	y District Maint	enance Engineer	or the Responsi	ble Party (if not	a State owned bridge) and	repairs made	when funds	and/or ma	inpower is a	available].				
X-IINKNOWN		N-NOT A	DDI ICAI	DIE	LI_1	HDDEN	LINIAC	CECC	DIE			D-	RFMC	VED

CITY/TOWN	B.I.N.	BR. DEPT. NO.	8STRUCTURE NO.	INSPECTION DATE
PITTSFIELD	51P	P-10-048	P10048-51P-MUN-BRI	JAN 22, 2024

BRIDGE ORIENTATION

Pecks Road travels north and south at this location. Onota Brook flows from west to east. This single span structure consists of 19 rolled steel beams supporting a concrete deck and an asphalt wearing surface. The beams and bays are numbered from west to east, upstream to downstream, in accordance with the 2019 Rating Report. Refer to sketch 1 & 2 and photos 1 - 2.

GENERAL REMARKS

Beams 1 - 3 are open to pedestrian traffic.

Beams 4 - 12 have been taken out of service by the placement steel barriers approximately 11'-4" away from the east interior guardrail. Refer to sketches 1 & 2 and see photo 1.

Beam 19 has been taken out of service with the placement of an interior guardrail along the east shoulder. See photo 1.

The current horizontal clearance is 10'-4". See sketches 2 & 3 and photo 1.

ITEM 58 - DECK

Item 58.2 - Deck Condition

Bays 1 - 16 are hidden by steel stay in place forms (bays 1 & 2 are jack arches and bays 4 - 16 have steel plate forms in place). The deck rating is based on the condition of the steel plates and forms. Solid concrete has been found above these plates in areas with holes. See photos 3 & 4.

Along the transverse open joints between the steel deck plates, the steel is damp from active leakage, with heavy delaminations, areas of perforations, and rust build-up between the plate and top flange of the beams. See photo 3.

Bay 3, at the south end, is spalled full depth, with a hole through the wearing surface at the edge of the sidewalk, up to 6" diameter. The hole has been covered with a steel plate.

Bays 17 & 18 have minor transverse cracks with efflorescence, damp areas, delaminated areas, up to 12" diameter.

Bays 17 & 18 have areas of honeycombing and cover spalls, up to 24" long x up to 36" wide x 2-1/2" deep.

The east deck fascia has a scaled area near mid-span, approximately 24" long x 6" high x 3-1/2" deep.

Item 58.3 - Stay in place forms

Bays 1 & 2 have corrugated steel forms in place (Jack-arch deck forms). The bottom 3" of the forms have moderate rusting with delamination, full length. See photo 4.

Bays 4 - 15 have steel plate forms in place. All of the steel plates have severe rusting with delamination and section loss. Also, there is severe active leakage in these bays. Most of the steel plates have pack rust between or are not in contact with the top flanges of the beams. See photo 3.

Item 58.4 - Curbs

The west curb was hidden by snow and ice at the time of inspection. The previous routine inspection report, dated 1/14/22, listed the curb reveal as 200mm with no comments.

CITY/TOWN	B.I.N.	BR. DEPT. NO.	8STRUCTURE NO.	INSPECTION DATE
PITTSFIELD	51P	P-10-048	P10048-51P-MUN-BRI	JAN 22, 2024

Item 58.6 - Sidewalks

The sidewalk was hidden by snow and ice at the time of inspection. The Routine Inspection Report, dated 1/30/2018, rated this item a 7 with no comments.

Item 58.8 - Railing

The interior east guardrail has a tear, approximately 35' long. All of the posts adjacent to the tear are bent. At the north end of the tear, two posts have detached anchor bolts. At the north end there is impact damage, 12' long x 2' bent out of plane. See photo 5.

The east rail base, along the top face, is spalled, full length x full width (top face) x 4" high (east face) x up to 2" deep. Several railing post base plates are partially undermined.

Item 58.10 - Drainage System

In bay 2, the drain pipes have moderate rusting and delamination. See photo 4.

<u>Item 58.12 - Utilities</u>

In bay 14, the natural gas pipe has minor rust stain bleeding from the pipe wrapping. At the south breastwall, the pipe has severe corrosion.

APPROACHES

Approaches c - Appr. Sidewalk Settlement

The approach sidewalks were hidden by snow and ice at the time of inspection. The Routine Inspection Report, dated 1/30/2018, rated this item a 7 with no comments.

ITEM 59 - SUPERSTRUCTURE

Item 59.4 - Girders or Beams

Beams 4 - 12, and 19 have been taken out of service.

Beams 1 - 16 have areas of moderate to severe rusting, delamination, and section loss. The worst conditions are found in areas exposed to active leakage; namely, at the ends of beams 11 & 14 and at mid-span of beams 4 - 8 & 16. There are holes in these areas. See sketches 4 - 18 and photos 4 & 6 - 9.

Beam 5, along the bottom flange, has random rolling defects.

Beams 13 - 15 have a gap, up to 3/4", in between the top flange and deck plate resulting in the deck not transferring live load to the beams at mid-span. The gap runs along the top flange for nearly the full length of the beams, except in the vicinity of the transverse open joint between the deck plates, where there is rust build-up.

Beam 13 has web distortion, full length x up to 3/16" out of plane to the west.

Beam 14 has web distortion, full length x up to 1/2" out of plane to the east.

Beam 16 has bottom flange distortion, full length x 3/4" out of plane. At the south end, the beam end is bent out of plane, 1/8" to the east.

Beam 17, at both end, has section loss. See sketch 17.

Beam 18, at the south ends, has an area of severe section loss and holes. Refer to sketch 18 and photo 10.

CITY/TOWN	B.I.N.	BR. DEPT. NO.	8STRUCTURE NO.	INSPECTION DATE
PITTSFIELD	51P	P-10-048	P10048-51P-MUN-BRI	JAN 22, 2024

Beam 19 has failed. See photo 11.

<u>Item 59.9 - Bearing Devices</u>

Beams 1 - 16 rest on the stone masonry abutments and are encased in concrete. See photos 7, 8, & 12.

Bearings 17 - 19, the exposed portions of the plates have surface rusting. See photo 10.

<u>Item 59.10 - Diaphragms/Cross Frames</u>

Only bay 17 has diaphragms.

The diaphragms in bay 17 have minor surface rusting.

Item 59.11 - Rivets & Bolts

The rivets in bay 17 have minor surface rusting.

Item 59.13 - Member Alignment

Beams 1 -16 have single plate bearings resting directly on the stone masonry abutment. See photos 7, 8, & 12. The uneven bearing areas are causing random rotations in the beams.

Beams 4 - 16 have varying amounts of pack rust formed between the deck and top flange. See photo 3.

Item 59.14 - Paint/Coating

Beams 1 - 16 & 19, have no paint remaining. See photo 2, 4, 6 - 9, & 11.

Beams 17 & 18 have large areas of missing paint. See photo 10.

SuperStructure Load Vibration Notes

Under heavy live loads, there is moderate vibration.

ITEM 60 - SUBSTRUCTURE

Item 60.1 - Abutments

<u>Item 60.1.b - Bridge Seats</u>

The stone masonry seats are uneven with areas of broken stones throughout. The worst conditions are found below both ends of beam 3. See photos 12 & 13.

Item 60.1.c - Backwalls

Throughout both backwalls, there are areas of cracking and honeycombing.

Item 60.1.d - Breastwalls

Both breastwalls have areas of cracked and missing mortar. See photos 12 & 13.

In front of both breastwalls, there are cast in place concrete curtain walls.

Both curtain walls have several vertical cracks, 1/16" wide x full height, and areas of rust staining.

The south breastwall, under beam 4, has an area of missing and loose stones with fill spilling through, approximately 12" diameter. See photo 13.

CITY/TOWN	B.I.N.	BR. DEPT. NO.	8STRUCTURE NO.	INSPECTION DATE
PITTSFIELD	51P	P-10-048	P10048-51P-MUN-BRI	JAN 22, 2024

Item 60.1.e - Wingwalls

The stone masonry portions of the wingwalls have random loose stones and missing mortar.

Item 60.1.g - Pointing

In the stone masonry portions of the abutments, there are random areas of missing mortar throughout. See photos 12 & 13.

<u>Item 60.1.h - Footings</u>

The stone masonry abutment footings are hidden by the streambed and curtain walls.

Item 60.1.j - Scour

The north curtain wall is undermined starting at the downstream (east) end, 31' long x up to 33" of penetration (to the original stone masonry abutment).

The south curtain wall is scoured and undermined at the upstream (west) end, approximately 4' long x 12" of penetration. See photo 14.

SubStructure Undermining Notes

Refer to Item 60.1.j - Scour.

SubStructure Scour Notes

Refer to Item 60.1.j - Scour.

ITEM 61 - CHANNEL AND CHANNEL PROTECTION

Item 61.1 - Channel Scour

The channel turns under the structure such that the southwest corner and the northeast corner have moderate scouring of the streambed.

Refer to chart 1 for channel profile readings.

Item 61.4 - Vegetation

Both the upstream and downstream channels have moderate vegetation growth along the embankments.

Item 61.5 - Utilities

In the upstream channel, approximately 4' west of the abutments, a portion of utility pipe, 10" diameter, is exposed, 7' long.

TRAFFIC SAFETY

Item 36a - Bridge Railing

The bridge railings consist of single steel W-beam panels mounted on steel posts with steel blockouts, spaced at 6'. There is a chain link fence mounted on the back side of the guardrails.

Approximately 2' from the east railing, an interior guardrail has been mounted to the deck (not through - bolted).

At 11'-4" from the east interior guardrail, steel barriers have been put in place.

Refer to Item 58.8 - Railing and General Remarks.

CITY/TOWN	B.I.N.	BR. DEPT. NO.	8STRUCTURE NO.	INSPECTION DATE
PITTSFIELD	51P	P-10-048	P10048-51P-MUN-BRI	JAN 22, 2024

Item 36b - Transitions

The west transitions consist of single steel W-beam panels mounted on steel posts with steel blockouts, spaced at 6'.

The east transitions (continuous with the interior bridge railing) consist of single steel W-beam panels mounted on steel posts with plastic blockouts, spaced at 6'.

The southeast transition panels have a tear down the center, approximately 20' long, and impact damage extending from the bridge railing. See photo 5.

Item 36c - Approach Guardrail

The west approach guardrails consist of single steel W-beam panels mounted on steel posts with steel blockouts, spaced at 6'.

The east approach guardrails (continuous with the interior bridge railing) consist of single steel W-beam panels mounted on steel posts with plastic blockouts, spaced at 6'.

Item 36d - Approach Guardrail Ends

The west approach guardrails have buried ends, not swept from traffic.

The east approach guardrails (continuous with the interior bridge railing) have swept terminal ends.

Sketch / Chart / Photo Log

Sketch 1:	Framing layout.	nlan viow
OKELLIII.	Fiaiiiiiu iavoul.	Diali view.

Sketch 2: Plan view of guardrail and barrier placement.

Sketch 3: Framing layout, cross section.

Sketch 4: Beams B1, B2, B3 & B9 Field Measured Properties.

Sketch 5: Beams B10, B13, B15 & B17 Field Measured Properties.

Sketch 6: Beam 4 section loss.

Sketch 7: Beam 5 section loss.

Sketch 8: Beam 6 section loss.

Sketch 9: Beam 7 section loss.

Sketch 10: Beam 8 section loss.

Sketch 11: Beam 9 section loss.

Sketch 12: Beam 11 section loss.

Sketch 13: Beam 13 section loss.

Sketch 14: Beam 14 section loss.

Sketch 15: Beam 15 section loss.

Sketch 16: Beam 16 section loss.

Sketch 17: Beam 17 section loss.

Sketch 18: Beam 18 section loss.

Chart 1: Channel profile readings.

Photo 1: General topside, looking north.

Photo 2: General underside, looking west.

Photo 3: Typical stay in place form condition, with section loss and holes. Note the concrete behind the

steel plate.

Photo 4: Bay 2, looking south, jack arch and drain pipe condition. Also, note the beam 3 rusting and

section loss.

Photo 5: East bridge guardrail with tear and impact damage.

Photo 6: Holes near mid-span, in the web of beam 7.

Photo 7: Beam 11, south end, with section loss and holes. Note, out of service.

PAGE 9 OF 35

 CITY/TOWN
 B.I.N.
 BR. DEPT. NO.
 8.-STRUCTURE NO.
 INSPECTION DATE

 PITTSFIELD
 51P
 P-10-048
 P10048-51P-MUN-BRI
 JAN 22, 2024

REMARKS

Photo 8: Beam 14, north end, with section loss and holes.


Photo 9: Beam 16, noth end, with section loss.


Photo 10: Beam 18, south end, with section loss and holes. Photo 11: East elevation, beam 19 failed. Note, out of service.


Photo 12: North breastwall condition.

Photo 13: Area of missing and loose stones in the south breastwall under beams 3 & 4.

Photo 14: North curtain wall scour.











This document was created by an application that isn't licensed to use <u>novaPDF</u>. Purchase a license to generate PDF files without this notice.


EM.(2)





























CITY/TOWN B.I.N. BR. DEPT. NO. 8.-STRUCTURE NO. INSPECTION DATE **PITTSFIELD** 51P P-10-048 P10048-51P-MUN-BRI **JAN 22, 2024 SKETCHES** Beam 15 North end .22" Minor 1/2" dia. hole 39" Minor 12"-Original Beam = American Standard 12" x 32# Flange Thickness (Avg.) = 0.474" Web Thickness = 0.259" Sketch 15: Beam 15 section loss.







CHARTS

P10048 Channel Profile Readings										
East Fascia West Fascia										
DATE	South Abutment 1/2 span North Abutment South Abutment 1/2 span North Abutment									
1/22/24	6.8 7.1 7.0 8.1 7.8					6.0				

NOTES:

*All readings in decimal feet.




Chart 1: Channel profile readings.



Photo 1: General topside, looking north.



Photo 2: General underside, looking west.



Photo 3: Typical stay in place form condition, with section loss and holes. Note the concrete behind the steel plate.



Photo 4: Bay 2, looking south, jack arch and drain pipe condition. Also, note the beam 3 rusting and section loss.



Photo 5: East bridge guardrail with tear and impact damage.



Photo 6: Holes near mid-span, in the web of beam 7.



Photo 7: Beam 11, south end, with section loss and holes. Note, out of service.



Photo 8: Beam 14, north end, with section loss and holes.



Photo 9: Beam 16, noth end, with section loss.



Photo 10: Beam 18, south end, with section loss and holes.



Photo 11: East elevation, beam 19 failed. Note, out of service.



Photo 12: North breastwall condition.



Photo 13: Area of missing and loose stones in the south breastwall under beams 3 & 4.



Photo 14: North curtain wall scour.