

October 29, 2015

Page 2 of 13

Please note that our review and findings should not be construed as a detailed and fully comprehensive evaluation. All areas were not inspected and the evaluation criteria as discussed further below, is a screening based methodology. Additionally, potentially hazardous findings identified maybe found to be acceptable after a more thorough engineering assessment and in-depth investigation is performed. For example, the buildings identified as requiring Further Evaluation during our review may prove to be safe to earthquake excitation after a more detailed evaluation is conducted by a structural engineer.

We hope you find this preliminary report helpful. The information gained for use in the Commission Project for Missouri school seismic safety improvements is very important. If you or the District have any questions regarding the preliminary conclusions presented herein, please do not hesitate to contact me or Commissioner Phillip L. Gould.

Sincerely

Dr. Eric Sandvol, Chairman
Missouri Seismic Safety Commission

***Sikeston R-6 School District
Preliminary Earthquake Findings & Observations***

Background

The Missouri Seismic Safety Commission is undertaking a pilot project to evaluate several school districts in southeast Missouri, which are located in the most vulnerable region of the state, to earthquakes occurring in the New Madrid Seismic Zone. Several districts have previously been completed. This year's project included three districts of which Sikeston was one identified as representative of schools within southeast Missouri. A seismic screening evaluation was performed for the Sikeston R-6 school buildings from the Kindergarten Center to the multiple buildings on the Senior High Campus. The evaluation was performed by teams of volunteers associated with respected engineering organizations in Missouri and Arkansas using the widely accepted methodology FEMA P-154 "Rapid Visual Screening of Buildings for Potential Seismic Hazards 3rd Edition" [1] which was extensively revised and published in January 2015.

FEMA P-154 is an industry accepted screening methodology to quickly and economically identify, inventory and rank buildings that are potentially vulnerable to earthquake ground shaking. The procedure yields a numerical score based on key building attributes or characteristics that reflect the potential for severe building damage under strong earthquake shaking. A score greater than 2.0 implies that a building is life-safe following a major earthquake. A building with a score of 2.0 or less suggests that the building is potentially not safe to strong earthquake shaking. Therefore, the results yield two categories of buildings. Those that are expected to have acceptable seismic performance, and those that may be seismically hazardous and are recommended for further evaluation. The potentially vulnerable buildings are then recommended for a more detailed evaluation by a structural engineer experienced in the design of buildings for seismic safety.

An addition to FEMA P-154 in the 3rd Edition is the option of performing a Level 2 screening review. The Level 2 screening review is more detailed than the Level 1 standard review as used in previous 154 Editions. The Level 2 review is required to be performed by a design professional experienced in seismic design and evaluation. Both Level 1 and Level 2 reviews were performed for the District buildings.

The Commission team member volunteers conducted a seismic review of the Sikeston school building sites on September 11, 2015. Available drawings (architectural, renovation, and structural) were reviewed and used in conjunction with the site visual reviews. Access to interior areas was available. Access above ceiling areas in the majority of building sections was also performed to assist in viewing building construction. Additionally, nonstructural components were reviewed on a sampling basis throughout the school buildings to identify critical life-safety hazards that could potentially affect students and staff.

The remainder of this report presents the seismicity, findings/observations for buildings and nonstructural components with recommendations for improving the seismic safety of the District facilities. The attachments to this report are the Rapid Visual Screening of Buildings for Potential Seismic Hazards FEMA P-154 Data Collection Forms used to evaluate the District school buildings. Generally one FEMA P-154 Data Collection Form was used for each major building and building section.

Seismicity

The seismic hazard used to evaluate the Sikeston R-6 District school buildings is presented below. The ground motion estimates are based on the 2012 International Building Code [2] as published in the 2008 USGS Seismic Hazard Maps [3]. The seismic ground motion values and hazard for the site as defined by FEMA P-154 criteria is as follows:

$S_s = 2.4g$
 $S_1 = 0.9g$
Site Class = D (assumed)
Liquefaction Potential = No
Seismic Hazard = Very High

Building Review Findings/Observations

The District buildings varied in vintage from 1954 Lee Hunter Elementary School to the new 2007 Senior High Math/Science building. The majority of buildings were constructed in the 1960s. The wide variation in building vintage also translated to a varied earthquake vulnerability potential for each building as evidenced by the P-154 screening procedure building scores. The older construction buildings were identified with the greatest vulnerability. These buildings are typically constructed of unreinforced masonry acting as bearing wall structures. Unreinforced masonry/brick buildings are one of the most vulnerable building types under earthquake shaking. These older buildings were also identified as potentially vulnerable to seismic damage as they lack seismic design and detailing as well as a definable lateral load resisting system for earthquake forces. Thus, these buildings were identified as potentially vulnerable to earthquake shaking.

Conversely, the new Senior High Math/Science building was identified as the least vulnerable and in fact was identified as having good seismic performance. The variation in vintage and building code usage clearly demonstrates that the adoption of the latest building codes for newer buildings yields a significant increase in seismic safety as the buildings are much less vulnerable to strong ground shaking. Thus, the Math/Science building is considered seismically safe.

Buildings which failed the FEMA P-154 criteria are recommended for further evaluation. Table 1 below summarizes the FEMA P-154 evaluation of the District building structures. The Further Evaluation Recommendations are based on the more refined Level 2 score presented and should be used by the District for any future seismic safety mitigation planning.

**Table 1
FEMA P-154 Building Evaluation Summary
Sikeston R-6 School District**

Building Section	Vintage	Screening Score		Further Evaluation Recom'd	Remarks
		Level 1	Level 2		
Sikeston Kindergarten Center:					
Original Construction	1978	0.5	0.6	Yes	Masonry construction. Multiple sections with no definable lateral system.
Lee Hunter Elementary School:					
Original Construction	1954	0.5	0.9	Yes	Masonry construction. Multiple sections with no definable lateral system.
Matthews Elementary School:					
Original Construction	1955	0.6	0.9	Yes	Unreinforced masonry construction.
Southeast Elementary School:					
Original Construction	1968	0.6	0.5	Yes	Unreinforced masonry construction. Irregular plan shape to the building.
Alternative Center:					
Wings A & C	1964	0.6	0.9	Yes	Unreinforced masonry construction. No definable lateral load

					resisting system.
Main Building/Wing B	1964	0.6	0.9	Yes	Unreinforced masonry construction. No definable lateral load resisting system.
Ancillary Building	1964	1.1	1.1	Yes	Manufactured single wide structure.
5th & 6th Grade Center:					
Original Construction Classroom section	1973	0.6	0.2	Yes	Unreinforced masonry construction. Vertical set back with pounding potential at Gym structure.
Original Construction Gym	1973	0.8	0.8	Yes	Steel construction. Discontinuous lateral system & pounding at lower classroom section.
7th & 8th Grade Center:					
Original Construction	1985	0.7	1.1	Yes	Masonry construction. Irregular plan shape.
Senior High School:					
Building A	1960	0.6	0.2	Yes	Multiple building types. Pounding potential between URM, C3 & S1 structures.
Building B	1960	0.6	0.7	Yes	Unreinforced masonry. Irregular plan shape. Pounding potential with adjacent building sections.
Building C	1960	0.5	1.3	Yes	Steel frame with masonry infill.

					Vertical irregularity at Library.
Building D – Girls Gym	1960	0.2	0.4	Yes	Unreinforced masonry. Vertical irregularity at Gym.
Building F – Band/Music	1959	0.6	0.4	Yes	Concrete with masonry infill. Severe torsional irregularity with outdoor concrete canopy.
Building G	1968	0.6	0.9	Yes	Unreinforced masonry. Addition. Pounding potential at adjacent buildings.
Building H	1967	0.3	0.9	Yes	Unreinforced masonry. Vertical irregularity. Questionable loadpath.
Building I	1969	0.6	0.9	Yes	Unreinforced masonry. Limited interior partition wall systems.
Field House	1969	0.3	0.9	Yes	Concrete frame with infill & unreinforced masonry. Vertical irregularity.
Math/Science	2007	2.5	2.7	No	Steel braced frame with good seismic detailing.
Bus Garage	1980	1.3	1.3	Yes	Pre-engineered steel structure.
District Peripheral Buildings:					
Adult Basic Education	1962	0.3	0.9	Yes	Vertical irregularity.
SPS Board Office	1975	0.9	1.1	Yes	Wood frame. Sloping site irregularity.

Nonstructural Component Review Findings/Observations

Interior reviews of selected classrooms, cafeterias, gyms and libraries for each of the schools were performed to assess nonstructural component, equipment and system earthquake hazards. Not every area was inspected due to access and time. Primary mitigation measures observed in all buildings included the incorporation of light fixture safety wires, some book shelves attached to wall systems, classroom exits were noted reasonably free and clear of clutter and contents which could overturn and block egress routes.

Several potential life-safety conditions were observed. Table 2 summarizes some of the key observations and findings identified during the review of the District buildings. It is recommended that these components be reviewed more thoroughly by a structural engineer and the life-safety risk mitigated as necessary.

**Table 2
Nonstructural Component Evaluation Summary
Sikeston R-6 School District**

Nonstructural Component Description	Further Evaluation Recommended	Remarks
Recessed Fluorescent Lights	No	Installations sampled were observed safety wired.
Suspended Drop Ceilings	Yes	Installations sampled in classrooms and corridors were observed without splay-wire bracing. Math/Science Center was observed with splay wire bracing.
Tall Bookcases/Storage Cabinets	Yes	Newer installations were observed restrained. However, numerous older installations were observed unrestrained.
Contents near egress exits at classrooms	Yes	Many areas were observed with contents that could fall and injure staff and students or fall and block egress.
CMU (heavy) interior partition walls	Yes	Extensive throughout buildings. Walls sampled did not have lateral out-of-plane bracing.
Corridor Partitions	Yes	Several of older buildings had glass corridor walls susceptible to

Nonstructural Component Description	Further Evaluation Recommended	Remarks
		breakage in an earthquake event.
Gas fired equipment	Yes	Kitchen equipment, water heaters, AHUs, suspended unit heaters were observed unanchored. Gas piping was observed unbraced.
Mechanical equipment	Yes	Chillers, pumps, etc. sampled were observed unanchored.
Electrical equipment	Yes	Elect. components. – transformers, MCCs, switchgear, etc., were observed unanchored.

Conclusions/Recommendations

The following recommendations are provided for district consideration in providing a more earthquake resistive and resilient school environment for students and staff.

1. Continued practice: Continue to implement pro-active earthquake risk mitigation measures observed throughout the campus to include:
 - a. Seismic safety philosophy – Incorporate seismic safety drills (drop-cover and hold-on) in to the school curriculum. If not already participating, the Great Shake-Out is a great way to incorporate this into practice. See <http://www.shakeout.org/centralus/> for additional information on the shake-out.
 - b. Building safety - Use building capital improvement projects to remove older more vulnerable buildings and replace with buildings having greater earthquake resistance designed to current building code and seismic provisions. Ensure the design professionals hired are knowledgeable in seismic design. Ensure that proper inspections are performed to verify that the seismic detailing has been properly incorporated during construction.
 - c. Nonstructural component safety - Nonstructural component safety improvements observed included:
 - Safety wiring light fixtures.
 - If not already performing, it is suggested that an annual review of nonstructural contents be addressed to ensure proper seismic safety

provisions are in place and have not been inadvertently removed including:

- i. Ensuring heavy contents (boxes, etc.) are not stored on top of cabinets in classrooms;
 - ii. Classroom exits and corridors are free and clear of contents.
 - iii. TV's are positively strapped to the wall bracket supports.
 - iv. Heavy (> 20lbs) overhead components are properly supported to prevent falling.
 - v. Storage shelving and bookcases are properly restrained to adjacent walls or arranged in more stable conditions; i.e., back-to-back bolted together.
2. **Building Assessment:** Based on the results presented in Table 1, the district should consider having a detailed structural engineering seismic safety evaluation performed for those buildings so recommended.
 3. **Nonstructural Component Mitigation:** Based on the results presented in Table 2, the following are key recommendations provided to reduce the risk from potential life-safety hazards associated with earthquake damage to nonstructural components in the schools. FEMA E-74, *Reducing the Risks of Nonstructural Earthquake Hazards – A Practical Guide* [4] developed by FEMA is a free document and one of the best available resources for assessing risk to nonstructural components and strategies for mitigating the risk. Key recommendations include:
 - a. **Gas-fired Equipment & Piping** - Given the potential for fire, all gas-fired equipment and piping should be anchored and braced. Consider reviewing the gas-fired equipment for proper anchorage and bracing gas piping within the building.
 - b. **Contents** – Perform a systematic review of all occupied areas of the school buildings for housekeeping such that egress doors, routes and corridors are free and clear of clutter, contents (file cabinets, storage cabinets, etc.) that could overturn and block doorways or egress routes are anchored or relocated. Relocate heavy contents to areas that will not impact egress. Or anchor the cabinets, bookcases, etc. to the adjacent wall system.
 - c. **Heavy items** – Perform a review throughout the school classrooms and ensure that heavy components & contents located greater than 4' above the floor and greater than 20 lbs. are adequately anchored, restrained or removed. This is particularly important near egress exits; i.e., contents stored above storage cabinets that are located adjacent to a classroom exit.
 - d. **Glass Corridor Walls** – Consider installing protective film on the corridor wall glazing where it occurs, or remove the wall and replace with a more earthquake resistant material.

- e. Heavy Masonry Partition Walls - Consider addressing the heavy masonry partition walls in the older sections of the school buildings for out-of-plane response. Adequate lateral bracing should be provided to prevent the walls from collapsing.
 - f. Electrical & Mechanical Equipment Anchorage – Consider reviewing and anchoring equipment that is not anchored. This is very inexpensive (anchor bolts properly installed) and will aid school recovery following an earthquake as the infrastructure (power, water, gas, etc.) equipment will not be damaged. This applies even in small earthquake shaking events where buildings will experience little damage, but nonstructural components can be extensively damaged.
4. Strategy Moving Forward: Implementing seismic safety improvements in conjunction with other capital improvement projects is the most cost-effective time to incorporate good seismic safety mitigation measures. Thus, it should be a priority for any new building or renovation project being planned going forward to ensure that seismic safety measures are implemented. Often the cost-premium is very minimal to incorporate good seismic safety into design and construction directed by professionals that understand seismic design and installation practices. A suggested strategy moving forward that yields cost-effective risk reduction in your facilities includes:
- a. New Building Construction: Ensure that the new and future buildings are designed for seismic loading. Question the design professionals until you are sure that seismic design is being properly performed with the latest edition of the applicable building code by a knowledgeable seismic/structural engineer. Request credentials to verify they have seismic design experience. If this advice is not followed, engineers not knowledgeable in seismic design can easily add significant cost to a project that is unnecessary.
 - b. Renovations or New Equipment Installations: Ensure that ANY new equipment, facility renovations, etc. are designed and constructed with seismic safety included in the design. Again, question the design professionals and contractors regarding seismic design and construction for these items.
 - c. FEMA Earthquake Program Cooperative Agreement Grant Program with the State of Missouri: Consider identifying key high risk nonstructural component vulnerabilities and applying for the State’s grant program to assist in reducing the financial impact to the District. Contact Jeff Briggs – Earthquake Program Manager (573) 526-9232.

Again, the most cost-effective time to incorporate good seismic safety practices is at the time of original construction. Thus, it should be a priority for any new project. Often the cost-premium is very minimal to incorporate good seismic safety into the design and construction directed by professionals that understand seismic design and installation practices.

References

1. FEMA P-154- *Rapid Visual Screening of Buildings for Potential Seismic Hazards, A Handbook*, Third Edition, January 2015.
2. *International Building Code* 2012 Edition, International Code Council.
3. USGS Seismic Hazard Data, 2008 USGS Hazard Data
4. FEMA E-74: *Reducing the Risks of Nonstructural Earthquake Hazards - A Practical Guide*, January 2011.

ATTACHMENTS



Address: 1310 E. Salcedo Road
Sikeston, MO Zip: 63801

Other Identifiers: Sikeston R-6 District

Building Name: Sikeston Kindergarten Center

Use: K-12 School

Latitude: 36.896561 Longitude: -89.588116

Ss: 2.338g S_r: 0.857g

Screeener(s): Varnell/Mills Date/Time: 9-11-15/ 9:00 am

No. Stories: Above Grade: 1 Below Grade: 0 Year Built: 1978 EST

Total Floor Area (sq. ft.): 43,130 Code Year: Unknown

Additions: None Yes, Year(s) Built: _____

Occupancy: Assembly Commercial Emer. Services Historic Shelter
Industrial Office School Government
Utility Warehouse Residential, # Units: _____

Soil Type: A B C D E F DNK
Hard Avg Dense Stiff Soft Poor DNK
Rock Rock Soil Soil Soil Soil
If DNK, assume Type D.

Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

Adjacency: Pounding Falling Hazards from Taller Adjacent Building

Irregularities: Vertical (type/severity) _____
 Plan (type) Re-entrant corner

Exterior Falling Hazards: Unbraced Chimneys Heavy Cladding or Heavy Veneer
 Parapets Appendages
 Other: NONE



COMMENTS:

- Falling hazard at interior fire wall, CMU partition walls
- Book case not secure to wall
- Lights safe-tied

Additional sketches or comments on separate page

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE, S_{L1}

FEMA BUILDING TYPE	Do Not Know	W1	W1A	W2	S1 (MRF)	S2 (BR)	S3 (LM)	S4 (RC SW)	S5 (URM INF)	C1 (MRF)	C2 (SW)	C3 (URM INF)	PC1 (TU)	PC2	RM1 (FD)	RM2 (RD)	URM	MH
Basic Score		2.1	1.9	1.8	1.5	1.4	1.6	1.4	1.2	1.0	1.2	0.9	1.1	1.0	1.1	1.1	0.9	1.1
Severe Vertical Irregularity, V _{L1}		-0.9	-0.9	-0.9	-0.8	-0.7	-0.8	-0.7	-0.7	-0.7	-0.8	-0.6	-0.7	-0.7	-0.7	-0.7	-0.6	NA
Moderate Vertical Irregularity, V _{L1}		-0.6	-0.5	-0.5	-0.4	-0.4	-0.5	-0.4	-0.3	-0.4	-0.4	-0.3	-0.4	-0.4	-0.4	-0.4	-0.3	NA
Plan Irregularity, P _{L1}		-0.7	-0.7	-0.6	-0.5	-0.5	-0.6	-0.4	-0.4	-0.4	-0.5	-0.3	-0.5	-0.4	-0.4	-0.4	-0.3	NA
Pre-Code		-0.3	-0.3	-0.3	-0.3	-0.2	-0.3	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	0.0
Post-Benchmark		1.9	1.9	2.0	1.0	1.1	1.1	1.5	NA	1.4	1.7	NA	1.5	1.7	1.6	1.6	NA	0.5
Soil Type A or B		0.5	0.5	0.4	0.3	0.3	0.4	0.3	0.2	0.2	0.3	0.1	0.3	0.2	0.3	0.3	0.1	0.1
Soil Type E (1-3 stories)		0.0	-0.2	-0.4	-0.3	-0.2	-0.2	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	-0.1
Soil Type E (> 3 stories)		-0.4	-0.4	-0.4	-0.3	-0.3	NA	-0.3	-0.1	-0.1	-0.3	-0.1	NA	-0.1	-0.2	-0.2	0.0	NA
Minimum Score, S _{MIN}		0.7	0.7	0.7	0.5	0.5	0.5	0.5	0.5	0.3	0.3	0.3	0.2	0.2	0.3	0.3	0.2	1.0

FINAL LEVEL 1 SCORE, S_{L1} ≥ S_{MIN}: **0.5**

<p>EXTENT OF REVIEW</p> <p>Exterior: <input type="checkbox"/> Partial <input type="checkbox"/> All Sides <input checked="" type="checkbox"/> Aerial</p> <p>Interior: <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered</p> <p>Drawings Reviewed: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p> <p>Soil Type Source: Vs30</p> <p>Geologic Hazards Source: Regional Data</p> <p>Contact Person: Mike Brown</p> <p>LEVEL 2 SCREENING PERFORMED?</p> <p><input checked="" type="checkbox"/> Yes, Final Level 2 Score, S_{L2} 0.6 <input type="checkbox"/> No</p> <p>Nonstructural hazards? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p>	<p>OTHER HAZARDS</p> <p>Are There Hazards That Trigger A Detailed Structural Evaluation?</p> <p><input type="checkbox"/> Pounding potential (unless S_{L2} > cut-off, if known)</p> <p><input type="checkbox"/> Falling hazards from taller adjacent building</p> <p><input type="checkbox"/> Geologic hazards or Soil Type F</p> <p><input type="checkbox"/> Significant damage/deterioration to the structural system</p>	<p>ACTION REQUIRED</p> <p>Detailed Structural Evaluation Required?</p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building</p> <p><input checked="" type="checkbox"/> Yes, score less than cut-off</p> <p><input type="checkbox"/> Yes, other hazards present</p> <p><input type="checkbox"/> No</p> <p>Detailed Nonstructural Evaluation Recommended? (check one)</p> <p><input checked="" type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated</p> <p><input type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary</p> <p><input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p>
---	---	--

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Rapid Visual Screening of Buildings for Potential Seismic Hazards

FEMA P-154 Data Collection Form

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

Level 2 (Optional)
VERY HIGH Seismicity

Bldg Name: Sikeston Kindergarten Center	Final Level 1 Score: $S_{L1} = 0.5$	<i>(do not consider S_{MIN})</i>	
Screener: Varnell/Mills/ Griffin	Level 1 Irregularity Modifiers:	Vertical Irregularity, $V_{L1} = 0$	Plan Irregularity, $P_{L1} = -0.4$
Date/Time: 9-11-15/ 9:00 am	ADJUSTED BASELINE SCORE:	$S' = (S_{L1} - V_{L1} - P_{L1}) = 0.9$	

STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

Topic	Statement (If statement is true, circle the "Yes" modifier, otherwise cross out the modifier.)	Yes	Subtotals
Vertical Irregularity, V_{L2}	Sloping Site	W1 building: There is at least a full story grade change from one side of the building to the other.	-0.9
		Non-W1 building: There is at least a full story grade change from one side of the building to the other.	-0.2
	Weak and/or Soft Story (circle one maximum)	W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.	-0.5
		W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum).	-0.9
		W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.	-0.9
		Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.	-0.7
		Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.	-0.4
	Setback	Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.	-0.7
		Vertical elements of the lateral system at upper stories are inboard of those at lower stories.	-0.4
		There is an in-plane offset of the lateral elements that is greater than the length of the elements.	-0.2
	Short Column/ Pier	C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.	-0.4
		C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.	-0.4
Split Level	There is a split level at one of the floor levels or at the roof.	-0.4	
Other Irregularity	There is another observable severe vertical irregularity that obviously affects the building's seismic performance.	-0.7	
	There is another observable moderate vertical irregularity that may affect the building's seismic performance.	-0.4	
Plan Irregularity, P_{L2}	Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.)	-0.5	
	Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.	-0.2	
	Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.	-0.2	
	Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.	-0.2	
	C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.	-0.2	
	Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.	-0.5	
Redundancy	The building has at least two bays of lateral elements on each side of the building in each direction.	+0.2	
Pounding	Building is separated from an adjacent structure by less than 1.5% of the height of the shorter of the building and adjacent structure and:	The floors do not align vertically within 2 feet.	(Cap total pounding modifiers at -0.9) -0.7
		One building is 2 or more stories taller than the other.	-0.7
		The building is at the end of the block.	-0.4
S2 Building	"K" bracing geometry is visible.	-0.7	
C1 Building	Flat plate serves as the beam in the moment frame.	-0.3	
PC1/RM1 Bldg	There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)	+0.2	
PC1/RM1 Bldg	The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).	+0.2	
URM	Gable walls are present.	-0.3	
MH	There is a supplemental seismic bracing system provided between the carriage and the ground.	+0.5	
Retrofit	Comprehensive seismic retrofit is visible or known from drawings.	+1.2	
FINAL LEVEL 2 SCORE, $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$:			0.6 (Transfer to Level 1 form)

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance: Yes No
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

OBSERVABLE NONSTRUCTURAL HAZARDS

Location	Statement (Check "Yes" or "No")	Yes	No	Comment
Exterior	There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.		X	
	There is heavy cladding or heavy veneer.		X	
	There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported.		X	
	There is an unreinforced masonry appendage over exit doors or pedestrian walkways.		X	
	There is a sign posted on the building that indicates hazardous materials are present.		X	
	There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney.		X	
	Other observed exterior nonstructural falling hazard:		X	
Interior	There are hollow clay tile or brick partitions at any stair or exit corridor.		X	
	Other observed interior nonstructural falling hazard:	X		Contents, CMU partitions

Estimated Nonstructural Seismic Performance (Check appropriate box and transfer to Level 1 form conclusions)
 Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended
 Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required
 Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

Comments: Bookcases unrestrained. CMU partition walls not braced OOP. Metal roof deck attachment to perimeter CMU parallel to roof joists very questionable.



Address: 315 Baker Lane
Sikeston, MO Zip: 63801

Other Identifiers: Sikeston R-6 District

Building Name: Lee Hunter Elementary School

Use: K-12 School

Latitude: 36.882008 Longitude: -89.595138

Ss: 2.385g S_r: 0.880g

Screener(s): Varnell/Mills Date/Time: 9-11-15/ 11:00 am

No. Stories: Above Grade: 1 Below Grade: 0 Year Built: 1954 EST

Total Floor Area (sq. ft.): 33,108 Code Year: Unknown

Additions: None Yes, Year(s) Built: Unknown

Occupancy: Assembly Commercial Emer. Services Historic Shelter
Industrial Office School Government
Utility Warehouse Residential, # Units: _____

Soil Type: A B C D E F **DNK**
Hard Avg Dense Stiff Soft Poor **DNK**
Rock Rock Soil Soil Soil Soil *If DNK, assume Type D.*

Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

Adjacency: NONE Pounding Falling Hazards from Taller Adjacent Building

Irregularities: Vertical (type/severity) _____
 Plan (type) Re-entrant corners

Exterior Falling Hazards: Unbraced Chimneys Heavy Cladding or Heavy Veneer
 Parapets Appendages
 Other: NONE



COMMENTS:
- Roof appears to be lite gypsum on bulb-tees.

Additional sketches or comments on separate page

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE, S_{L1}

FEMA BUILDING TYPE	Do Not Know	W1	W1A	W2	S1 (MRF)	S2 (BR)	S3 (LM)	S4 (RC SW)	S5 (URM INF)	C1 (MRF)	C2 (SW)	C3 (URM INF)	PC1 (TU)	PC2	RM1 (FD)	RM2 (RD)	URM	MH
Basic Score		2.1	1.9	1.8	1.5	1.4	1.6	1.4	1.2	1.0	1.2	0.9	1.1	1.0	1.1	1.1	0.9	1.1
Severe Vertical Irregularity, V _{L1}		-0.9	-0.9	-0.9	-0.8	-0.7	-0.8	-0.7	-0.7	-0.7	-0.8	-0.6	-0.7	-0.7	-0.7	-0.7	-0.6	NA
Moderate Vertical Irregularity, V _{L1}		-0.6	-0.5	-0.5	-0.4	-0.4	-0.5	-0.4	-0.3	-0.4	-0.4	-0.3	-0.4	-0.4	-0.4	-0.4	-0.3	NA
Plan Irregularity, P _{L1}		-0.7	-0.7	-0.6	-0.5	-0.5	-0.6	-0.4	-0.4	-0.4	-0.5	-0.3	-0.5	-0.4	-0.4	-0.4	-0.3	NA
Pre-Code		-0.3	-0.3	-0.3	-0.3	-0.2	-0.3	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	0.0
Post-Benchmark		1.9	1.9	2.0	1.0	1.1	1.1	1.5	NA	1.4	1.7	NA	1.5	1.7	1.6	1.6	NA	0.5
Soil Type A or B		0.5	0.5	0.4	0.3	0.3	0.4	0.3	0.2	0.2	0.3	0.1	0.3	0.2	0.3	0.3	0.1	0.1
Soil Type E (1-3 stories)		0.0	-0.2	-0.4	-0.3	-0.2	-0.2	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	-0.1
Soil Type E (> 3 stories)		-0.4	-0.4	-0.4	-0.3	-0.3	NA	-0.3	-0.1	-0.1	-0.3	-0.1	NA	-0.1	-0.2	-0.2	0.0	NA
Minimum Score, S _{MIN}		0.7	0.7	0.7	0.5	0.5	0.5	0.5	0.5	0.3	0.3	0.3	0.2	0.2	0.3	0.3	0.2	1.0

FINAL LEVEL 1 SCORE, S_{L1} ≥ S_{MIN}: 0.5

<p>EXTENT OF REVIEW</p> <p>Exterior: <input type="checkbox"/> Partial <input type="checkbox"/> All Sides <input checked="" type="checkbox"/> Aerial Interior: <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered</p> <p>Drawings Reviewed: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p> <p>Soil Type Source: Vs30</p> <p>Geologic Hazards Source: Regional Data</p> <p>Contact Person: Mike Brown</p> <hr/> <p>LEVEL 2 SCREENING PERFORMED?</p> <p><input checked="" type="checkbox"/> Yes, Final Level 2 Score, S_{L2} 0.9 <input type="checkbox"/> No</p> <p>Nonstructural hazards? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p>	<p>OTHER HAZARDS</p> <p>Are There Hazards That Trigger A Detailed Structural Evaluation?</p> <p><input type="checkbox"/> Pounding potential (unless S_{L2} > cut-off, if known)</p> <p><input type="checkbox"/> Falling hazards from taller adjacent building</p> <p><input type="checkbox"/> Geologic hazards or Soil Type F</p> <p><input type="checkbox"/> Significant damage/deterioration to the structural system</p>	<p>ACTION REQUIRED</p> <p>Detailed Structural Evaluation Required?</p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building</p> <p><input checked="" type="checkbox"/> Yes, score less than cut-off</p> <p><input type="checkbox"/> Yes, other hazards present</p> <p><input type="checkbox"/> No</p> <p>Detailed Nonstructural Evaluation Recommended? (check one)</p> <p><input checked="" type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated</p> <p><input type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary</p> <p><input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p>
--	---	--

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Rapid Visual Screening of Buildings for Potential Seismic Hazards

FEMA P-154 Data Collection Form

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

Level 2 (Optional)
VERY HIGH Seismicity

Bldg Name: Lee Hunter Elementary School	Final Level 1 Score: $S_{L1} = 0.5$	<i>(do not consider S_{MIN})</i>	
Screener: Varnell/Mills/Griffin	Level 1 Irregularity Modifiers:	Vertical Irregularity, $V_{L1} = 0$	Plan Irregularity, $P_{L1} = -0.4$
Date/Time: 9-11-15/ 11:00 am	ADJUSTED BASELINE SCORE:	$S' = (S_{L1} - V_{L1} - P_{L1}) = 0.9$	

STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

Topic	Statement (If statement is true, circle the "Yes" modifier, otherwise cross out the modifier.)	Yes	Subtotals
Vertical Irregularity, V_{L2}	Sloping Site	W1 building: There is at least a full story grade change from one side of the building to the other.	-0.9
		Non-W1 building: There is at least a full story grade change from one side of the building to the other.	-0.2
	Weak and/or Soft Story (circle one maximum)	W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.	-0.5
		W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum).	-0.9
		W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.	-0.9
		Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.	-0.7
		Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.	-0.4
	Setback	Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.	-0.7
		Vertical elements of the lateral system at upper stories are inboard of those at lower stories.	-0.4
		There is an in-plane offset of the lateral elements that is greater than the length of the elements.	-0.2
	Short Column/ Pier	C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.	-0.4
		C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.	-0.4
Split Level	There is a split level at one of the floor levels or at the roof.	-0.4	
Other Irregularity	There is another observable severe vertical irregularity that obviously affects the building's seismic performance.	-0.7	
	There is another observable moderate vertical irregularity that may affect the building's seismic performance.	-0.4	
Plan Irregularity, P_{L2}	Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.)	-0.5	
	Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.	-0.2	
	Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.	-0.2	
	Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.	-0.2	
	C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.	-0.2	
	Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.	-0.5	
Redundancy	The building has at least two bays of lateral elements on each side of the building in each direction.	+0.2	
Pounding	Building is separated from an adjacent structure by less than 1.5% of the height of the shorter of the building and adjacent structure and:	The floors do not align vertically within 2 feet.	-0.7
		One building is 2 or more stories taller than the other.	-0.7
		The building is at the end of the block.	-0.4
S2 Building	"K" bracing geometry is visible.	-0.7	
C1 Building	Flat plate serves as the beam in the moment frame.	-0.3	
PC1/RM1 Bldg	There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)	+0.2	
PC1/RM1 Bldg	The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).	+0.2	
URM	Gable walls are present.	-0.3	
MH	There is a supplemental seismic bracing system provided between the carriage and the ground.	+0.5	
Retrofit	Comprehensive seismic retrofit is visible or known from drawings.	+1.2	
			$V_{L2} = -0.0$ <i>(Cap at -0.9)</i>
			$P_{L2} = -0.2$ <i>(Cap at -0.7)</i>
			$M = +0.2$

FINAL LEVEL 2 SCORE, $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$: 0.9 *(Transfer to Level 1 form)*

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance: Yes No
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

OBSERVABLE NONSTRUCTURAL HAZARDS

Location	Statement (Check "Yes" or "No")	Yes	No	Comment
Exterior	There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.		X	
	There is heavy cladding or heavy veneer.		X	
	There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported.		X	
	There is an unreinforced masonry appendage over exit doors or pedestrian walkways.		X	
	There is a sign posted on the building that indicates hazardous materials are present.		X	
	There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney.		X	
	Other observed exterior nonstructural falling hazard:		X	
Interior	There are hollow clay tile or brick partitions at any stair or exit corridor.	X		CMU partition walls
	Other observed interior nonstructural falling hazard:	X		contents


Estimated Nonstructural Seismic Performance (Check appropriate box and transfer to Level 1 form conclusions)

- Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended
- Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required
- Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

Comments:



Address: 604 Elm Street
Sikeston, MO Zip: 63801
Other Identifiers: Sikeston R-6 District
Building Name: Matthews Elementary School
Use: K-12 School
Latitude: 36.874991 Longitude: -89.573143
Ss: 2.460g Sr: 0.915g
Screener(s): CS, JE, DK Date/Time: 9-11-15/
No. Stories: Above Grade: 1 Below Grade: 0 Year Built: 1955 EST
Total Floor Area (sq. ft.): 25,800 Code Year: Unknown
Additions: None Yes, Year(s) Built: _____
Occupancy: Assembly Commercial Emer. Services Historic Shelter
Industrial Office School Government
Utility Warehouse Residential, # Units: _____



Soil Type: A B C D E F DNK
Hard Avg Dense Stiff Soft Poor If DNK, assume Type D.
Rock Rock Soil Soil Soil Soil
Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK
Adjacency: Pounding Falling Hazards from Taller Adjacent Building
Irregularities: Vertical (type/severity) _____
 Plan (type) Re-entrant corner
Exterior Falling Hazards: Unbraced Chimneys Heavy Cladding or Heavy Veneer
 Parapets Appendages
 Other: _____
COMMENTS:
- Unanchored items in egress
- Natural gas water heater, boiler & stove
- Unreinforced masonry partitions
 Additional sketches or comments on separate page

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE, S_{L1}

FEMA BUILDING TYPE	Do Not Know	W1	W1A	W2	S1 (MRF)	S2 (BR)	S3 (LM)	S4 (RC SW)	S5 (URM INF)	C1 (MRF)	C2 (SW)	C3 (URM INF)	PC1 (TU)	PC2	RM1 (FD)	RM2 (RD)	URM	MH
Basic Score		2.1	1.9	1.8	1.5	1.4	1.6	1.4	1.2	1.0	1.2	0.9	1.1	1.0	1.1	1.1	0.9	1.1
Severe Vertical Irregularity, V _{L1}		-0.9	-0.9	-0.9	-0.8	-0.7	-0.8	-0.7	-0.7	-0.7	-0.8	-0.6	-0.7	-0.7	-0.7	-0.7	-0.6	NA
Moderate Vertical Irregularity, V _{L1}		-0.6	-0.5	-0.5	-0.4	-0.4	-0.5	-0.4	-0.3	-0.4	-0.4	-0.3	-0.4	-0.4	-0.4	-0.4	-0.3	NA
Plan Irregularity, P _{L1}		-0.7	-0.7	-0.6	-0.5	-0.5	-0.6	-0.4	-0.4	-0.4	-0.5	-0.3	-0.5	-0.4	-0.4	-0.4	-0.3	NA
Pre-Code		-0.3	-0.3	-0.3	-0.3	-0.2	-0.3	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	0.0
Post-Benchmark		1.9	1.9	2.0	1.0	1.1	1.1	1.5	NA	1.4	1.7	NA	1.5	1.7	1.6	1.6	NA	0.5
Soil Type A or B		0.5	0.5	0.4	0.3	0.3	0.4	0.3	0.2	0.2	0.3	0.1	0.3	0.2	0.3	0.3	0.1	0.1
Soil Type E (1-3 stories)		0.0	-0.2	-0.4	-0.3	-0.2	-0.2	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	-0.1
Soil Type E (> 3 stories)		-0.4	-0.4	-0.4	-0.3	-0.3	NA	-0.3	-0.1	-0.1	-0.3	-0.1	NA	-0.1	-0.2	-0.2	0.0	NA
Minimum Score, S _{MIN}		0.7	0.7	0.7	0.5	0.5	0.5	0.5	0.5	0.3	0.3	0.3	0.2	0.2	0.3	0.3	0.2	1.0

FINAL LEVEL 1 SCORE, S_{L1} ≥ S_{MIN}: 0.6

<p>EXTENT OF REVIEW</p> <p>Exterior: <input type="checkbox"/> Partial <input checked="" type="checkbox"/> All Sides <input type="checkbox"/> Aerial Interior: <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered Drawings Reviewed: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Soil Type Source: Vs30 Geologic Hazards Source: Regional Data Contact Person: Mike Brown</p> <p>LEVEL 2 SCREENING PERFORMED?</p> <p><input checked="" type="checkbox"/> Yes, Final Level 2 Score, S_{L2} 0.9 <input type="checkbox"/> No Nonstructural hazards? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p>	<p>OTHER HAZARDS</p> <p>Are There Hazards That Trigger A Detailed Structural Evaluation?</p> <p><input type="checkbox"/> Pounding potential (unless S_{L2} > cut-off, if known) <input type="checkbox"/> Falling hazards from taller adjacent building <input type="checkbox"/> Geologic hazards or Soil Type F <input type="checkbox"/> Significant damage/deterioration to the structural system</p>	<p>ACTION REQUIRED</p> <p>Detailed Structural Evaluation Required?</p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building <input checked="" type="checkbox"/> Yes, score less than cut-off <input type="checkbox"/> Yes, other hazards present <input type="checkbox"/> No</p> <p>Detailed Nonstructural Evaluation Recommended? (check one)</p> <p><input checked="" type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated <input type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary <input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p>
---	--	---

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Rapid Visual Screening of Buildings for Potential Seismic Hazards

FEMA P-154 Data Collection Form

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

Level 2 (Optional)
VERY HIGH Seismicity

Bldg Name: Matthew Elementary School	Final Level 1 Score: $S_{L1} = 0.6$	<i>(do not consider S_{MIN})</i>	
Screener: CS, JE, DK	Level 1 Irregularity Modifiers:	Vertical Irregularity, $V_{L1} = 0$	Plan Irregularity, $P_{L1} = -0.3$
Date/Time: 9-11-15/	ADJUSTED BASELINE SCORE:	$S' = (S_{L1} - V_{L1} - P_{L1}) = 0.9$	

STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

Topic	Statement (If statement is true, circle the "Yes" modifier, otherwise cross out the modifier.)	Yes	Subtotals
Vertical Irregularity, V_{L2}	Sloping Site	W1 building: There is at least a full story grade change from one side of the building to the other.	-0.9
		Non-W1 building: There is at least a full story grade change from one side of the building to the other.	-0.2
	Weak and/or Soft Story (circle one maximum)	W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.	-0.5
		W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum).	-0.9
		W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.	-0.9
		Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.	-0.7
		Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.	-0.4
	Setback	Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.	-0.7
		Vertical elements of the lateral system at upper stories are inboard of those at lower stories.	-0.4
		There is an in-plane offset of the lateral elements that is greater than the length of the elements.	-0.2
	Short Column/ Pier	C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.	-0.4
		C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.	-0.4
Split Level	There is a split level at one of the floor levels or at the roof.	-0.4	
Other Irregularity	There is another observable severe vertical irregularity that obviously affects the building's seismic performance.	-0.7	
	There is another observable moderate vertical irregularity that may affect the building's seismic performance.	-0.4	
Plan Irregularity, P_{L2}	Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.)	-0.5	
	Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.	-0.2	
	Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.	-0.2	
	Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.	-0.2	
	C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.	-0.2	
	Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.	-0.5	
Redundancy	The building has at least two bays of lateral elements on each side of the building in each direction.		+0.2
Pounding	Building is separated from an adjacent structure by less than 1.5% of the height of the shorter of the building and adjacent structure and:	The floors do not align vertically within 2 feet.	-0.7
		One building is 2 or more stories taller than the other.	-0.7
		The building is at the end of the block.	-0.4
S2 Building	"K" bracing geometry is visible.		-0.7
C1 Building	Flat plate serves as the beam in the moment frame.		-0.3
PC1/RM1 Bldg	There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)		+0.2
PC1/RM1 Bldg	The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).		+0.2
URM	Gable walls are present.		-0.3
MH	There is a supplemental seismic bracing system provided between the carriage and the ground.		+0.5
Retrofit	Comprehensive seismic retrofit is visible or known from drawings.		+1.2
FINAL LEVEL 2 SCORE, $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$:			0.9
			<i>(Transfer to Level 1 form)</i>

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance: Yes No
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

OBSERVABLE NONSTRUCTURAL HAZARDS

Location	Statement (Check "Yes" or "No")	Yes	No	Comment
Exterior	There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.		X	
	There is heavy cladding or heavy veneer.	X		
	There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported.	X		Canopy over egress
	There is an unreinforced masonry appendage over exit doors or pedestrian walkways.		X	
	There is a sign posted on the building that indicates hazardous materials are present.		X	
	There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney.		X	
Interior	Other observed exterior nonstructural falling hazard:		X	
Interior	There are hollow clay tile or brick partitions at any stair or exit corridor.	X		
	Other observed interior nonstructural falling hazard:	X		

Estimated Nonstructural Seismic Performance (Check appropriate box and transfer to Level 1 form conclusions)
 Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended
 Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required
 Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

Comments:



Address: 2300 Ables Road
Sikeston, MO Zip: 63801
Other Identifiers: Sikeston R-6 District
Building Name: Southeast Elementary School
Use: K-12 School
Latitude: 36.876090 Longitude: -89.547930
Ss: 2.507g Sr: 0.938g
Screener(s): CS, JE, DK Date/Time: 9-11-15/

No. Stories: Above Grade: 1 Below Grade: 0 Year Built: 1968 EST
Total Floor Area (sq. ft.): 27,702 Code Year: Unknown
Additions: None Yes, Year(s) Built: _____

Occupancy: Assembly Commercial Emer. Services Historic Shelter
Industrial Office School Government
Utility Warehouse Residential, # Units: _____

Soil Type: A B C D E F DNK
Hard Avg Dense Stiff Soft Poor DNK
Rock Rock Soil Soil Soil Soil
If DNK, assume Type D

Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

Adjacency: Pounding Falling Hazards from Taller Adjacent Building

Irregularities: Vertical (type/severity) _____
 Plan (type) Irregular

Exterior Falling Hazards: Unbraced Chimneys Heavy Cladding or Heavy Veneer
 Parapets Appendages
 Other: _____

COMMENTS:
- Natural gas boiler, water heater & stove unanchored
- Interior bookshelves unanchored
- Lights anchored to structure
- Office area w/unanchored bookshelves, file cabinets & copy machines
- Unanchored items near egress

 Additional sketches or comments on separate page



610.021(20)

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE, S_{L1}

FEMA BUILDING TYPE	Do Not Know	W1	W1A	W2	S1 (MRF)	S2 (BR)	S3 (LM)	S4 (RC SW)	S5 (URM INF)	C1 (MRF)	C2 (SW)	C3 (URM INF)	PC1 (TU)	PC2	RM1 (FD)	RM2 (RD)	URM	MH
Basic Score		2.1	1.9	1.8	1.5	1.4	1.6	1.4	1.2	1.0	1.2	0.9	1.1	1.0	1.1	1.1	0.9	1.1
Severe Vertical Irregularity, V _{L1}		-0.9	-0.9	-0.9	-0.8	-0.7	-0.8	-0.7	-0.7	-0.7	-0.8	-0.6	-0.7	-0.7	-0.7	-0.7	-0.6	NA
Moderate Vertical Irregularity, V _{L1}		-0.6	-0.5	-0.5	-0.4	-0.4	-0.5	-0.4	-0.3	-0.4	-0.4	-0.3	-0.4	-0.4	-0.4	-0.4	-0.3	NA
Plan Irregularity, P _{L1}		-0.7	-0.7	-0.6	-0.5	-0.5	-0.6	-0.4	-0.4	-0.4	-0.5	-0.3	-0.5	-0.4	-0.4	-0.4	-0.3	NA
Pre-Code		-0.3	-0.3	-0.3	-0.3	-0.2	-0.3	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	0.0
Post-Benchmark		1.9	1.9	2.0	1.0	1.1	1.1	1.5	NA	1.4	1.7	NA	1.5	1.7	1.6	1.6	NA	0.5
Soil Type A or B		0.5	0.5	0.4	0.3	0.3	0.4	0.3	0.2	0.2	0.3	0.1	0.3	0.2	0.3	0.3	0.1	0.1
Soil Type E (1-3 stories)		0.0	-0.2	-0.4	-0.3	-0.2	-0.2	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	-0.1
Soil Type E (> 3 stories)		-0.4	-0.4	-0.4	-0.3	-0.3	NA	-0.3	-0.1	-0.1	-0.3	-0.1	NA	-0.1	-0.2	-0.2	0.0	NA
Minimum Score, S _{MIN}		0.7	0.7	0.7	0.5	0.5	0.5	0.5	0.5	0.3	0.3	0.3	0.2	0.2	0.3	0.3	0.2	1.0

FINAL LEVEL 1 SCORE, S_{L1} ≥ S_{MIN}: 0.6

<p>EXTENT OF REVIEW</p> <p>Exterior: <input type="checkbox"/> Partial <input checked="" type="checkbox"/> All Sides <input type="checkbox"/> Aerial Interior: <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered Drawings Reviewed: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Soil Type Source: Vs30 Geologic Hazards Source: Regional Data Contact Person: Mike Brown</p> <p>LEVEL 2 SCREENING PERFORMED?</p> <p><input checked="" type="checkbox"/> Yes, Final Level 2 Score, S_{L2} 0.5 <input type="checkbox"/> No Nonstructural hazards? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p>	<p>OTHER HAZARDS</p> <p>Are There Hazards That Trigger A Detailed Structural Evaluation?</p> <p><input type="checkbox"/> Pounding potential (unless S_{L2} > cut-off, if known) <input type="checkbox"/> Falling hazards from taller adjacent building <input type="checkbox"/> Geologic hazards or Soil Type F <input type="checkbox"/> Significant damage/deterioration to the structural system</p>	<p>ACTION REQUIRED</p> <p>Detailed Structural Evaluation Required?</p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building <input checked="" type="checkbox"/> Yes, score less than cut-off <input type="checkbox"/> Yes, other hazards present <input type="checkbox"/> No</p> <p>Detailed Nonstructural Evaluation Recommended? (check one)</p> <p><input checked="" type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated <input type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary <input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p>
---	--	---

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Rapid Visual Screening of Buildings for Potential Seismic Hazards

FEMA P-154 Data Collection Form

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

Level 2 (Optional)
VERY HIGH Seismicity

Bldg Name: Southeast Elementary School	Final Level 1 Score: $S_{L1} = 0.6$	<i>(do not consider S_{MIN})</i>	
Screener: CS, JE, DK	Level 1 Irregularity Modifiers:	Vertical Irregularity, $V_{L1} = 0$	Plan Irregularity, $P_{L1} = -0.3$
Date/Time: 9-11-15/	ADJUSTED BASELINE SCORE:	$S' = (S_{L1} - V_{L1} - P_{L1}) = 0.9$	

STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

Topic	Statement (If statement is true, circle the "Yes" modifier, otherwise cross out the modifier.)	Yes	Subtotals
Vertical Irregularity, V_{L2}	Sloping Site	W1 building: There is at least a full story grade change from one side of the building to the other.	-0.9
		Non-W1 building: There is at least a full story grade change from one side of the building to the other.	-0.2
	Weak and/or Soft Story (circle one maximum)	W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.	-0.5
		W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum).	-0.9
		W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.	-0.9
		Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.	-0.7
		Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.	-0.4
	Setback	Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.	-0.7
		Vertical elements of the lateral system at upper stories are inboard of those at lower stories.	-0.4
		There is an in-plane offset of the lateral elements that is greater than the length of the elements.	-0.2
	Short Column/ Pier	C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.	-0.4
		C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.	-0.4
Split Level	There is a split level at one of the floor levels or at the roof.	-0.4	
Other Irregularity	There is another observable severe vertical irregularity that obviously affects the building's seismic performance.	-0.7	
	There is another observable moderate vertical irregularity that may affect the building's seismic performance.	-0.4	
Plan Irregularity, P_{L2}	Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.)	-0.5	
	Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.	-0.2	
	Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.	-0.2	
	Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.	-0.2	
	C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.	-0.2	
	Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.	-0.5	
Redundancy	The building has at least two bays of lateral elements on each side of the building in each direction.	+0.2	
Pounding	Building is separated from an adjacent structure by less than 1.5% of the height of the shorter of the building and adjacent structure and:	The floors do not align vertically within 2 feet.	(Cap total pounding modifiers at -0.9) -0.7
		One building is 2 or more stories taller than the other.	-0.7
		The building is at the end of the block.	-0.4
S2 Building	"K" bracing geometry is visible.	-0.7	
C1 Building	Flat plate serves as the beam in the moment frame.	-0.3	
PC1/RM1 Bldg	There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)	+0.2	
PC1/RM1 Bldg	The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).	+0.2	
URM	Gable walls are present.	-0.3	
MH	There is a supplemental seismic bracing system provided between the carriage and the ground.	+0.5	
Retrofit	Comprehensive seismic retrofit is visible or known from drawings.	+1.2	
FINAL LEVEL 2 SCORE, $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$:			0.5 (Transfer to Level 1 form)
There is observable damage or deterioration or another condition that negatively affects the building's seismic performance: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.			

FINAL LEVEL 2 SCORE, $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$: 0.5 (Transfer to Level 1 form)

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance: Yes No
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

OBSERVABLE NONSTRUCTURAL HAZARDS

Location	Statement (Check "Yes" or "No")	Yes	No	Comment
Exterior	There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.		X	
	There is heavy cladding or heavy veneer.	X		
	There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported.	X		
	There is an unreinforced masonry appendage over exit doors or pedestrian walkways.		X	
	There is a sign posted on the building that indicates hazardous materials are present.		X	
	There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney.		X	
	Other observed exterior nonstructural falling hazard:		X	
Interior	There are hollow clay tile or brick partitions at any stair or exit corridor.	X		
	Other observed interior nonstructural falling hazard:	X		

Estimated Nonstructural Seismic Performance (Check appropriate box and transfer to Level 1 form conclusions)

Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended

Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required

Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

Comments:



Address: 835 W. Murray Lane
Sikeston, MO Zip: 63801

Other Identifiers: Sikeston R-6 District

Building Name: Alternative Center - Wings A & C

Use: K-12 School

Latitude: 36.866032 Longitude: -89.601513

Ss: 2.438g Sr: 0.906g

Screener(s): CS, JE, DK Date/Time: 9-11-2015/

No. Stories: Above Grade: 1 Below Grade: 0 Year Built: 1964 EST

Total Floor Area (sq. ft.): 27,981 Code Year: Unknown

Additions: None Yes, Year(s) Built: _____

Occupancy: Assembly Commercial Emer. Services Historic Shelter
Industrial Office School Government
Utility Warehouse Residential, # Units: _____

Soil Type: A B C D E F DNK
Hard Avg Dense Stiff Soft Poor *If DNK, assume Type D.*
Rock Rock Soil Soil Soil Soil

Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

Adjacency: Pounding Falling Hazards from Taller Adjacent Building

Irregularities: Vertical (type/severity) _____
 Plan (type) Re-entrant corner

Exterior Falling Hazards: Unbraced Chimneys Heavy Cladding or Heavy Veneer
 Parapets Appendages
 Other: _____

610.021(20)

COMMENTS:
- Items near classroom doors
- URM partitions - unbraced @ top

Additional sketches or comments on separate page

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE, S_{L1}

FEMA BUILDING TYPE	Do Not Know	W1	W1A	W2	S1 (MRF)	S2 (BR)	S3 (LM)	S4 (RC SW)	S5 (URM INF)	C1 (MRF)	C2 (SW)	C3 (URM INF)	PC1 (TU)	PC2	RM1 (FD)	RM2 (RD)	URM	MH
Basic Score		2.1	1.9	1.8	1.5	1.4	1.6	1.4	1.2	1.0	1.2	0.9	1.1	1.0	1.1	1.1	0.9	1.1
Severe Vertical Irregularity, V_{L1}		-0.9	-0.9	-0.9	-0.8	-0.7	-0.8	-0.7	-0.7	-0.7	-0.8	-0.6	-0.7	-0.7	-0.7	-0.7	-0.6	NA
Moderate Vertical Irregularity, V_{L1}		-0.6	-0.5	-0.5	-0.4	-0.4	-0.5	-0.4	-0.3	-0.4	-0.4	-0.3	-0.4	-0.4	-0.4	-0.4	-0.3	NA
Plan Irregularity, P_{L1}		-0.7	-0.7	-0.6	-0.5	-0.5	-0.6	-0.4	-0.4	-0.4	-0.5	-0.3	-0.5	-0.4	-0.4	-0.4	-0.3	NA
Pre-Code		-0.3	-0.3	-0.3	-0.3	-0.2	-0.3	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	0.0
Post-Benchmark		1.9	1.9	2.0	1.0	1.1	1.1	1.5	NA	1.4	1.7	NA	1.5	1.7	1.6	1.6	NA	0.5
Soil Type A or B		0.5	0.5	0.4	0.3	0.3	0.4	0.3	0.2	0.2	0.3	0.1	0.3	0.2	0.3	0.3	0.1	0.1
Soil Type E (1-3 stories)		0.0	-0.2	-0.4	-0.3	-0.2	-0.2	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	-0.1
Soil Type E (> 3 stories)		-0.4	-0.4	-0.4	-0.3	-0.3	NA	-0.3	-0.1	-0.1	-0.3	-0.1	NA	-0.1	-0.2	-0.2	0.0	NA
Minimum Score, S_{MIN}		0.7	0.7	0.7	0.5	0.5	0.5	0.5	0.5	0.3	0.3	0.3	0.2	0.2	0.3	0.3	0.2	1.0

FINAL LEVEL 1 SCORE, $S_{L1} \geq S_{MIN}$: 0.6

<p>EXTENT OF REVIEW</p> <p>Exterior: <input type="checkbox"/> Partial <input checked="" type="checkbox"/> All Sides <input type="checkbox"/> Aerial Interior: <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered Drawings Reviewed: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Soil Type Source: Vs30 Geologic Hazards Source: Regional Data Contact Person: Mike Brown</p> <p>LEVEL 2 SCREENING PERFORMED?</p> <p><input checked="" type="checkbox"/> Yes, Final Level 2 Score, S_{L2} 0.9 <input type="checkbox"/> No Nonstructural hazards? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p>	<p>OTHER HAZARDS</p> <p>Are There Hazards That Trigger A Detailed Structural Evaluation?</p> <p><input type="checkbox"/> Pounding potential (unless $S_{L2} >$ cut-off, if known) <input type="checkbox"/> Falling hazards from taller adjacent building <input type="checkbox"/> Geologic hazards or Soil Type F <input type="checkbox"/> Significant damage/deterioration to the structural system</p>	<p>ACTION REQUIRED</p> <p>Detailed Structural Evaluation Required?</p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building <input checked="" type="checkbox"/> Yes, score less than cut-off <input type="checkbox"/> Yes, other hazards present <input type="checkbox"/> No</p> <p>Detailed Nonstructural Evaluation Recommended? (check one)</p> <p><input type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated <input checked="" type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary <input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p>
--	---	---

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Rapid Visual Screening of Buildings for Potential Seismic Hazards

FEMA P-154 Data Collection Form

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

Level 2 (Optional)
VERY HIGH Seismicity

Bldg Name: Alternative Center – Wings A, B & C	Final Level 1 Score: $S_{L1} = 0.6$	<i>(do not consider S_{MIN})</i>	
Screener: CS, JE, DK	Level 1 Irregularity Modifiers:	Vertical Irregularity, $V_{L1} = 0$	Plan Irregularity, $P_{L1} = -0.3$
Date/Time: 9-11-2015/	ADJUSTED BASELINE SCORE:	$S' = (S_{L1} - V_{L1} - P_{L1}) = 0.9$	

STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

Topic	Statement (If statement is true, circle the "Yes" modifier, otherwise cross out the modifier.)	Yes	Subtotals
Vertical Irregularity, V_{L2}	Sloping Site	W1 building: There is at least a full story grade change from one side of the building to the other.	-0.9
		Non-W1 building: There is at least a full story grade change from one side of the building to the other.	-0.2
	Weak and/or Soft Story (circle one maximum)	W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.	-0.5
		W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum).	-0.9
		W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.	-0.9
		Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.	-0.7
		Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.	-0.4
	Setback	Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.	-0.7
		Vertical elements of the lateral system at upper stories are inboard of those at lower stories.	-0.4
		There is an in-plane offset of the lateral elements that is greater than the length of the elements.	-0.2
	Short Column/ Pier	C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.	-0.4
		C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.	-0.4
	Split Level	There is a split level at one of the floor levels or at the roof.	-0.4
Other Irregularity	There is another observable severe vertical irregularity that obviously affects the building's seismic performance.	-0.7	
	There is another observable moderate vertical irregularity that may affect the building's seismic performance.	-0.4	
Plan Irregularity, P_{L2}	Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.)	-0.5	
	Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.	-0.2	
	Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.	-0.2	
	Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.	-0.2	
	C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.	-0.2	
	Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.	-0.5	
Redundancy	The building has at least two bays of lateral elements on each side of the building in each direction.	+0.2	
Pounding	Building is separated from an adjacent structure by less than 1.5% of the height of the shorter of the building and adjacent structure and:	The floors do not align vertically within 2 feet.	(Cap total pounding modifiers at -0.9) -0.7
		One building is 2 or more stories taller than the other.	-0.7
		The building is at the end of the block.	-0.4
S2 Building	"K" bracing geometry is visible.	-0.7	
C1 Building	Flat plate serves as the beam in the moment frame.	-0.3	
PC1/RM1 Bldg	There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)	+0.2	
PC1/RM1 Bldg	The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).	+0.2	
URM	Gable walls are present.	-0.3	
MH	There is a supplemental seismic bracing system provided between the carriage and the ground.	+0.5	
Retrofit	Comprehensive seismic retrofit is visible or known from drawings.	+1.2	
			$M = +0.2$

FINAL LEVEL 2 SCORE, $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$: 0.9 *(Transfer to Level 1 form)*

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance: Yes No
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

OBSERVABLE NONSTRUCTURAL HAZARDS

Location	Statement (Check "Yes" or "No")	Yes	No	Comment
Exterior	There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.		X	
	There is heavy cladding or heavy veneer.	X		Brick veneer
	There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported.		X	
	There is an unreinforced masonry appendage over exit doors or pedestrian walkways.		X	
	There is a sign posted on the building that indicates hazardous materials are present.		X	
	There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney.		X	
	Other observed exterior nonstructural falling hazard:		X	
Interior	There are hollow clay tile or brick partitions at any stair or exit corridor.		X	
	Other observed interior nonstructural falling hazard:	X		

Estimated Nonstructural Seismic Performance (Check appropriate box and transfer to Level 1 form conclusions)
 Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended
 Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required
 Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

Comments:



Address: 835 W. Murray Lane
Sikeston, MO Zip: 63801

Other Identifiers: Sikeston R-6 District

Building Name: Alternative Center - Main Building/Wing B

Use: K-12 School

Latitude: 36.866032 Longitude: -89.601513

Ss: 2.438g S: 0.906g

Screener(s): CS, JE, DK Date/Time: 9-11-2015/

No. Stories: Above Grade: 1 Below Grade: 0 Year Built: 1964 EST

Total Floor Area (sq. ft.): 27,981 Code Year: Unknown

Additions: None Yes, Year(s) Built: _____

Occupancy: Assembly Commercial Emer. Services Historic Shelter
Industrial Office School Government
Utility Warehouse Residential, # Units: _____

Soil Type: A B C D E F DNK
Hard Avg Dense Stiff Soft Poor DNK
Rock Rock Soil Soil Soil Soil *If DNK, assume Type D.*

Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

Adjacency: Pounding Falling Hazards from Taller Adjacent Building

Irregularities: Vertical (type/severity) _____
 Plan (type) Re-entrant corner

Exterior Falling Hazards: Unbraced Chimneys Heavy Cladding or Heavy Veneer
 Parapets Appendages
 Other: _____

610.021(20)

COMMENTS:

- URM partitions - unbraced @ top
- Unanchored interior bookshelves in Library
- Unanchored natural gas systems
- Unanchored file cabinets & copy machine in office
- Unanchored items near classrooms doors

Additional sketches or comments on separate page

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE, S_{L1}

FEMA BUILDING TYPE	Do Not Know	W1	W1A	W2	S1 (MRF)	S2 (BR)	S3 (LM)	S4 (RC SW)	S5 (URM INF)	C1 (MRF)	C2 (SW)	C3 (URM INF)	PC1 (TU)	PC2	RM1 (FD)	RM2 (RD)	URM	MH
Basic Score		2.1	1.9	1.8	1.5	1.4	1.6	1.4	1.2	1.0	1.2	0.9	1.1	1.0	1.1	1.1	0.9	1.1
Severe Vertical Irregularity, V _{L1}		-0.9	-0.9	-0.9	-0.8	-0.7	-0.8	-0.7	-0.7	-0.7	-0.8	-0.6	-0.7	-0.7	-0.7	-0.7	-0.6	NA
Moderate Vertical Irregularity, V _{L1}		-0.6	-0.5	-0.5	-0.4	-0.4	-0.5	-0.4	-0.3	-0.4	-0.4	-0.3	-0.4	-0.4	-0.4	-0.4	-0.3	NA
Plan Irregularity, P _{L1}		-0.7	-0.7	-0.6	-0.5	-0.5	-0.6	-0.4	-0.4	-0.4	-0.5	-0.3	-0.5	-0.4	-0.4	-0.4	-0.3	NA
Pre-Code		-0.3	-0.3	-0.3	-0.3	-0.2	-0.3	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	0.0
Post-Benchmark		1.9	1.9	2.0	1.0	1.1	1.1	1.5	NA	1.4	1.7	NA	1.5	1.7	1.6	1.6	NA	0.5
Soil Type A or B		0.5	0.5	0.4	0.3	0.3	0.4	0.3	0.2	0.2	0.3	0.1	0.3	0.2	0.3	0.3	0.1	0.1
Soil Type E (1-3 stories)		0.0	-0.2	-0.4	-0.3	-0.2	-0.2	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	-0.1
Soil Type E (> 3 stories)		-0.4	-0.4	-0.4	-0.3	-0.3	NA	-0.3	-0.1	-0.1	-0.3	-0.1	NA	-0.1	-0.2	-0.2	0.0	NA
Minimum Score, S _{MIN}		0.7	0.7	0.7	0.5	0.5	0.5	0.5	0.5	0.3	0.3	0.3	0.2	0.2	0.3	0.3	0.2	1.0

FINAL LEVEL 1 SCORE, S_{L1} ≥ S_{MIN}: 0.6

<p>EXTENT OF REVIEW</p> <p>Exterior: <input type="checkbox"/> Partial <input checked="" type="checkbox"/> All Sides <input type="checkbox"/> Aerial Interior: <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered Drawings Reviewed: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Soil Type Source: Vs30 Geologic Hazards Source: Regional Data Contact Person: Mike Brown</p> <p>LEVEL 2 SCREENING PERFORMED?</p> <p><input checked="" type="checkbox"/> Yes, Final Level 2 Score, S_{L2} 0.9 <input type="checkbox"/> No Nonstructural hazards? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p>	<p>OTHER HAZARDS</p> <p>Are There Hazards That Trigger A Detailed Structural Evaluation?</p> <p><input type="checkbox"/> Pounding potential (unless S_{L2} > cut-off, if known) <input type="checkbox"/> Falling hazards from taller adjacent building <input type="checkbox"/> Geologic hazards or Soil Type F <input type="checkbox"/> Significant damage/deterioration to the structural system</p>	<p>ACTION REQUIRED</p> <p>Detailed Structural Evaluation Required?</p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building <input checked="" type="checkbox"/> Yes, score less than cut-off <input type="checkbox"/> Yes, other hazards present <input type="checkbox"/> No</p> <p>Detailed Nonstructural Evaluation Recommended? (check one)</p> <p><input checked="" type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated <input checked="" type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary <input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p>
---	--	--

Where information cannot be verified, screener shall note the following: wing: EST = Estimated or unreliable data OR DNK = Do Not Know

Rapid Visual Screening of Buildings for Potential Seismic Hazards

FEMA P-154 Data Collection Form

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

Level 2 (Optional)
VERY HIGH Seismicity

Bldg Name: Alternative Center – Main Building	Final Level 1 Score: $S_{L1} = 0.6$ <i>(do not consider S_{MIN})</i>
Screener: CS, JE, DK	Level 1 Irregularity Modifiers: <i>Vertical Irregularity, $V_{L1} = 0$</i> <i>Plan Irregularity, $P_{L1} = -0.3$</i>
Date/Time: 9-11-2015/	ADJUSTED BASELINE SCORE: $S' = (S_{L1} - V_{L1} - P_{L1}) = 0.9$

STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

Topic	Statement (If statement is true, circle the "Yes" modifier, otherwise cross out the modifier.)	Yes	Subtotals
Vertical Irregularity, V_{L2}	Sloping Site	W1 building: There is at least a full story grade change from one side of the building to the other.	-0.9
		Non-W1 building: There is at least a full story grade change from one side of the building to the other.	-0.2
	Weak and/or Soft Story (circle one maximum)	W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.	-0.5
		W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum).	-0.9
		W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.	-0.9
		Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.	-0.7
		Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.	-0.4
	Setback	Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.	-0.7
		Vertical elements of the lateral system at upper stories are inboard of those at lower stories.	-0.4
		There is an in-plane offset of the lateral elements that is greater than the length of the elements.	-0.2
	Short Column/ Pier	C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.	-0.4
		C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.	-0.4
Split Level	There is a split level at one of the floor levels or at the roof.	-0.4	
Other Irregularity	There is another observable severe vertical irregularity that obviously affects the building's seismic performance.	-0.7	
	There is another observable moderate vertical irregularity that may affect the building's seismic performance.	-0.4	
Plan Irregularity, P_{L2}	Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.)	-0.5	
	Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.	-0.2	
	Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.	-0.2	
	Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.	-0.2	
	C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.	-0.2	
	Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.	-0.5	
Redundancy	The building has at least two bays of lateral elements on each side of the building in each direction.	+0.2	
Pounding	Building is separated from an adjacent structure by less than 1.5% of the height of the shorter of the building and adjacent structure and:	The floors do not align vertically within 2 feet.	-0.7
		One building is 2 or more stories taller than the other.	-0.7
		The building is at the end of the block.	-0.4
S2 Building	"K" bracing geometry is visible.	-0.7	
C1 Building	Flat plate serves as the beam in the moment frame.	-0.3	
PC1/RM1 Bldg	There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)	+0.2	
PC1/RM1 Bldg	The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).	+0.2	
URM	Gable walls are present.	-0.3	
MH	There is a supplemental seismic bracing system provided between the carriage and the ground.	+0.5	
Retrofit	Comprehensive seismic retrofit is visible or known from drawings.	+1.2	
FINAL LEVEL 2 SCORE, $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$:			0.9 <i>(Transfer to Level 1 form)</i>

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance: Yes No
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

OBSERVABLE NONSTRUCTURAL HAZARDS

Location	Statement (Check "Yes" or "No")	Yes	No	Comment
Exterior	There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.		X	
	There is heavy cladding or heavy veneer.	X		Brick veneer over CMU
	There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported.	X		Steel canopy w/masonry
	There is an unreinforced masonry appendage over exit doors or pedestrian walkways.		X	
	There is a sign posted on the building that indicates hazardous materials are present.		X	
	There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney.		X	
Interior	Other observed exterior nonstructural falling hazard:		X	
	There are hollow clay tile or brick partitions at any stair or exit corridor.		X	
	Other observed interior nonstructural falling hazard:	X		Interior bookcase – URM partition

Estimated Nonstructural Seismic Performance (Check appropriate box and transfer to Level 1 form conclusions)
 Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended
 Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required
 Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

Comments:

Rapid Visual Screening of Buildings for Potential Seismic Hazards

FEMA P-154 Data Collection Form

Level 1
VERY HIGH Seismicity



Address: 835 W. Murray Lane
Sikeston, MO Zip: 63801
Other Identifiers: Sikeston R-6 District
Building Name: Alternative Center – Add't Building/Trailer
Use: K-12 School
Latitude: 36.866032 Longitude: -89.601513
Ss: 2.438g S_r: 0.906g
Screener(s): CS, JE, DK Date/Time: 9-11-2015/

No. Stories: Above Grade: 1 Below Grade: 0 Year Built: 1964 EST
Total Floor Area (sq. ft.): 1,750 Code Year: Unknown
Additions: None Yes, Year(s) Built: _____

Occupancy: Assembly Commercial Emer. Services Historic Shelter
Industrial Office School Government
Utility Warehouse Residential, # Units: _____

Soil Type: A B C D E F DNK
Hard Avg Dense Stiff Soft Poor DNK
Rock Rock Soil Soil Soil Soil If DNK, assume Type D.

Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK


Adjacency: Pounding Falling Hazards from Taller Adjacent Building

Irregularities: Vertical (type/severity) _____
 Plan (type) _____

Exterior Falling Hazards: Unbraced Chimneys Heavy Cladding or Heavy Veneer
 Parapets Appendages
 Other: _____

COMMENTS:
- Interior contents are tables w/computers
- Hard ceilings
- Contact indicated there was supplemental anchorage – likely wind straps

Additional sketches or comments on separate page



SKETCH

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE, S_{L1}

FEMA BUILDING TYPE	Do Not Know	W1	W1A	W2	S1 (MRF)	S2 (BR)	S3 (LM)	S4 (RC SW)	S5 (URM INF)	C1 (MRF)	C2 (SW)	C3 (URM INF)	PC1 (TU)	PC2	RM1 (FD)	RM2 (RD)	URM	MH
Basic Score		2.1	1.9	1.8	1.5	1.4	1.6	1.4	1.2	1.0	1.2	0.9	1.1	1.0	1.1	1.1	0.9	1.1
Severe Vertical Irregularity, V _{L1}		-0.9	-0.9	-0.9	-0.8	-0.7	-0.8	-0.7	-0.7	-0.7	-0.8	-0.6	-0.7	-0.7	-0.7	-0.7	-0.6	NA
Moderate Vertical Irregularity, V _{L1}		-0.6	-0.5	-0.5	-0.4	-0.4	-0.5	-0.4	-0.3	-0.4	-0.4	-0.3	-0.4	-0.4	-0.4	-0.4	-0.3	NA
Plan Irregularity, P _{L1}		-0.7	-0.7	-0.6	-0.5	-0.5	-0.6	-0.4	-0.4	-0.4	-0.5	-0.3	-0.5	-0.4	-0.4	-0.4	-0.3	NA
Pre-Code		-0.3	-0.3	-0.3	-0.3	-0.2	-0.3	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	0.0
Post-Benchmark		1.9	1.9	2.0	1.0	1.1	1.1	1.5	NA	1.4	1.7	NA	1.5	1.7	1.6	1.6	NA	0.5
Soil Type A or B		0.5	0.5	0.4	0.3	0.3	0.4	0.3	0.2	0.2	0.3	0.1	0.3	0.2	0.3	0.3	0.1	0.1
Soil Type E (1-3 stories)		0.0	-0.2	-0.4	-0.3	-0.2	-0.2	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	-0.1
Soil Type E (> 3 stories)		-0.4	-0.4	-0.4	-0.3	-0.3	NA	-0.3	-0.1	-0.1	-0.3	-0.1	NA	-0.1	-0.2	-0.2	0.0	NA
Minimum Score, S _{MIN}		0.7	0.7	0.7	0.5	0.5	0.5	0.5	0.5	0.3	0.3	0.3	0.2	0.2	0.3	0.3	0.2	1.0

FINAL LEVEL 1 SCORE, S_{L1} ≥ S_{MIN}: **1.1**

EXTENT OF REVIEW
Exterior: Partial All Sides Aerial
Interior: None Visible Entered
Drawings Reviewed: Yes No
Soil Type Source: Vs30
Geologic Hazards Source: Regional Data
Contact Person: Mike Brown

LEVEL 2 SCREENING PERFORMED?
 Yes, Final Level 2 Score, S_{L2} 1.1 No
Nonstructural hazards? Yes No

OTHER HAZARDS
Are There Hazards That Trigger A Detailed Structural Evaluation?
 Pounding potential (unless S_{L2} > cut-off, if known)
 Falling hazards from taller adjacent building
 Geologic hazards or Soil Type F
 Significant damage/deterioration to the structural system

ACTION REQUIRED
Detailed Structural Evaluation Required?
 Yes, unknown FEMA building type or other building
 Yes, score less than cut-off
 Yes, other hazards present
 No
Detailed Nonstructural Evaluation Recommended? (check one)
 Yes, nonstructural hazards identified that should be evaluated
 No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary
 No, no nonstructural hazards identified DNK

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Legend: MRF = Moment-resisting frame RC = Reinforced concrete URM INF = Unreinforced masonry infill MH = Manufactured Housing FD = Flexible diaphragm
BR = Braced frame SW = Shear wall TU = Tilt up LM = Light metal RD = Rigid diaphragm

Rapid Visual Screening of Buildings for Potential Seismic Hazards

FEMA P-154 Data Collection Form

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

Level 2 (Optional)
VERY HIGH Seismicity

Bldg Name: Alternative Center – Add't Bldg/Trailer	Final Level 1 Score: $S_{L1} = 1.1$	<i>(do not consider S_{MIN})</i>	
Screener: CS, JE, DK	Level 1 Irregularity Modifiers:	Vertical Irregularity, $V_{L1} = 0$	Plan Irregularity, $P_{L1} = 0$
Date/Time: 9-11-2015/	ADJUSTED BASELINE SCORE:	$S' = (S_{L1} - V_{L1} - P_{L1}) = 1.1$	

STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

Topic	Statement (If statement is true, circle the "Yes" modifier, otherwise cross out the modifier.)	Yes	Subtotals
Vertical Irregularity, V_{L2}	Sloping Site	W1 building: There is at least a full story grade change from one side of the building to the other.	-0.9
		Non-W1 building: There is at least a full story grade change from one side of the building to the other.	-0.2
	Weak and/or Soft Story (circle one maximum)	W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.	-0.5
		W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum).	-0.9
		W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.	-0.9
		Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.	-0.7
		Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.	-0.4
	Setback	Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.	-0.7
		Vertical elements of the lateral system at upper stories are inboard of those at lower stories.	-0.4
		There is an in-plane offset of the lateral elements that is greater than the length of the elements.	-0.2
	Short Column/ Pier	C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.	-0.4
		C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.	-0.4
Split Level	There is a split level at one of the floor levels or at the roof.	-0.4	
Other Irregularity	There is another observable severe vertical irregularity that obviously affects the building's seismic performance.	-0.7	
	There is another observable moderate vertical irregularity that may affect the building's seismic performance.	-0.4	
Plan Irregularity, P_{L2}	Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.)	-0.5	
	Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.	-0.2	
	Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.	-0.2	
	Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.	-0.2	
	C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.	-0.2	
	Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.	-0.5	
Redundancy	The building has at least two bays of lateral elements on each side of the building in each direction.	+0.2	
Pounding	Building is separated from an adjacent structure by less than 1.5% of the height of the shorter of the building and adjacent structure and:	The floors do not align vertically within 2 feet.	-0.7
		One building is 2 or more stories taller than the other.	-0.7
		The building is at the end of the block.	-0.4
S2 Building	"K" bracing geometry is visible.	-0.7	
C1 Building	Flat plate serves as the beam in the moment frame.	-0.3	
PC1/RM1 Bldg	There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)	+0.2	
PC1/RM1 Bldg	The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).	+0.2	
URM	Gable walls are present.	-0.3	
MH	There is a supplemental seismic bracing system provided between the carriage and the ground.	+0.5	
Retrofit	Comprehensive seismic retrofit is visible or known from drawings.	+1.2	
FINAL LEVEL 2 SCORE, $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$:			1.1
			<i>(Transfer to Level 1 form)</i>

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance: Yes No
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

OBSERVABLE NONSTRUCTURAL HAZARDS

Location	Statement (Check "Yes" or "No")	Yes	No	Comment
Exterior	There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.		X	
	There is heavy cladding or heavy veneer.		X	
	There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported.		X	
	There is an unreinforced masonry appendage over exit doors or pedestrian walkways.		X	
	There is a sign posted on the building that indicates hazardous materials are present.		X	
	There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney.		X	
	Other observed exterior nonstructural falling hazard:		X	
Interior	There are hollow clay tile or brick partitions at any stair or exit corridor.		X	
	Other observed interior nonstructural falling hazard:		X	

Estimated Nonstructural Seismic Performance (Check appropriate box and transfer to Level 1 form conclusions)
 Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended
 Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required
 Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

Comments:



Address: 100 Twitty Drive
Sikeston, MO Zip: 63801

Other Identifiers: Sikeston R-6 District

Building Name: 5th & 6th Grade Center

Use: K-12 School

Latitude: 36.875001 Longitude: -89.569236

Ss: 2.468g Sr: 0.919g

Screener(s): CS, JE, DK Date/Time: 9-11-15/

No. Stories: Above Grade: 1 Below Grade: 0 Year Built: 1973 EST

Total Floor Area (sq. ft.): 61,268 Code Year: Unknown

Additions: None Yes, Year(s) Built: DNK

Occupancy: Assembly Commercial Emer. Services Historic Shelter
Industrial Office School Government
Utility Warehouse Residential, # Units: _____

Soil Type: A B C D E F DNK
Hard Avg Dense Stiff Soft Poor DNK
Rock Rock Soil Soil Soil Soil *If DNK, assume Type D.*

Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt: Yes/No/DNK

Adjacency: Pounding Falling Hazards from Taller Adjacent Building

Irregularities: Vertical (type/severity) Split level @ gym
 Plan (type)

Exterior Falling Hazards: Unbraced Chimneys Heavy Cladding or Heavy Veneer
 Parapets Appendages
 Other: Brick Veneer

610.021(20)

COMMENTS:
- Strip lights anchored to ceiling grid in egress
- Natural gas water heater & roof top equipment unanchored

Additional sketches or comments on separate page

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE, S_{L1}

FEMA BUILDING TYPE	Do Not Know	W1	W1A	W2	S1 (MRF)	S2 (BR)	S3 (LM)	S4 (RC SW)	S5 (URM INF)	C1 (MRF)	C2 (SW)	C3 (URM INF)	PC1 (TU)	PC2	RM1 (FD)	RM2 (RD)	URM	MH
Basic Score		2.1	1.9	1.8	1.5	1.4	1.6	1.4	1.2	1.0	1.2	0.9	1.1	1.0	1.1	1.1	0.9	1.1
Severe Vertical Irregularity, V_{L1}		-0.9	-0.9	-0.9	-0.8	-0.7	-0.8	-0.7	-0.7	-0.7	-0.8	-0.6	-0.7	-0.7	-0.7	-0.7	-0.6	NA
Moderate Vertical Irregularity, V_{L1}		-0.6	-0.5	-0.5	-0.4	-0.4	-0.5	-0.4	-0.3	-0.4	-0.4	-0.3	-0.4	-0.4	-0.4	-0.4	-0.3	NA
Plan Irregularity, P_{L1}		-0.7	-0.7	-0.6	-0.5	-0.5	-0.6	-0.4	-0.4	-0.4	-0.5	-0.3	-0.5	-0.4	-0.4	-0.4	-0.3	NA
Pre-Code		-0.3	-0.3	-0.3	-0.3	-0.2	-0.3	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	0.0
Post-Benchmark		1.9	1.9	2.0	1.0	1.1	1.1	1.5	NA	1.4	1.7	NA	1.5	1.7	1.6	1.6	NA	0.5
Soil Type A or B		0.5	0.5	0.4	0.3	0.3	0.4	0.3	0.2	0.2	0.3	0.1	0.3	0.2	0.3	0.3	0.1	0.1
Soil Type E (1-3 stories)		0.0	-0.2	-0.4	-0.3	-0.2	-0.2	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	-0.1
Soil Type E (> 3 stories)		-0.4	-0.4	-0.4	-0.3	-0.3	NA	-0.3	-0.1	-0.1	-0.3	-0.1	NA	-0.1	-0.2	-0.2	0.0	NA
Minimum Score, S_{Min}		0.7	0.7	0.7	0.5	0.5	0.5	0.5	0.5	0.3	0.3	0.3	0.2	0.2	0.3	0.3	0.2	1.0

FINAL LEVEL 1 SCORE, $S_{L1} \geq S_{MIN}$: 0.8 0.6

<p>EXTENT OF REVIEW</p> <p>Exterior: <input type="checkbox"/> Partial <input checked="" type="checkbox"/> All Sides <input type="checkbox"/> Aerial Interior: <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered Drawings Reviewed: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Soil Type Source: Vs30 Geologic Hazards Source: Regional Data Contact Person: Mike Brown</p> <p>LEVEL 2 SCREENING PERFORMED?</p> <p><input checked="" type="checkbox"/> Yes, Final Level 2 Score, S_{L2} 0.2 <input type="checkbox"/> No Nonstructural hazards? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p>	<p>OTHER HAZARDS</p> <p>Are There Hazards That Trigger A Detailed Structural Evaluation?</p> <p><input checked="" type="checkbox"/> Pounding potential (unless $S_{L2} >$ cut-off, if known) <input type="checkbox"/> Falling hazards from taller adjacent building <input type="checkbox"/> Geologic hazards or Soil Type F <input type="checkbox"/> Significant damage/deterioration to the structural system</p>	<p>ACTION REQUIRED</p> <p>Detailed Structural Evaluation Required?</p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building <input checked="" type="checkbox"/> Yes, score less than cut-off <input type="checkbox"/> Yes, other hazards present <input type="checkbox"/> No</p> <p>Detailed Nonstructural Evaluation Recommended? (check one)</p> <p><input checked="" type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated <input type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary <input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p>
--	--	---

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Rapid Visual Screening of Buildings for Potential Seismic Hazards

FEMA P-154 Data Collection Form

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

Level 2 (Optional)
VERY HIGH Seismicity

Bldg Name: 5 th & 6 th Grade Center	Final Level 1 Score: $S_{L1} = 0.6$	<i>(do not consider S_{MIN})</i>	
Screener: CS, JE, DK	Level 1 Irregularity Modifiers:	Vertical Irregularity, $V_{L1} = -0.3$	Plan Irregularity, $P_{L1} = 0$
Date/Time: 9-11-15/	ADJUSTED BASELINE SCORE:	$S' = (S_{L1} - V_{L1} - P_{L1}) = 0.9$	

STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

Topic	Statement (If statement is true, circle the "Yes" modifier; otherwise cross out the modifier.)	Yes	Subtotals
Vertical Irregularity, V_{L2}	Sloping Site	W1 building: There is at least a full story grade change from one side of the building to the other.	-0.9
		Non-W1 building: There is at least a full story grade change from one side of the building to the other.	-0.2
	Weak and/or Soft Story (circle one maximum)	W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.	-0.5
		W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum).	-0.9
		W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.	-0.9
		Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.	-0.7
		Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.	-0.4
	Setback	Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.	-0.7
		Vertical elements of the lateral system at upper stories are inboard of those at lower stories.	-0.4
		There is an in-plane offset of the lateral elements that is greater than the length of the elements.	-0.2
	Short Column/ Pier	C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.	-0.4
		C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.	-0.4
Split Level	There is a split level at one of the floor levels or at the roof.	-0.4	
Other Irregularity	There is another observable severe vertical irregularity that obviously affects the building's seismic performance.	-0.7	
	There is another observable moderate vertical irregularity that may affect the building's seismic performance.	-0.4	
Plan Irregularity, P_{L2}	Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.)	-0.5	
	Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.	-0.2	
	Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.	-0.2	
	Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.	-0.2	
	C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.	-0.2	
	Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.	-0.5	
Redundancy	The building has at least two bays of lateral elements on each side of the building in each direction.	+0.2	
Pounding	Building is separated from an adjacent structure by less than 1.5% of the height of the shorter of the building and adjacent structure and:	The floors do not align vertically within 2 feet.	-0.7
		One building is 2 or more stories taller than the other.	-0.7
		The building is at the end of the block.	-0.4
S2 Building	"K" bracing geometry is visible.	-0.7	
C1 Building	Flat plate serves as the beam in the moment frame.	-0.3	
PC1/RM1 Bldg	There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)	+0.2	
PC1/RM1 Bldg	The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).	+0.2	
URM	Gable walls are present.	-0.3	
MH	There is a supplemental seismic bracing system provided between the carriage and the ground.	+0.5	
Retrofit	Comprehensive seismic retrofit is visible or known from drawings.	+1.2	
FINAL LEVEL 2 SCORE, $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$:			0.2
			<i>(Transfer to Level 1 form)</i>

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance: Yes No
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

OBSERVABLE NONSTRUCTURAL HAZARDS

Location	Statement (Check "Yes" or "No")	Yes	No	Comment
Exterior	There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.		X	
	There is heavy cladding or heavy veneer.	X		Brick Veneer
	There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported.		X	
	There is an unreinforced masonry appendage over exit doors or pedestrian walkways.		X	
	There is a sign posted on the building that indicates hazardous materials are present.		X	
	There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney.		X	
	Other observed exterior nonstructural falling hazard:		X	
Interior	There are hollow clay tile or brick partitions at any stair or exit corridor.		X	
	Other observed interior nonstructural falling hazard:	X		

Estimated Nonstructural Seismic Performance (Check appropriate box and transfer to Level 1 form conclusions)
 Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended
 Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required
 Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

Comments:



Address: 510 Lindenwood Ave.
Sikeston, MO Zip: 63801

Other Identifiers: Sikeston R-6 District

Building Name: 7th & 8th Grade Center

Use: K-12 School

Latitude: 36.892651 Longitude: -89.605366

Ss: 2.316g Sr: 0.847g

Screener(s): Varnell/Mills Date/Time: 9-11-15/ 10:00 am

No. Stories: Above Grade: 1 Below Grade: 0 Year Built: 1985 EST

Total Floor Area (sq. ft.): 84,020 Code Year: Unknown

Additions: None Yes, Year(s) Built: _____

Occupancy: Assembly Commercial Emer. Services Historic Shelter
Industrial Office School Government
Utility Warehouse Residential, # Units: _____

Soil Type: A B C D E F DNK
Hard Avg Dense Stiff Soft Poor DNK
Rock Rock Soil Soil Soil Soil *If DNK, assume Type D.*

Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

Adjacency: NONE Pounding Falling Hazards from Taller Adjacent Building

Irregularities: Vertical (type/severity) _____
 Plan (type) Re-entrant Corners

Exterior Falling Hazards: Unbraced Chimneys Heavy Cladding or Heavy Veneer
 Parapets Appendages
 Other: _____

610.021(20)

COMMENTS:

- Canopy at front entrance is an exterior falling hazard (appendage)
- Crack located in Mechanical room at N.W. corner
- Unsecured book case
- Unsecured hot water tank

Additional sketches or comments on separate page

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE, S_{L1}

FEMA BUILDING TYPE	Do Not Know	W1	W1A	W2	S1 (MRF)	S2 (BR)	S3 (LM)	S4 (RC SW)	S5 (URM INF)	C1 (MRF)	C2 (SW)	C3 (URM INF)	PC1 (TU)	PC2	RM1 (FD)	RM2 (RD)	URM	MH
Basic Score		2.1	1.9	1.8	1.5	1.4	1.6	1.4	1.2	1.0	1.2	0.9	1.1	1.0	1.1	1.1	0.9	1.1
Severe Vertical Irregularity, V _{L1}		-0.9	-0.9	-0.9	-0.8	-0.7	-0.8	-0.7	-0.7	-0.7	-0.8	-0.6	-0.7	-0.7	-0.7	-0.7	-0.6	NA
Moderate Vertical Irregularity, V _{L1}		-0.6	-0.5	-0.5	-0.4	-0.4	-0.5	-0.4	-0.3	-0.4	-0.4	-0.3	-0.4	-0.4	-0.4	-0.4	-0.3	NA
Plan Irregularity, P _{L1}		-0.7	-0.7	-0.6	-0.5	-0.5	-0.6	-0.4	-0.4	-0.4	-0.5	-0.3	-0.5	-0.4	-0.4	-0.4	-0.3	NA
Pre-Code		-0.3	-0.3	-0.3	-0.3	-0.2	-0.3	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	0.0
Post-Benchmark		1.9	1.9	2.0	1.0	1.1	1.1	1.5	NA	1.4	1.7	NA	1.5	1.7	1.6	1.6	NA	0.5
Soil Type A or B		0.5	0.5	0.4	0.3	0.3	0.4	0.3	0.2	0.2	0.3	0.1	0.3	0.2	0.3	0.3	0.1	0.1
Soil Type E (1-3 stories)		0.0	-0.2	-0.4	-0.3	-0.2	-0.2	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	-0.1
Soil Type E (> 3 stories)		-0.4	-0.4	-0.4	-0.3	-0.3	NA	-0.3	-0.1	-0.1	-0.3	-0.1	NA	-0.1	-0.2	-0.2	0.0	NA
Minimum Score, S _{MIN}		0.7	0.7	0.7	0.5	0.5	0.5	0.5	0.5	0.3	0.3	0.3	0.2	0.2	0.3	0.3	0.2	1.0

FINAL LEVEL 1 SCORE, S_{L1} ≥ S_{MIN}:

0.7

<p>EXTENT OF REVIEW</p> <p>Exterior: <input type="checkbox"/> Partial <input type="checkbox"/> All Sides <input checked="" type="checkbox"/> Aerial Interior: <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered Drawings Reviewed: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Soil Type Source: Vs30 Geologic Hazards Source: Regional Data Contact Person: Mike Brown</p> <p>LEVEL 2 SCREENING PERFORMED?</p> <p><input checked="" type="checkbox"/> Yes, Final Level 2 Score, S_{L2} 1.1 <input type="checkbox"/> No Nonstructural hazards? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p>	<p>OTHER HAZARDS</p> <p>Are There Hazards That Trigger A Detailed Structural Evaluation?</p> <p><input type="checkbox"/> Pounding potential (unless S_{L2} > cut-off, if known) <input type="checkbox"/> Falling hazards from taller adjacent building <input type="checkbox"/> Geologic hazards or Soil Type F <input type="checkbox"/> Significant damage/deterioration to the structural system</p>	<p>ACTION REQUIRED</p> <p>Detailed Structural Evaluation Required?</p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building <input checked="" type="checkbox"/> Yes, score less than cut-off <input type="checkbox"/> Yes, other hazards present <input type="checkbox"/> No</p> <p>Detailed Nonstructural Evaluation Recommended? (check one)</p> <p><input checked="" type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated <input type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary <input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p>
---	--	---

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Rapid Visual Screening of Buildings for Potential Seismic Hazards

FEMA P-154 Data Collection Form

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

Level 2 (Optional)
VERY HIGH Seismicity

Bldg Name: 7 th & 8 th Grade Center	Final Level 1 Score: $S_{L1} = 0.7$	<i>(do not consider S_{MIN})</i>	
Screener: Varnell/Mills/Griffin	Level 1 Irregularity Modifiers:	Vertical Irregularity, $V_{L1} = 0$	Plan Irregularity, $P_{L1} = -0.4$
Date/Time: 9-11-15/ 10:00 am	ADJUSTED BASELINE SCORE:	$S' = (S_{L1} - V_{L1} - P_{L1}) = 1.1$	

STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

Topic	Statement (If statement is true, circle the "Yes" modifier, otherwise cross out the modifier.)	Yes	Subtotals
Vertical Irregularity, V_{L2}	Sloping Site	W1 building: There is at least a full story grade change from one side of the building to the other.	-0.9
		Non-W1 building: There is at least a full story grade change from one side of the building to the other.	-0.2
	Weak and/or Soft Story (circle one maximum)	W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.	-0.5
		W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum).	-0.9
		W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.	-0.9
		Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.	-0.7
		Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.	-0.4
	Setback	Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.	-0.7
		Vertical elements of the lateral system at upper stories are inboard of those at lower stories.	-0.4
		There is an in-plane offset of the lateral elements that is greater than the length of the elements.	-0.2
	Short Column/ Pier	C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.	-0.4
		C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.	-0.4
Split Level	There is a split level at one of the floor levels or at the roof.	-0.4	
Other Irregularity	There is another observable severe vertical irregularity that obviously affects the building's seismic performance.	-0.7	
	There is another observable moderate vertical irregularity that may affect the building's seismic performance.	-0.4	
Plan Irregularity, P_{L2}	Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.)	-0.5	
	Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.	-0.2	
	Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.	-0.2	
	Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.	-0.2	
	C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.	-0.2	
	Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.	-0.5	
Redundancy	The building has at least two bays of lateral elements on each side of the building in each direction.	+0.2	
Pounding	Building is separated from an adjacent structure by less than 1.5% of the height of the shorter of the building and adjacent structure and:	The floors do not align vertically within 2 feet.	-0.7
		One building is 2 or more stories taller than the other.	-0.7
		The building is at the end of the block.	-0.4
S2 Building	"K" bracing geometry is visible.	-0.7	
C1 Building	Flat plate serves as the beam in the moment frame.	-0.3	
PC1/RM1 Bldg	There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)	+0.2	
PC1/RM1 Bldg	The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).	+0.2	
URM	Gable walls are present.	-0.3	
MH	There is a supplemental seismic bracing system provided between the carriage and the ground.	+0.5	
Retrofit	Comprehensive seismic retrofit is visible or known from drawings.	+1.2	
FINAL LEVEL 2 SCORE, $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$:			1.1
			<i>(Transfer to Level 1 form)</i>

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance: Yes No
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

OBSERVABLE NONSTRUCTURAL HAZARDS

Location	Statement (Check "Yes" or "No")	Yes	No	Comment
Exterior	There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.		X	
	There is heavy cladding or heavy veneer.		X	
	There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported.		X	
	There is an unreinforced masonry appendage over exit doors or pedestrian walkways.	X		Brick walls @ entrance
	There is a sign posted on the building that indicates hazardous materials are present.		X	
	There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney.		X	
	Other observed exterior nonstructural falling hazard:		X	
Interior	There are hollow clay tile or brick partitions at any stair or exit corridor.	X		CMU partitions
	Other observed interior nonstructural falling hazard:	X		Contents

Estimated Nonstructural Seismic Performance (Check appropriate box and transfer to Level 1 form conclusions)
 Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended
 Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required
 Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

Comments: Lights sampled safe-tied. CMU partition walls not restrained OOP. Book cases, storage cabinets and electric water heater unrestrained.



Address: 200 Pine Street
Sikeston, MO Zip: 63801

Other Identifiers: Sikeston R-6 District

Building Name: Sikeston Senior High School - Building A

Use: K-12 School

Latitude: 36.879228 Longitude: -89.572154

Ss: 2.445g Sr: 0.908g

Screeener(s): M. Griffin/B. Smith Date/Time: 9-11-15/

No. Stories: Above Grade: 1 Below Grade: 0 Year Built: 1960 EST

Total Floor Area (sq. ft.): 24,328 Code Year: Unknown

Additions: None Yes, Year(s) Built: Various small additions

Occupancy: Assembly Commercial Emer. Services Historic Shelter
Industrial Office School Government
Utility Warehouse Residential, # Units: _____

Soil Type: A B C D E F DNK
Hard Avg Dense Stiff Soft Poor
Rock Rock Soil Soil Soil Soil
If DNK, assume Type D.

Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

Adjacency: Pounding Falling Hazards from Taller Adjacent Building NONE

Irregularities: Vertical (type/severity) _____
 Plan (type) Re-entrant corner

Exterior Falling Hazards: Unbraced Chimneys Heavy Cladding or Heavy Veneer
 Parapets Appendages
 Other: _____

610.021(20)

COMMENTS:

- Multiple additions & fill-ins over the years:
- Café is RC w/URM in-fill
- Seating area below café is constructed of STL knee-braced frames
- Remainder is STL bar joists w/Bulb-T roof diaphragm and CMU Brg walls
- Classrooms have hard ceilings
- Lights safety'd; drop ceilings braced
- Egress corridors nice & clear
- Kitchen equipment UA with gas piping unbraced
- 3" dia. gas header unbraced

Additional sketches or comments on separate page

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE, S_{L1} Cafe

FEMA BUILDING TYPE	Do Not Know	W1	W1A	W2	S1 (MRF)	S2 (BR)	S3 (LM)	S4 (RC SW)	S5 (URM INF)	C1 (MRF)	C2 (SW)	C3 (URM INF)	PC1 (TU)	PC2	RM1 (FD)	RM2 (RD)	URM	MH
Basic Score		2.1	1.9	1.8	1.5	1.4	1.6	1.4	1.2	1.0	1.2	0.9	1.1	1.0	1.1	1.1	0.9	1.1
Severe Vertical Irregularity, V _{L1}		-0.9	-0.9	-0.9	-0.8	-0.7	-0.8	-0.7	-0.7	-0.7	-0.8	-0.6	-0.7	-0.7	-0.7	-0.7	-0.6	NA
Moderate Vertical Irregularity, V _{L1}		-0.6	-0.5	-0.5	-0.4	-0.4	-0.5	-0.4	-0.3	-0.4	-0.4	-0.3	-0.4	-0.4	-0.4	-0.4	-0.3	NA
Plan Irregularity, P _{L1}		-0.7	-0.7	-0.6	-0.5	-0.5	-0.6	-0.4	-0.4	-0.4	-0.5	-0.3	-0.5	-0.4	-0.4	-0.4	-0.3	NA
Pre-Code		-0.3	-0.3	-0.3	-0.3	-0.2	-0.3	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	0.0
Post-Benchmark		1.9	1.9	2.0	1.0	1.1	1.1	1.5	NA	1.4	1.7	NA	1.5	1.7	1.6	1.6	NA	0.5
Soil Type A or B		0.5	0.5	0.4	0.3	0.3	0.4	0.3	0.2	0.2	0.3	0.1	0.3	0.2	0.3	0.3	0.1	0.1
Soil Type E (1-3 stories)		0.0	-0.2	-0.4	-0.3	-0.2	-0.2	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	-0.1
Soil Type E (> 3 stories)		-0.4	-0.4	-0.4	-0.3	-0.3	NA	-0.3	-0.1	-0.1	-0.3	-0.1	NA	-0.1	-0.2	-0.2	0.0	NA
Minimum Score, S _{MIN}		0.7	0.7	0.7	0.5	0.5	0.5	0.5	0.5	0.3	0.3	0.3	0.2	0.2	0.3	0.3	0.2	1.0

FINAL LEVEL 1 SCORE, S_{L1} ≥ S_{MIN}: 0.7 0.9 0.6

<p>EXTENT OF REVIEW</p> <p>Exterior: <input type="checkbox"/> Partial <input checked="" type="checkbox"/> All Sides <input type="checkbox"/> Aerial <input type="checkbox"/> None <input checked="" type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered</p> <p>Drawings Reviewed: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p> <p>Soil Type Source: Vs30</p> <p>Geologic Hazards Source: Regional Data</p> <p>Contact Person: Mie Brown</p> <p>LEVEL 2 SCREENING PERFORMED?</p> <p><input checked="" type="checkbox"/> Yes, Final Level 2 Score, S_{L2} 0.2 (min) <input type="checkbox"/> No</p> <p>Nonstructural hazards? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p>	<p>OTHER HAZARDS</p> <p>Are There Hazards That Trigger A Detailed Structural Evaluation?</p> <p><input checked="" type="checkbox"/> Pounding potential (unless S_{L2} > cut-off, if known)</p> <p><input type="checkbox"/> Falling hazards from taller adjacent building</p> <p><input type="checkbox"/> Geologic hazards or Soil Type F</p> <p><input type="checkbox"/> Significant damage/deterioration to the structural system</p>	<p>ACTION REQUIRED</p> <p>Detailed Structural Evaluation Required?</p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building</p> <p><input checked="" type="checkbox"/> Yes, score less than cut-off</p> <p><input checked="" type="checkbox"/> Yes, other hazards present</p> <p><input type="checkbox"/> No</p> <p>Detailed Nonstructural Evaluation Recommended? (check one)</p> <p><input checked="" type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated</p> <p><input type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary</p> <p><input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p>
---	--	---

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Rapid Visual Screening of Buildings for Potential Seismic Hazards

FEMA P-154 Data Collection Form

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

Level 2 (Optional)
VERY HIGH Seismicity

Bldg Name: Sikeston High School – Building A	Final Level 1 Score: $S_{L1} = 0.6$ (URM)	<i>(do not consider S_{MIN})</i>	
Screener: M. Griffin/B. Smith	Level 1 Irregularity Modifiers: Vertical Irregularity, $V_{L1} = 0$	Plan Irregularity, $P_{L1} = -0.3$	
Date/Time: 9-11-15/	ADJUSTED BASELINE SCORE: $S' = (S_{L1} - V_{L1} - P_{L1}) = 0.9$		

STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

Topic	Statement (If statement is true, circle the "Yes" modifier; otherwise cross out the modifier.)	Yes	Subtotals
Vertical Irregularity, V_{L2}	Sloping Site	W1 building: There is at least a full story grade change from one side of the building to the other.	-0.9
		Non-W1 building: There is at least a full story grade change from one side of the building to the other.	-0.2
	Weak and/or Soft Story (circle one maximum)	W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.	-0.5
		W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum).	-0.9
		W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.	-0.9
		Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.	-0.7
		Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.	-0.4
	Setback	Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.	-0.7
		Vertical elements of the lateral system at upper stories are inboard of those at lower stories.	-0.4
		There is an in-plane offset of the lateral elements that is greater than the length of the elements.	-0.2
	Short Column/ Pier	C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.	-0.4
		C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.	-0.4
	Split Level	There is a split level at one of the floor levels or at the roof.	-0.4
	Other Irregularity	There is another observable severe vertical irregularity that obviously affects the building's seismic performance.	-0.7
There is another observable moderate vertical irregularity that may affect the building's seismic performance.		-0.4	
Plan Irregularity, P_{L2}	Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.)	-0.5	
	Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.	-0.2	
	Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.	-0.2	
	Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.	-0.2	
	C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.	-0.2	
	Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.	-0.5	
Redundancy	The building has at least two bays of lateral elements on each side of the building in each direction.	+0.2	
Pounding	Building is separated from an adjacent structure by less than 1.5% of the height of the shorter of the building and adjacent structure and:	The floors do not align vertically within 2 feet.	-0.7
		One building is 2 or more stories taller than the other.	-0.7
		The building is at the end of the block.	-0.4
S2 Building	"K" bracing geometry is visible.	-0.7	
C1 Building	Flat plate serves as the beam in the moment frame.	-0.3	
PC1/RM1 Bldg	There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)	+0.2	
PC1/RM1 Bldg	The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).	+0.2	
URM	Gable walls are present.	-0.3	
MH	There is a supplemental seismic bracing system provided between the carriage and the ground.	+0.5	
Retrofit	Comprehensive seismic retrofit is visible or known from drawings.	+1.2	
FINAL LEVEL 2 SCORE, $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$:			0.0
			<i>(Transfer to Level 1 form)</i>

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance: Yes No
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

OBSERVABLE NONSTRUCTURAL HAZARDS

Location	Statement (Check "Yes" or "No")	Yes	No	Comment
Exterior	There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.		X	
	There is heavy cladding or heavy veneer.	X		Exterior & Interior
	There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported.		X	
	There is an unreinforced masonry appendage over exit doors or pedestrian walkways.		X	
	There is a sign posted on the building that indicates hazardous materials are present.		X	
	There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney.		X	Limited OK
	Other observed exterior nonstructural falling hazard:			
Interior	There are hollow clay tile or brick partitions at any stair or exit corridor.	X		URM partition walls
	Other observed interior nonstructural falling hazard:			

Estimated Nonstructural Seismic Performance (Check appropriate box and transfer to Level 1 form conclusions)
 Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended
 Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required
 Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

Comments: Gas header unbraced. Gas kitchen equipment unrestrained.



Address: 200 Pine Street
Sikeston, MO Zip: 63801

Other Identifiers: Sikeston R-6 District

Building Name: Sikeston Senior High School - Building B

Use: K-12 School

Latitude: 36.879228 Longitude: -89.572154

Ss: 2.445g Sr: 0.908g

Screener(s): M. Griffin/B. Smith Date/Time: 9-11-15/

No. Stories: Above Grade: 1 Below Grade: 0 Year Built: 1960 EST

Total Floor Area (sq. ft.): 19,399 Code Year: Unknown

Additions: None Yes, Year(s) Built: Interior Renovations

Occupancy: Assembly Commercial Emer. Services Historic Shelter
Industrial Office School Government
Utility Warehouse Residential, # Units: _____

Soil Type: A B C D E F DNK
Hard Avg Dense Stiff Soft Poor If DNK, assume Type D.
Rock Rock Soil Soil Soil Soil

Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

Adjacency: Pounding Falling Hazards from Taller Adjacent Building

Irregularities: Vertical (type/severity) _____
 Plan (type) Re-entrant corners

Exterior Falling Hazards: Unbraced Chimneys Heavy Cladding or Heavy Veneer
 Parapets Appendages
 Other: _____

610.021(20)

COMMENTS:

- Welding shop is steel gravity w/CMU Brg wall, URM bar joist w/Bulb-T light wt concrete roof diaphragm
- Classroom areas are STL bar joists to Brg CMU walls. Roof diaphragm is lite weight concrete w/Blub-T's.
- Lights safety'd
- Maintenance room has gas boilers, UA.
- Gas pipe unbraced
- Interior partitions not braced
- Some tall storage cabinets in classrooms unrestrained

Additional sketches or comments on separate page

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE, S_{L1}

FEMA BUILDING TYPE	Do Not Know	W1	W1A	W2	S1 (MRF)	S2 (BR)	S3 (LM)	S4 (RC SW)	S5 (URM INF)	C1 (MRF)	C2 (SW)	C3 (URM INF)	PC1 (TU)	PC2	RM1 (FD)	RM2 (RD)	URM	MH
Basic Score		2.1	1.9	1.8	1.5	1.4	1.6	1.4	1.2	1.0	1.2	0.9	1.1	1.0	1.1	1.1	0.9	1.1
Severe Vertical Irregularity, V _{L1}		-0.9	-0.9	-0.9	-0.8	-0.7	-0.8	-0.7	-0.7	-0.7	-0.8	-0.6	-0.7	-0.7	-0.7	-0.7	-0.6	NA
Moderate Vertical Irregularity, V _{L1}		-0.6	-0.5	-0.5	-0.4	-0.4	-0.5	-0.4	-0.3	-0.4	-0.4	-0.3	-0.4	-0.4	-0.4	-0.4	-0.3	NA
Plan Irregularity, P _{L1}		-0.7	-0.7	-0.6	-0.5	-0.5	-0.6	-0.4	-0.4	-0.4	-0.5	-0.3	-0.5	-0.4	-0.4	-0.4	-0.3	NA
Pre-Code		-0.3	-0.3	-0.3	-0.3	-0.2	-0.3	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	0.0
Post-Benchmark		1.9	1.9	2.0	1.0	1.1	1.1	1.5	NA	1.4	1.7	NA	1.5	1.7	1.6	1.6	NA	0.5
Soil Type A or B		0.5	0.5	0.4	0.3	0.3	0.4	0.3	0.2	0.2	0.3	0.1	0.3	0.2	0.3	0.3	0.1	0.1
Soil Type E (1-3 stories)		0.0	-0.2	-0.4	-0.3	-0.2	-0.2	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	-0.1
Soil Type E (> 3 stories)		-0.4	-0.4	-0.4	-0.3	-0.3	NA	-0.3	-0.1	-0.1	-0.3	-0.1	NA	-0.1	-0.2	-0.2	0.0	NA
Minimum Score, S _{MIN}		0.7	0.7	0.7	0.5	0.5	0.5	0.5	0.5	0.3	0.3	0.3	0.2	0.2	0.3	0.3	0.2	1.0

FINAL LEVEL 1 SCORE, S_{L1} ≥ S_{MIN}: 0.6

<p>EXTENT OF REVIEW</p> <p>Exterior: <input type="checkbox"/> Partial <input checked="" type="checkbox"/> All Sides <input type="checkbox"/> Aerial Interior: <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered</p> <p>Drawings Reviewed: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p> <p>Soil Type Source: Vs30</p> <p>Geologic Hazards Source: Regional Data</p> <p>Contact Person: Mike Brown</p>	<p>OTHER HAZARDS</p> <p>Are There Hazards That Trigger A Detailed Structural Evaluation?</p> <p><input type="checkbox"/> Pounding potential (unless S_{L2} > cut-off, if known)</p> <p><input type="checkbox"/> Falling hazards from taller adjacent building</p> <p><input type="checkbox"/> Geologic hazards or Soil Type F</p> <p><input type="checkbox"/> Significant damage/deterioration to the structural system</p>	<p>ACTION REQUIRED</p> <p>Detailed Structural Evaluation Required?</p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building</p> <p><input checked="" type="checkbox"/> Yes, score less than cut-off</p> <p><input type="checkbox"/> Yes, other hazards present</p> <p><input type="checkbox"/> No</p> <p>Detailed Nonstructural Evaluation Recommended? (check one)</p> <p><input checked="" type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated</p> <p><input type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary</p> <p><input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p>
---	---	--

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Legend: MRF = Moment-resisting frame RC = Reinforced concrete URM INF = Unreinforced masonry infill MH = Manufactured Housing FD = Flexible diaphragm
RD = Rigid frame SW = Shear wall TU = Tilt up IM = Light metal DD = Diaphragm

Rapid Visual Screening of Buildings for Potential Seismic Hazards

FEMA P-154 Data Collection Form

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

Level 2 (Optional)
VERY HIGH Seismicity

Bldg Name: Sikeston High School – Building B	Final Level 1 Score: $S_{L1} = 0.6$	<i>(do not consider S_{MIN})</i>	
Screener: M. Griffin/B. Smith	Level 1 Irregularity Modifiers:	Vertical Irregularity, $V_{L1} = 0$	Plan Irregularity, $P_{L1} = -0.3$
Date/Time: 9-11-15/	ADJUSTED BASELINE SCORE:	$S' = (S_{L1} - V_{L1} - P_{L1}) = 0.9$	

STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

Topic	Statement (If statement is true, circle the "Yes" modifier, otherwise cross out the modifier.)	Yes	Subtotals
Vertical Irregularity, V_{L2}	Sloping Site	W1 building: There is at least a full story grade change from one side of the building to the other.	-0.9
		Non-W1 building: There is at least a full story grade change from one side of the building to the other.	-0.2
	Weak and/or Soft Story (circle one maximum)	W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.	-0.5
		W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum).	-0.9
		W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.	-0.9
		Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.	-0.7
		Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.	-0.4
	Setback	Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.	-0.7
		Vertical elements of the lateral system at upper stories are inboard of those at lower stories.	-0.4
		There is an in-plane offset of the lateral elements that is greater than the length of the elements.	-0.2
	Short Column/ Pier	C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.	-0.4
		C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.	-0.4
	Split Level	There is a split level at one of the floor levels or at the roof.	-0.4
Other Irregularity	There is another observable severe vertical irregularity that obviously affects the building's seismic performance.	-0.7	
	There is another observable moderate vertical irregularity that may affect the building's seismic performance.	-0.4	
Plan Irregularity, P_{L2}	Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.)	-0.5	
	Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.	-0.2	
	Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.	-0.2	
	Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.	-0.2	
	C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.	-0.2	
	Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.	-0.5	
Redundancy	The building has at least two bays of lateral elements on each side of the building in each direction.	+0.2	
Pounding	Building is separated from an adjacent structure by less than 1.5% of the height of the shorter of the building and adjacent structure and:	The floors do not align vertically within 2 feet.	(Cap total pounding modifiers at -0.9) -0.7
		One building is 2 or more stories taller than the other.	-0.7
		The building is at the end of the block.	-0.4
S2 Building	"K" bracing geometry is visible.	-0.7	
C1 Building	Flat plate serves as the beam in the moment frame.	-0.3	
PC1/RM1 Bldg	There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)	+0.2	
PC1/RM1 Bldg	The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).	+0.2	
URM	Gable walls are present.	-0.3	
MH	There is a supplemental seismic bracing system provided between the carriage and the ground.	+0.5	
Retrofit	Comprehensive seismic retrofit is visible or known from drawings.	+1.2	
FINAL LEVEL 2 SCORE, $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$:			0.7 <i>(Transfer to Level 1 form)</i>

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance: Yes No
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

OBSERVABLE NONSTRUCTURAL HAZARDS

Location	Statement (Check "Yes" or "No")	Yes	No	Comment
Exterior	There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.		X	
	There is heavy cladding or heavy veneer.	X		Exterior
	There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported.		X	
	There is an unreinforced masonry appendage over exit doors or pedestrian walkways.		X	
	There is a sign posted on the building that indicates hazardous materials are present.		X	
	There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney.		X	
	Other observed exterior nonstructural falling hazard:		X	
Interior	There are hollow clay tile or brick partitions at any stair or exit corridor.	X		CMU partitions, no OOP
	Other observed interior nonstructural falling hazard:	X		Contents

Estimated Nonstructural Seismic Performance (Check appropriate box and transfer to Level 1 form conclusions)
 Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended
 Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required
 Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

Comments: Tall storage cabinets UA. Boilers UA. Gas hot water tanks UA. Generally pretty clean in classrooms. Halls nice & clear.



Address: 200 Pine Street
Sikeston, MO Zip: 63801

Other Identifiers: Sikeston R-6 District

Building Name: Sikeston Senior High School - Building C

Use: K-12 School

Latitude: 36.879228 Longitude: -89.572154

Ss: 2.445g Sr: 0.908g

Screener(s): M. Griffin/B. Smith Date/Time: 9-11-15/

No. Stories: Above Grade: 1 Below Grade: 0 Year Built: 1960 EST

Total Floor Area (sq. ft.): 25,477 Code Year: Unknown

Additions: None Yes, Year(s) Built: Over 20 years ago - library west

Occupancy: Assembly Commercial Emer. Services Historic Shelter
Industrial Office School Government
Utility Warehouse Residential, # Units: _____

Soil Type: A B C D E F DNK
Hard Avg Dense Stiff Soft Poor If DNK, assume Type D.
Rock Rock Soil Soil Soil Soil

Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

Adjacency: NONE Pounding Falling Hazards from Taller Adjacent Building

Irregularities: Vertical (type/severity) Vertical set-back
 Plan (type) Re-entrant corner

Exterior Falling Hazards: Unbraced Chimneys Heavy Cladding or Heavy Veneer
 Parapets Appendages
 Other: _____ Brick Veneer

610.021(20)

COMMENTS:

- Steel TS framing w/masonry infill
- Tectum roof system w/Bulb-T's
- Suspended rigid drywall ceiling
- Interior CMU partition walls without OOP bracing
- Corridor classroom walls have at the floor return air openings. Timber framed, some short shelving is sup'd from walls. Some tall shelving near classroom exits.
- Library shelving is restrained
- Corridors clear

Additional sketches or comments on separate page

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE, S_{L1}

FEMA BUILDING TYPE	Do Not Know	W1	W1A	W2	S1 (MRF)	S2 (BR)	S3 (LM)	S4 (RC SW)	S5 (URM INF)	C1 (MRF)	C2 (SW)	C3 (URM INF)	PC1 (TU)	PC2	RM1 (FD)	RM2 (RD)	URM	MH
Basic Score		2.1	1.9	1.8	1.5	1.4	1.6	1.4	1.2	1.0	1.2	0.9	1.1	1.0	1.1	1.1	0.9	1.1
Severe Vertical Irregularity, V_{L1}		-0.9	-0.9	-0.9	-0.8	-0.7	-0.8	-0.7	-0.7	-0.7	-0.8	-0.6	-0.7	-0.7	-0.7	-0.7	-0.6	NA
Moderate Vertical Irregularity, V_{L1}		-0.6	-0.5	-0.5	-0.4	-0.4	-0.5	-0.4	-0.3	-0.4	-0.4	-0.3	-0.4	-0.4	-0.4	-0.4	-0.3	NA
Plan Irregularity, P_{L1}		-0.7	-0.7	-0.6	-0.5	-0.5	-0.6	-0.4	-0.4	-0.4	-0.5	-0.3	-0.5	-0.4	-0.4	-0.4	-0.3	NA
Pre-Code		-0.3	-0.3	-0.3	-0.3	-0.2	-0.3	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	0.0
Post-Benchmark		1.9	1.9	2.0	1.0	1.1	1.1	1.5	NA	1.4	1.7	NA	1.5	1.7	1.6	1.6	NA	0.5
Soil Type A or B		0.5	0.5	0.4	0.3	0.3	0.4	0.3	0.2	0.2	0.3	0.1	0.3	0.2	0.3	0.3	0.1	0.1
Soil Type E (1-3 stories)		0.0	-0.2	-0.4	-0.3	-0.2	-0.2	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	-0.1
Soil Type E (> 3 stories)		-0.4	-0.4	-0.4	-0.3	-0.3	NA	-0.3	-0.1	-0.1	-0.3	-0.1	NA	-0.1	-0.2	-0.2	0.0	NA
Minimum Score, S_{MIN}		0.7	0.7	0.7	0.5	0.5	0.5	0.5	0.5	0.3	0.3	0.3	0.2	0.2	0.3	0.3	0.2	1.0

FINAL LEVEL 1 SCORE, $S_{L1} \geq S_{MIN}$: 0.5(0.0)

<p>EXTENT OF REVIEW</p> <p>Exterior: <input type="checkbox"/> Partial <input checked="" type="checkbox"/> All Sides <input type="checkbox"/> Aerial Interior: <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered</p> <p>Drawings Reviewed: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p> <p>Soil Type Source: Vs30</p> <p>Geologic Hazards Source: Regional Data</p> <p>Contact Person: Mike Brown</p>	<p>OTHER HAZARDS</p> <p>Are There Hazards That Trigger A Detailed Structural Evaluation?</p> <p><input type="checkbox"/> Pounding potential (unless $S_{L2} >$ cut-off, if known)</p> <p><input type="checkbox"/> Falling hazards from taller adjacent building</p> <p><input type="checkbox"/> Geologic hazards or Soil Type F</p> <p><input type="checkbox"/> Significant damage/deterioration to the structural system</p>	<p>ACTION REQUIRED</p> <p>Detailed Structural Evaluation Required?</p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building</p> <p><input checked="" type="checkbox"/> Yes, score less than cut-off</p> <p><input type="checkbox"/> Yes, other hazards present</p> <p><input type="checkbox"/> No</p> <p>Detailed Nonstructural Evaluation Recommended? (check one)</p> <p><input checked="" type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated</p> <p><input type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary</p> <p><input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p>
<p>LEVEL 2 SCREENING PERFORMED?</p> <p><input checked="" type="checkbox"/> Yes, Final Level 2 Score, S_{L2} 1.3 <input type="checkbox"/> No</p> <p>Nonstructural hazards? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p>		

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Rapid Visual Screening of Buildings for Potential Seismic Hazards

FEMA P-154 Data Collection Form

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

Level 2 (Optional)
VERY HIGH Seismicity

Bldg Name: Sikeston High School – Building C	Final Level 1 Score: $S_{L1} = 0.0$	<i>(do not consider S_{Min})</i>	
Screener: M. Griffin/B. Smith	Level 1 Irregularity Modifiers:	Vertical Irregularity, $V_{L1} = -0.7$	Plan Irregularity, $P_{L1} = -0.4$
Date/Time: 9-11-15/	ADJUSTED BASELINE SCORE:	$S' = (S_{L1} - V_{L1} - P_{L1}) = 1.1$	

STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

Topic	Statement (If statement is true, circle the "Yes" modifier, otherwise cross out the modifier.)	Yes	Subtotals
Vertical Irregularity, V_{L2}	Sloping Site	W1 building: There is at least a full story grade change from one side of the building to the other.	-0.9
		Non-W1 building: There is at least a full story grade change from one side of the building to the other.	-0.2
	Weak and/or Soft Story (circle one maximum)	W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.	-0.5
		W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum).	-0.9
		W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.	-0.9
		Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.	-0.7
		Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.	-0.4
	Setback	Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.	-0.7
		Vertical elements of the lateral system at upper stories are inboard of those at lower stories.	-0.4
		There is an in-plane offset of the lateral elements that is greater than the length of the elements.	-0.2
	Short Column/ Pier	C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.	-0.4
		C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.	-0.4
	Split Level	There is a split level at one of the floor levels or at the roof.	-0.4
	Other Irregularity	There is another observable severe vertical irregularity that obviously affects the building's seismic performance.	-0.7
There is another observable moderate vertical irregularity that may affect the building's seismic performance.		-0.4	
Plan Irregularity, P_{L2}	Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.)	-0.5	
	Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.	-0.2	
	Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.	-0.2	
	Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.	-0.2	
	C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.	-0.2	
	Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.	-0.5	
Redundancy	The building has at least two bays of lateral elements on each side of the building in each direction.	+0.2	
Pounding	Building is separated from an adjacent structure by less than 1.5% of the height of the shorter of the building and adjacent structure and:	The floors do not align vertically within 2 feet.	(Cap total Pounding Modifiers at -0.9) -0.7
		One building is 2 or more stories taller than the other.	-0.7
		The building is at the end of the block.	-0.4
S2 Building	"K" bracing geometry is visible.	-0.7	
C1 Building	Flat plate serves as the beam in the moment frame.	-0.3	
PC1/RM1 Bldg	There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)	+0.2	
PC1/RM1 Bldg	The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).	+0.2	
URM	Gable walls are present.	-0.3	
MH	There is a supplemental seismic bracing system provided between the carriage and the ground.	+0.5	
Retrofit	Comprehensive seismic retrofit is visible or known from drawings.	+1.2	
FINAL LEVEL 2 SCORE, $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{Min}$:			1.3
			<i>(Transfer to Level 1 form)</i>

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance: Yes No
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

OBSERVABLE NONSTRUCTURAL HAZARDS

Location	Statement (Check "Yes" or "No")	Yes	No	Comment
Exterior	There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.		X	
	There is heavy cladding or heavy veneer.	X		Brick Veneer
	There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported.		X	
	There is an unreinforced masonry appendage over exit doors or pedestrian walkways.		X	
	There is a sign posted on the building that indicates hazardous materials are present.		X	
	There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney.		X	
	Other observed exterior nonstructural falling hazard:		X	
Interior	There are hollow clay tile or brick partitions at any stair or exit corridor.	X		Interior CMU & brick partition
	Other observed interior nonstructural falling hazard:	X		Contents

Estimated Nonstructural Seismic Performance (Check appropriate box and transfer to Level 1 form conclusions)
 Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended
 Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required
 Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

Comments: Minor interior contents, tall unrestrained bookshelves near classroom exists. Other small misc. contents as well. Generally clear.



Address: 200 Pine Street
Sikeston, MO Zip: 63801

Other Identifiers: Sikeston R-6 District

Building Name: Sikeston Senior High School - Building D, Girls Gym

Use: K-12 School

Latitude: 36.879228 Longitude: -89.572154

Ss: 2.445g S: 0.908g

Screener(s): M. Griffin/B. Smith Date/Time: 9-11-15/

No. Stories: Above Grade: 1 Below Grade: 0 Year Built: 1960 EST

Total Floor Area (sq. ft.): 13,421 Code Year: Unknown

Additions: None Yes, Year(s) Built: _____

Occupancy: Assembly Commercial Emer. Services Historic Shelter
Industrial Office School Government
Utility Warehouse Residential, # Units: _____

Soil Type: A B C D E F DNK
Hard Avg Dense Stiff Soft Poor DNK
Rock Rock Soil Soil Soil Soil If DNK, assume Type D

Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf Rupt: Yes/No/DNK

Adjacency: Pounding Falling Hazards from Taller Adjacent Building

Irregularities: Vertical (type/severity) Out-of-plane set-back
 Plan (type) Torsion-upper window openings

Exterior Falling Hazards: Unbraced Chimneys Heavy Cladding or Heavy Veneer
 Parapets Appendages
 Other: _____ Exterior brick veneer

610.021(20)

COMMENTS:

- Tectum roof system over steel girders & steel joists
- CMU bearing wall system. One side of gym has upper window openings between girder pilaster columns
- Gym CMU walls have vertical cracks ~ 25' o.c. no control joists were observed
- Gym floor was attached to base of perimeter wall with STL angle... Said it was a retrofit?

Additional sketches or comments on separate page

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE, S_{L1}

FEMA BUILDING TYPE	Do Not Know	W1	W1A	W2	S1 (MRF)	S2 (BR)	S3 (LM)	S4 (RC SW)	S5 (URM INF)	C1 (MRF)	C2 (SW)	C3 (URM INF)	PC1 (TU)	PC2	RM1 (FD)	RM2 (RD)	URM	MH
Basic Score		2.1	1.9	1.8	1.5	1.4	1.6	1.4	1.2	1.0	1.2	0.9	1.1	1.0	1.1	1.1	0.9	1.1
Severe Vertical Irregularity, V _{L1}		-0.9	-0.9	-0.9	-0.8	-0.7	-0.8	-0.7	-0.7	-0.7	-0.8	-0.6	-0.7	-0.7	-0.7	-0.7	-0.6	NA
Moderate Vertical Irregularity, V _{L1}		-0.6	-0.5	-0.5	-0.4	-0.4	-0.5	-0.4	-0.3	-0.4	-0.4	-0.3	-0.4	-0.4	-0.4	-0.4	-0.3	NA
Plan Irregularity, P _{L1}		-0.7	-0.7	-0.6	-0.5	-0.5	-0.6	-0.4	-0.4	-0.4	-0.5	-0.3	-0.5	-0.4	-0.4	-0.4	-0.3	NA
Pre-Code		-0.3	-0.3	-0.3	-0.3	-0.2	-0.3	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	0.0
Post-Benchmark		1.9	1.9	2.0	1.0	1.1	1.1	1.5	NA	1.4	1.7	NA	1.5	1.7	1.6	1.6	NA	0.5
Soil Type A or B		0.5	0.5	0.4	0.3	0.3	0.4	0.3	0.2	0.2	0.3	0.1	0.3	0.2	0.3	0.3	0.1	0.1
Soil Type E (1-3 stories)		0.0	-0.2	-0.4	-0.3	-0.2	-0.2	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	-0.1
Soil Type E (> 3 stories)		-0.4	-0.4	-0.4	-0.3	-0.3	NA	-0.3	-0.1	-0.1	-0.3	-0.1	NA	-0.1	-0.2	-0.2	0.0	NA
Minimum Score, S _{MIN}		0.7	0.7	0.7	0.5	0.5	0.5	0.5	0.5	0.3	0.3	0.3	0.2	0.2	0.3	0.3	0.2	1.0

FINAL LEVEL 1 SCORE, S_{L1} ≥ S_{MIN}: **0.2(0.0)**

<p>EXTENT OF REVIEW</p> <p>Exterior: <input type="checkbox"/> Partial <input checked="" type="checkbox"/> All Sides <input type="checkbox"/> Aerial</p> <p>Interior: <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered</p> <p>Drawings Reviewed: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No partial</p> <p>Soil Type Source: Vs30</p> <p>Geologic Hazards Source: Regional Data</p> <p>Contact Person: Mike Brown</p> <p>LEVEL 2 SCREENING PERFORMED?</p> <p><input checked="" type="checkbox"/> Yes, Final Level 2 Score, S_{L2} 0.4 <input type="checkbox"/> No</p> <p>Nonstructural hazards? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p>	<p>OTHER HAZARDS</p> <p>Are There Hazards That Trigger A Detailed Structural Evaluation?</p> <p><input type="checkbox"/> Pounding potential (unless S_{L2} > cut-off, if known)</p> <p><input type="checkbox"/> Falling hazards from taller adjacent building</p> <p><input type="checkbox"/> Geologic hazards or Soil Type F</p> <p><input type="checkbox"/> Significant damage/deterioration to the structural system</p>	<p>ACTION REQUIRED</p> <p>Detailed Structural Evaluation Required?</p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building</p> <p><input checked="" type="checkbox"/> Yes, score less than cut-off</p> <p><input type="checkbox"/> Yes, other hazards present</p> <p><input type="checkbox"/> No</p> <p>Detailed Nonstructural Evaluation Recommended? (check one)</p> <p><input type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated</p> <p><input checked="" type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary</p> <p><input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p>
---	---	--

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Rapid Visual Screening of Buildings for Potential Seismic Hazards

FEMA P-154 Data Collection Form

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

Level 2 (Optional)
VERY HIGH Seismicity

Bldg Name: Sikeston High School -Bldg D,Girls Gym	Final Level 1 Score: $S_{L1} =$ 0.0	<i>(do not consider S_{MIN})</i>	
Screener: M. Griffin/B. Smith	Level 1 Irregularity Modifiers:	<i>Vertical Irregularity, $V_{L1} =$ -0.6</i>	<i>Plan Irregularity, $P_{L1} =$ -0.3</i>
Date/Time: 9-11-15/	ADJUSTED BASELINE SCORE:	$S' = (S_{L1} - V_{L1} - P_{L1}) =$ 0.9	

STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

Topic	Statement (If statement is true, circle the "Yes" modifier, otherwise cross out the modifier.)	Yes	Subtotals
Vertical Irregularity, V_{L2}	Sloping Site	W1 building: There is at least a full story grade change from one side of the building to the other.	-0.9
		Non-W1 building: There is at least a full story grade change from one side of the building to the other.	-0.2
	Weak and/or Soft Story (circle one maximum)	W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.	-0.5
		W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum).	-0.9
		W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.	-0.9
		Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.	-0.7
		Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.	-0.4
	Setback	Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.	-0.7
		Vertical elements of the lateral system at upper stories are inboard of those at lower stories.	-0.4
		There is an in-plane offset of the lateral elements that is greater than the length of the elements.	-0.2
	Short Column/ Pier	C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.	-0.4
		C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.	-0.4
	Split Level	There is a split level at one of the floor levels or at the roof.	-0.4
	Other Irregularity	There is another observable severe vertical irregularity that obviously affects the building's seismic performance.	-0.7
There is another observable moderate vertical irregularity that may affect the building's seismic performance.		-0.4	
Plan Irregularity, P_{L2}	Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.)	-0.5	
	Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.	-0.2	
	Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.	-0.2	
	Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.	-0.2	
	C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.	-0.2	
	Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.	-0.5	
Redundancy	The building has at least two bays of lateral elements on each side of the building in each direction.	+0.2	
Pounding	Building is separated from an adjacent structure by less than 1.5% of the height of the shorter of the building and adjacent structure and:	The floors do not align vertically within 2 feet.	-0.7
		One building is 2 or more stories taller than the other.	-0.7
		The building is at the end of the block.	-0.4
S2 Building	"K" bracing geometry is visible.	-0.7	
C1 Building	Flat plate serves as the beam in the moment frame.	-0.3	
PC1/RM1 Bldg	There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)	+0.2	
PC1/RM1 Bldg	The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).	+0.2	
URM	Gable walls are present.	-0.3	
MH	There is a supplemental seismic bracing system provided between the carriage and the ground.	+0.5	
Retrofit	Comprehensive seismic retrofit is visible or known from drawings.	+1.2	
			$V_{L2} =$ <u>0.0</u> <i>(Cap at -0.9)</i>
			$P_{L2} =$ <u>-0.5</u> <i>(Cap at -0.7)</i>
			$M =$ <u>0.0</u>

FINAL LEVEL 2 SCORE, $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$: **0.4** *(Transfer to Level 1 form)*

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance: Yes No
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

OBSERVABLE NONSTRUCTURAL HAZARDS

Location	Statement (Check "Yes" or "No")	Yes	No	Comment
Exterior	There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.		X	
	There is heavy cladding or heavy veneer.	X		Brick Veneer
	There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported.		X	
	There is an unreinforced masonry appendage over exit doors or pedestrian walkways.		X	
	There is a sign posted on the building that indicates hazardous materials are present.		X	
	There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney.		X	
	Other observed exterior nonstructural falling hazard:		X	
Interior	There are hollow clay tile or brick partitions at any stair or exit corridor.	X		Interior CMU partition
	Other observed interior nonstructural falling hazard:		X	

Estimated Nonstructural Seismic Performance (Check appropriate box and transfer to Level 1 form conclusions)
 Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended
 Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required
 Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

Comments: Minor issue with masonry interior partition walls.



Address: 200 Pine Street
Sikeston, MO Zip: 63801

Other Identifiers: Sikeston R-6 District

Building Name: Sikeston Senior High School - Building F Band/Music

Use: K-12 School

Latitude: 36.879228 Longitude: -89.572154

Ss: 2.445g S: 0.908g

Screener(s): M. Griffin/B. Smith Date/Time: 9-11-15/

No. Stories: Above Grade: 1 Below Grade: 0 Year Built: 1960 EST

Total Floor Area (sq. ft.): 4,137 Code Year: Unknown

Additions: None Yes, Year(s) Built: _____

Occupancy: Assembly Commercial Emer. Services Historic Shelter
Industrial Office School Government
Utility Warehouse Residential, # Units: _____

Soil Type: A B C D E F DNK
Hard Avg Dense Stiff Soft Poor DNK
Rock Rock Soil Soil Soil Soil *If DNK, assume Type D.*

Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

Adjacency: Pounding Falling Hazards from Taller Adjacent Building

Irregularities: Vertical (type/severity) _____
 Plan (type) Torsion w/canopy structure

Exterior Falling Hazards: Unbraced Chimneys Heavy Cladding or Heavy Veneer
 Parapets Appendages
 Other: _____ **Brick Veneer**

610.021(20)

COMMENTS:
- 1959 Drawings
- Reinforced concrete frame
- Columns have #3@12 shear ties
- Spread footings
- Bookcases not restrained to walls
- Shelves (music) on wheels, but wheels were locked
- Infill walls have no OOP restraint

Additional sketches or comments on separate page

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE, S_{L1}

FEMA BUILDING TYPE	Do Not Know	W1	W1A	W2	S1 (MRF)	S2 (BR)	S3 (LM)	S4 (RC SW)	S5 (URM INF)	C1 (MRF)	C2 (SW)	C3 (URM INF)	PC1 (TU)	PC2	RM1 (FD)	RM2 (RD)	URM	MH
Basic Score		2.1	1.9	1.8	1.5	1.4	1.6	1.4	1.2	1.0	1.2	0.9	1.1	1.0	1.1	1.1	0.9	1.1
Severe Vertical Irregularity, V_{L1}		-0.9	-0.9	-0.9	-0.8	-0.7	-0.8	-0.7	-0.7	-0.7	-0.8	-0.6	-0.7	-0.7	-0.7	-0.7	-0.6	NA
Moderate Vertical Irregularity, V_{L2}		-0.6	-0.5	-0.5	-0.4	-0.4	-0.5	-0.4	-0.3	-0.4	-0.4	-0.3	-0.4	-0.4	-0.4	-0.4	-0.3	NA
Plan Irregularity, P_{L1}		-0.7	-0.7	-0.6	-0.5	-0.5	-0.6	-0.4	-0.4	-0.4	-0.5	-0.3	-0.5	-0.4	-0.4	-0.4	-0.3	NA
Pre-Code		-0.3	-0.3	-0.3	-0.3	-0.2	-0.3	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	0.0
Post-Benchmark		1.9	1.9	2.0	1.0	1.1	1.1	1.5	NA	1.4	1.7	NA	1.5	1.7	1.6	1.6	NA	0.5
Soil Type A or B		0.5	0.5	0.4	0.3	0.3	0.4	0.3	0.2	0.2	0.3	0.1	0.3	0.2	0.3	0.3	0.1	0.1
Soil Type E (1-3 stories)		0.0	-0.2	-0.4	-0.3	-0.2	-0.2	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	-0.1
Soil Type E (> 3 stories)		-0.4	-0.4	-0.4	-0.3	-0.3	NA	-0.3	-0.1	-0.1	-0.3	-0.1	NA	-0.1	-0.2	-0.2	0.0	NA
Minimum Score, S_{MIN}		0.7	0.7	0.7	0.5	0.5	0.5	0.5	0.5	0.3	0.3	0.3	0.2	0.2	0.3	0.3	0.2	1.0

FINAL LEVEL 1 SCORE, $S_{L1} \geq S_{MIN}$:

0.6

EXTENT OF REVIEW

Exterior: Partial All Sides Aerial
Interior: None Visible Entered
Drawings Reviewed: Yes No
Soil Type Source: Vs30
Geologic Hazards Source: Regional Data
Contact Person: Mike Brown

OTHER HAZARDS

Are There Hazards That Trigger A Detailed Structural Evaluation?

Pounding potential (unless $S_{L2} >$ cut-off, if known)
 Falling hazards from taller adjacent building
 Geologic hazards or Soil Type F
 Significant damage/deterioration to the structural system

ACTION REQUIRED

Detailed Structural Evaluation Required?

Yes, unknown FEMA building type or other building
 Yes, score less than cut-off
 Yes, other hazards present
 No

Detailed Nonstructural Evaluation Recommended? (check one)

Yes, nonstructural hazards identified that should be evaluated
 No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary
 No, no nonstructural hazards identified DNK

LEVEL 2 SCREENING PERFORMED?

Yes, Final Level 2 Score, S_{L2} 0.4 No
Nonstructural hazards? Yes No

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Rapid Visual Screening of Buildings for Potential Seismic Hazards

FEMA P-154 Data Collection Form

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

Level 2 (Optional)
VERY HIGH Seismicity

Bldg Name: Sikeston High School-Bldg F, Band Music	Final Level 1 Score: $S_{L1} = 0.6$	<i>(do not consider S_{MIN})</i>	
Screener: M. Griffin/B. Smith	Level 1 Irregularity Modifiers:	Vertical Irregularity, $V_{L1} = 0$	Plan Irregularity, $P_{L1} = -0.3$
Date/Time: 9-11-15/	ADJUSTED BASELINE SCORE:	$S' = (S_{L1} - V_{L1} - P_{L1}) = 0.9$	

STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

Topic	Statement (If statement is true, circle the "Yes" modifier, otherwise cross out the modifier.)	Yes	Subtotals
Vertical Irregularity, V_{L2}	Sloping Site	W1 building: There is at least a full story grade change from one side of the building to the other.	-0.9
		Non-W1 building: There is at least a full story grade change from one side of the building to the other.	-0.2
	Weak and/or Soft Story (circle one maximum)	W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.	-0.5
		W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum).	-0.9
		W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.	-0.9
		Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.	-0.7
		Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.	-0.4
	Setback	Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.	-0.7
		Vertical elements of the lateral system at upper stories are inboard of those at lower stories.	-0.4
		There is an in-plane offset of the lateral elements that is greater than the length of the elements.	-0.2
	Short Column/ Pier	C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.	-0.4
		C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.	-0.4
Split Level	There is a split level at one of the floor levels or at the roof.	-0.4	
Other Irregularity	There is another observable severe vertical irregularity that obviously affects the building's seismic performance.	-0.7	
	There is another observable moderate vertical irregularity that may affect the building's seismic performance.	-0.4	
		$V_{L2} = 0.0$ <i>(Cap at -0.9)</i>	
Plan Irregularity, P_{L2}	Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. <i>(Do not include the W1A open front irregularity listed above.)</i>	-0.5	
Overhead RC cover	Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.	-0.2	
	Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.	-0.2	
	Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.	-0.2	
	C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.	-0.2	
	Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.	-0.5	
		$P_{L2} = -0.5$ <i>(Cap at -0.7)</i>	
Redundancy	The building has at least two bays of lateral elements on each side of the building in each direction.	+0.2	
Pounding	Building is separated from an adjacent structure by less than 1.5% of the height of the shorter of the building and adjacent structure and:	The floors do not align vertically within 2 feet.	-0.7
		One building is 2 or more stories taller than the other.	-0.7
		The building is at the end of the block.	-0.4
		<i>(Cap total pounding modifiers at -0.9)</i>	
S2 Building	"K" bracing geometry is visible.	-0.7	
C1 Building	Flat plate serves as the beam in the moment frame.	-0.3	
PC1/RM1 Bldg	There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. <i>(Do not combine with post-benchmark or retrofit modifier.)</i>	+0.2	
PC1/RM1 Bldg	The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).	+0.2	
URM	Gable walls are present.	-0.3	
MH	There is a supplemental seismic bracing system provided between the carriage and the ground.	+0.5	
Retrofit	Comprehensive seismic retrofit is visible or known from drawings.	+1.2	
		$M = 0.0$	

FINAL LEVEL 2 SCORE, $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$: 0.4 *(Transfer to Level 1 form)*

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance: Yes No
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

OBSERVABLE NONSTRUCTURAL HAZARDS

Location	Statement (Check "Yes" or "No")	Yes	No	Comment
Exterior	There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.		X	
	There is heavy cladding or heavy veneer.	X		Brick veneer
	There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported.		X	Canopy integral to structure
	There is an unreinforced masonry appendage over exit doors or pedestrian walkways.		X	
	There is a sign posted on the building that indicates hazardous materials are present.		X	
	There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney.		X	
	Other observed exterior nonstructural falling hazard:		X	
Interior	There are hollow clay tile or brick partitions at any stair or exit corridor.	X		CMU partition walls
	Other observed interior nonstructural falling hazard:	X		Contents

Estimated Nonstructural Seismic Performance *(Check appropriate box and transfer to Level 1 form conclusions)*

Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended

Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required

Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

Comments: Shelving on wheels, locked at back of room. Shelving, tall, unrestrained to walls. CMU partition walls with no OOP bracing.



Address: 200 Pine Street
Sikeston, MO Zip: 63801

Other Identifiers: Sikeston R-6 District

Building Name: Sikeston Senior High School - Building G

Use: K-12 School

Latitude: 36.879228 Longitude: -89.572154

Ss: 2.445g S: 0.908g

Screeener(s): M. Griffin/B. Smith Date/Time: 9-11-15/

No. Stories: Above Grade: 1 Below Grade: 0 Year Built: 1968 EST

Total Floor Area (sq. ft.): 19,198 Code Year: Unknown

Additions: None Yes, Year(s) Built: Unknown

Occupancy: Assembly Commercial Emer. Services Historic Shelter
Industrial Office School Government
Utility Warehouse Residential, # Units: _____


Soil Type: A B C D E F **DNK**
Hard Avg Dense Stiff Soft Poor *If DNK, assume Type D.*
Rock Rock Soil Soil Soil Soil

Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

Adjacency: Pounding Falling Hazards from Taller Adjacent Building

Irregularities: Vertical (type/severity) _____
 Plan (type) Re-entrant corners

Exterior Falling Hazards: Unbraced Chimneys Heavy Cladding or Heavy Veneer
 Parapets Appendages
 Other: _____ Brick Veneer



610.021(20)

COMMENTS:
- CMU Brg wall (URM)
- Tectum roof system over STL bar joists
- Possible addition between classrooms 2-3 & 9-8 as change in floor elevation
- Glass in corridor partitions, w/bottom open for return air flow
- Suspended drywall ceilings, lights directly attached

Additional sketches or comments on separate page

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE, S_{L1}

FEMA BUILDING TYPE	Do Not Know	W1	W1A	W2	S1 (MRF)	S2 (BR)	S3 (LM)	S4 (RC SW)	S5 (URM INF)	C1 (MRF)	C2 (SW)	C3 (URM INF)	PC1 (TU)	PC2	RM1 (FD)	RM2 (RD)	URM	MH
Basic Score		2.1	1.9	1.8	1.5	1.4	1.6	1.4	1.2	1.0	1.2	0.9	1.1	1.0	1.1	1.1	0.9	1.1
Severe Vertical Irregularity, V _{L1}		-0.9	-0.9	-0.9	-0.8	-0.7	-0.8	-0.7	-0.7	-0.7	-0.8	-0.6	-0.7	-0.7	-0.7	-0.7	-0.6	NA
Moderate Vertical Irregularity, V _{L1}		-0.6	-0.5	-0.5	-0.4	-0.4	-0.5	-0.4	-0.3	-0.4	-0.4	-0.3	-0.4	-0.4	-0.4	-0.4	-0.3	NA
Plan Irregularity, P _{L1}		-0.7	-0.7	-0.6	-0.5	-0.5	-0.6	-0.4	-0.4	-0.4	-0.5	-0.3	-0.5	-0.4	-0.4	-0.4	-0.3	NA
Pre-Code		-0.3	-0.3	-0.3	-0.3	-0.2	-0.3	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	0.0
Post-Benchmark		1.9	1.9	2.0	1.0	1.1	1.1	1.5	NA	1.4	1.7	NA	1.5	1.7	1.6	1.6	NA	0.5
Soil Type A or B		0.5	0.5	0.4	0.3	0.3	0.4	0.3	0.2	0.2	0.3	0.1	0.3	0.2	0.3	0.3	0.1	0.1
Soil Type E (1-3 stories)		0.0	-0.2	-0.4	-0.3	-0.2	-0.2	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	-0.1
Soil Type E (> 3 stories)		-0.4	-0.4	-0.4	-0.3	-0.3	NA	-0.3	-0.1	-0.1	-0.3	-0.1	NA	-0.1	-0.2	-0.2	0.0	NA
Minimum Score, S _{MIN}		0.7	0.7	0.7	0.5	0.5	0.5	0.5	0.5	0.3	0.3	0.3	0.2	0.2	0.3	0.3	0.2	1.0

FINAL LEVEL 1 SCORE, S_{L1} ≥ S_{MIN}: 0.6

<p>EXTENT OF REVIEW</p> <p>Exterior: <input type="checkbox"/> Partial <input checked="" type="checkbox"/> All Sides <input type="checkbox"/> Aerial Interior: <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered Drawings Reviewed: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Soil Type Source: Vs30 Geologic Hazards Source: Regional Data Contact Person: Mike Brown</p> <p>LEVEL 2 SCREENING PERFORMED?</p> <p><input checked="" type="checkbox"/> Yes, Final Level 2 Score, S_{L2} 0.9 <input type="checkbox"/> No Nonstructural hazards? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p>	<p>OTHER HAZARDS</p> <p>Are There Hazards That Trigger A Detailed Structural Evaluation?</p> <p><input type="checkbox"/> Pounding potential (unless S_{L2} > cut-off, if known) <input type="checkbox"/> Falling hazards from taller adjacent building <input type="checkbox"/> Geologic hazards or Soil Type F <input type="checkbox"/> Significant damage/deterioration to the structural system</p>	<p>ACTION REQUIRED</p> <p>Detailed Structural Evaluation Required?</p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building <input checked="" type="checkbox"/> Yes, score less than cut-off <input type="checkbox"/> Yes, other hazards present <input type="checkbox"/> No</p> <p>Detailed Nonstructural Evaluation Recommended? (check one)</p> <p><input checked="" type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated <input type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary <input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p>
---	--	---

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Rapid Visual Screening of Buildings for Potential Seismic Hazards

FEMA P-154 Data Collection Form

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

Level 2 (Optional)
VERY HIGH Seismicity

Bldg Name: Sikeston High School – Building G	Final Level 1 Score: $S_{L1} = 0.6$	<i>(do not consider S_{MIN})</i>	
Screener: M. Griffin/B. Smith	Level 1 Irregularity Modifiers:	Vertical Irregularity, $V_{L1} = 0$	Plan Irregularity, $P_{L1} = -0.3$
Date/Time: 9-11-15/	ADJUSTED BASELINE SCORE:	$S' = (S_{L1} - V_{L1} - P_{L1}) = 0.9$	

STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

Topic	Statement (If statement is true, circle the "Yes" modifier, otherwise cross out the modifier.)	Yes	Subtotals
Vertical Irregularity, V_{L2}	Sloping Site	W1 building: There is at least a full story grade change from one side of the building to the other.	-0.9
		Non-W1 building: There is at least a full story grade change from one side of the building to the other.	-0.2
	Weak and/or Soft Story (circle one maximum)	W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.	-0.5
		W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum).	-0.9
		W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.	-0.9
		Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.	-0.7
		Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.	-0.4
	Setback	Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.	-0.7
		Vertical elements of the lateral system at upper stories are inboard of those at lower stories.	-0.4
		There is an in-plane offset of the lateral elements that is greater than the length of the elements.	-0.2
	Short Column/ Pier	C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.	-0.4
		C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.	-0.4
Split Level	There is a split level at one of the floor levels or at the roof.	-0.4	
Other Irregularity	There is another observable severe vertical irregularity that obviously affects the building's seismic performance.	-0.7	
	There is another observable moderate vertical irregularity that may affect the building's seismic performance.	-0.4	
Plan Irregularity, P_{L2}	Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.)	-0.5	
	Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.	-0.2	
	Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.	-0.2	
	Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.	-0.2	
	C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.	-0.2	
	Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.	-0.5	
Redundancy	The building has at least two bays of lateral elements on each side of the building in each direction.	+0.2	
Pounding	Building is separated from an adjacent structure by less than 1.5% of the height of the shorter of the building and adjacent structure and:	The floors do not align vertically within 2 feet.	-0.7
		One building is 2 or more stories taller than the other.	-0.7
		The building is at the end of the block.	-0.4
S2 Building	"K" bracing geometry is visible.	-0.7	
C1 Building	Flat plate serves as the beam in the moment frame.	-0.3	
PC1/RM1 Bldg	There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)	+0.2	
PC1/RM1 Bldg	The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).	+0.2	
URM	Gable walls are present.	-0.3	
MH	There is a supplemental seismic bracing system provided between the carriage and the ground.	+0.5	
Retrofit	Comprehensive seismic retrofit is visible or known from drawings.	+1.2	
			$V_{L2} = 0.0$ (Cap at -0.9)
			$P_{L2} = 0.0$ (Cap at -0.7)
			$M = 0.0$

FINAL LEVEL 2 SCORE, $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$: 0.9 *(Transfer to Level 1 form)*

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance: Yes No
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

OBSERVABLE NONSTRUCTURAL HAZARDS

Location	Statement (Check "Yes" or "No")	Yes	No	Comment
Exterior	There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.		X	
	There is heavy cladding or heavy veneer.	X		Brick veneer
	There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported.		X	
	There is an unreinforced masonry appendage over exit doors or pedestrian walkways.		X	
	There is a sign posted on the building that indicates hazardous materials are present.		X	
	There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney.		X	
	Other observed exterior nonstructural falling hazard:		X	
Interior	There are hollow clay tile or brick partitions at any stair or exit corridor.	X		Partition walls CMU
	Other observed interior nonstructural falling hazard:	X		See below

Estimated Nonstructural Seismic Performance (Check appropriate box and transfer to Level 1 form conclusions)

- Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended
- Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required
- Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

Comments: Electric transformer is UA. Chiller (new) is UA. CMU partition walls with no OOP bracing. Corridor walls have glazing. Cooling tower is marginally anchored.



Address: 200 Pine Street
Sikeston, MO Zip: 63801

Other Identifiers: Sikeston R-6 District

Building Name: Sikeston Senior High School - Building H

Use: K-12 School

Latitude: 36.879228 Longitude: -89.572154

Ss: 2.445g S_r: 0.908g

Screener(s): M. Griffin/B. Smith Date/Time: 9-11-15/

No. Stories: Above Grade: 1 Below Grade: 0 Year Built: 1967 EST

Total Floor Area (sq. ft.): 17,717 Code Year: Unknown

Additions: None Yes, Year(s) Built: Auto Diagnostics, unknown

Occupancy: Assembly Commercial Emer. Services Historic Shelter
Industrial Office School Government
Utility Warehouse Residential, # Units: _____

Soil Type: A B C D E F DNK
Hard Avg Dense Stiff Soft Poor DNK
Rock Rock Soil Soil Soil Soil If DNK, assume Type D.

Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

Adjacency: Pounding Falling Hazards from Taller Adjacent Building

Irregularities: Vertical (type/severity) Vertical set-back
 Plan (type)

Exterior Falling Hazards: Unbraced Chimneys Heavy Cladding or Heavy Veneer
 Parapets Appendages
 Other: Brick veneer

610.021(20)

COMMENTS:
- URM CMU Brg wall system
- Tectum roof system over STL bar joists
- Auto mechanics is now child care
- Power mechanics is now screen printing shop
- AG is now culinary arts

Additional sketches or comments on separate page

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE, S_{L1}

FEMA BUILDING TYPE	Do Not Know	W1	W1A	W2	S1 (MRF)	S2 (BR)	S3 (LM)	S4 (RC SW)	S5 (URM INF)	C1 (MRF)	C2 (SW)	C3 (URM INF)	PC1 (TU)	PC2	RM1 (FD)	RM2 (RD)	URM	MH
Basic Score		2.1	1.9	1.8	1.5	1.4	1.6	1.4	1.2	1.0	1.2	0.9	1.1	1.0	1.1	1.1	0.9	1.1
Severe Vertical Irregularity, V _{L1}		-0.9	-0.9	-0.9	-0.8	-0.7	-0.8	-0.7	-0.7	-0.7	-0.8	-0.6	-0.7	-0.7	-0.7	-0.7	-0.6	NA
Moderate Vertical Irregularity, V _{L1}		-0.6	-0.5	-0.5	-0.4	-0.4	-0.5	-0.4	-0.3	-0.4	-0.4	-0.3	-0.4	-0.4	-0.4	-0.4	-0.3	NA
Plan Irregularity, P _{L1}		-0.7	-0.7	-0.6	-0.5	-0.5	-0.6	-0.4	-0.4	-0.4	-0.5	-0.3	-0.5	-0.4	-0.4	-0.4	-0.3	NA
Pre-Code		-0.3	-0.3	-0.3	-0.3	-0.2	-0.3	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	0.0
Post-Benchmark		1.9	1.9	2.0	1.0	1.1	1.1	1.5	NA	1.4	1.7	NA	1.5	1.7	1.6	1.6	NA	0.5
Soil Type A or B		0.5	0.5	0.4	0.3	0.3	0.4	0.3	0.2	0.2	0.3	0.1	0.3	0.2	0.3	0.3	0.1	0.1
Soil Type E (1-3 stories)		0.0	-0.2	-0.4	-0.3	-0.2	-0.2	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	-0.1
Soil Type E (> 3 stories)		-0.4	-0.4	-0.4	-0.3	-0.3	NA	-0.3	-0.1	-0.1	-0.3	-0.1	NA	-0.1	-0.2	-0.2	0.0	NA
Minimum Score, S _{MIN}		0.7	0.7	0.7	0.5	0.5	0.5	0.5	0.5	0.3	0.3	0.3	0.2	0.2	0.3	0.3	0.2	1.0

FINAL LEVEL 1 SCORE, S_{L1} ≥ S_{MIN}: **0.3**

<p>EXTENT OF REVIEW</p> <p>Exterior: <input type="checkbox"/> Partial <input checked="" type="checkbox"/> All Sides <input type="checkbox"/> Aerial Interior: <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered Drawings Reviewed: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Soil Type Source: Vs30 Geologic Hazards Source: Regional Data Contact Person: Mike Brown</p> <p>LEVEL 2 SCREENING PERFORMED?</p> <p><input checked="" type="checkbox"/> Yes, Final Level 2 Score, S_{L2} 0.9 <input type="checkbox"/> No Nonstructural hazards? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p>	<p>OTHER HAZARDS</p> <p>Are There Hazards That Trigger A Detailed Structural Evaluation?</p> <p><input type="checkbox"/> Pounding potential (unless S_{L2} > cut-off, if known) <input type="checkbox"/> Falling hazards from taller adjacent building <input type="checkbox"/> Geologic hazards or Soil Type F <input type="checkbox"/> Significant damage/deterioration to the structural system</p>	<p>ACTION REQUIRED</p> <p>Detailed Structural Evaluation Required?</p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building <input checked="" type="checkbox"/> Yes, score less than cut-off <input type="checkbox"/> Yes, other hazards present <input type="checkbox"/> No</p> <p>Detailed Nonstructural Evaluation Recommended? (check one)</p> <p><input checked="" type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated <input type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary <input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p>
---	--	---

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Rapid Visual Screening of Buildings for Potential Seismic Hazards

FEMA P-154 Data Collection Form

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

Level 2 (Optional)
VERY HIGH Seismicity

Bldg Name: Sikeston High School – Building H	Final Level 1 Score: $S_{L1} = 0.3$	<i>(do not consider S_{MIN})</i>	
Screener: M. Griffin/B. Smith	Level 1 Irregularity Modifiers:	Vertical Irregularity, $V_{L1} = -0.6$	Plan Irregularity, $P_{L1} = 0$
Date/Time: 9-11-15/	ADJUSTED BASELINE SCORE:	$S' = (S_{L1} - V_{L1} - P_{L1}) = 0.9$	

STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

Topic	Statement (If statement is true, circle the "Yes" modifier, otherwise cross out the modifier.)	Yes	Subtotals
Vertical Irregularity, V_{L2}	Sloping Site	W1 building: There is at least a full story grade change from one side of the building to the other.	-0.9
		Non-W1 building: There is at least a full story grade change from one side of the building to the other.	-0.2
	Weak and/or Soft Story (circle one maximum)	W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.	-0.5
		W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum).	-0.9
		W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.	-0.9
		Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.	-0.7
		Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.	-0.4
	Setback	Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.	-0.7
		Vertical elements of the lateral system at upper stories are inboard of those at lower stories.	-0.4
		There is an in-plane offset of the lateral elements that is greater than the length of the elements.	-0.2
	Short Column/ Pier	C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.	-0.4
		C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.	-0.4
Split Level	There is a split level at one of the floor levels or at the roof.	-0.4	
Other Irregularity	There is another observable severe vertical irregularity that obviously affects the building's seismic performance.	-0.7	
	There is another observable moderate vertical irregularity that may affect the building's seismic performance.	-0.4	
Plan Irregularity, P_{L2}	Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.)	-0.5	
	Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.	-0.2	
	Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.	-0.2	
	Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.	-0.2	
	C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.	-0.2	
	Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.	-0.5	
Redundancy	The building has at least two bays of lateral elements on each side of the building in each direction.		+0.2
Pounding	Building is separated from an adjacent structure by less than 1.5% of the height of the shorter of the building and adjacent structure and:	The floors do not align vertically within 2 feet.	(Cap total pounding modifiers at -0.9)
		One building is 2 or more stories taller than the other.	-0.7
		The building is at the end of the block.	-0.4
S2 Building	"K" bracing geometry is visible.		-0.7
C1 Building	Flat plate serves as the beam in the moment frame.		-0.3
PC1/RM1 Bldg	There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)		+0.2
PC1/RM1 Bldg	The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).		+0.2
URM	Gable walls are present.		-0.3
MH	There is a supplemental seismic bracing system provided between the carriage and the ground.		+0.5
Retrofit	Comprehensive seismic retrofit is visible or known from drawings.		+1.2
FINAL LEVEL 2 SCORE, $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$:			0.9 <i>(Transfer to Level 1 form)</i>
There is observable damage or deterioration or another condition that negatively affects the building's seismic performance: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.			

FINAL LEVEL 2 SCORE, $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$: 0.9 *(Transfer to Level 1 form)*

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance: Yes No
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

OBSERVABLE NONSTRUCTURAL HAZARDS

Location	Statement (Check "Yes" or "No")	Yes	No	Comment
Exterior	There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.		X	
	There is heavy cladding or heavy veneer.	X		Brick veneer
	There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported.		X	
	There is an unreinforced masonry appendage over exit doors or pedestrian walkways.		X	
	There is a sign posted on the building that indicates hazardous materials are present.		X	
	There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney.		X	
	Other observed exterior nonstructural falling hazard:		X	
Interior	There are hollow clay tile or brick partitions at any stair or exit corridor.	X		Partitions
	Other observed interior nonstructural falling hazard:	X		Minor contents

Estimated Nonstructural Seismic Performance (Check appropriate box and transfer to Level 1 form conclusions)

Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended

Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required

Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

Comments: Hard drywall ceilings & suspended. Tall URM CMU partition walls. Questionable girder end connection to Brg wall. Inadequate gas bottle chain Supts.



Address: 200 Pine Street
Sikeston, MO Zip: 63801

Other Identifiers: Sikeston R-6 District

Building Name: Sikeston Senior High School - Building I

Use: K-12 School

Latitude: 36.879228 Longitude: -89.572154

Ss: 2.445g S: 0.908g

Screener(s): M. Griffin/B. Smith Date/Time: 9-11-15/

No. Stories: Above Grade: 1 Below Grade: 0 Year Built: 1969 EST

Total Floor Area (sq. ft.): 9,798 Code Year: Unknown

Additions: None Yes, Year(s) Built: _____

Occupancy: Assembly Commercial Emer. Services Historic Shelter
Industrial Office School Government
Utility Warehouse Residential, # Units: _____

Soil Type: A B C D E F DNK
Hard Avg Dense Stiff Soft Poor DNK
Rock Rock Soil Soil Soil Soil If DNK, assume Type D.

Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf Rupt: Yes/No/DNK

Adjacency: Pounding Falling Hazards from Taller Adjacent Building

Irregularities: Vertical (type/severity) _____
 Plan (type) Re-entrant corner

Exterior Falling Hazards: Unbraced Chimneys Heavy Cladding or Heavy Veneer
 Parapets Appendages
 Other: Brick veneer

610.021(20)

COMMENTS:

- Tectum roof over bar joists & Steel girders to CMU Bearing walls
- Very little interior walls
- Auto & carpentry trades
- Minor contents & equipment hung overhead issues

Additional sketches or comments on separate page

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE, S_{L1}

FEMA BUILDING TYPE	Do Not Know	W1	W1A	W2	S1 (MRF)	S2 (BR)	S3 (LM)	S4 (RC SW)	S5 (URM INF)	C1 (MRF)	C2 (SW)	C3 (URM INF)	PC1 (TU)	PC2	RM1 (FD)	RM2 (RD)	URM	MH
Basic Score		2.1	1.9	1.8	1.5	1.4	1.6	1.4	1.2	1.0	1.2	0.9	1.1	1.0	1.1	1.1	0.9	1.1
Severe Vertical Irregularity, V _{L1}		-0.9	-0.9	-0.9	-0.8	-0.7	-0.8	-0.7	-0.7	-0.7	-0.8	-0.6	-0.7	-0.7	-0.7	-0.7	-0.6	NA
Moderate Vertical Irregularity, V _{L1}		-0.6	-0.5	-0.5	-0.4	-0.4	-0.5	-0.4	-0.3	-0.4	-0.4	-0.3	-0.4	-0.4	-0.4	-0.4	-0.3	NA
Plan Irregularity, P _{L1}		-0.7	-0.7	-0.6	-0.5	-0.5	-0.6	-0.4	-0.4	-0.4	-0.5	-0.3	-0.5	-0.4	-0.4	-0.4	-0.3	NA
Pre-Code		-0.3	-0.3	-0.3	-0.3	-0.2	-0.3	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	0.0
Post-Benchmark		1.9	1.9	2.0	1.0	1.1	1.1	1.5	NA	1.4	1.7	NA	1.5	1.7	1.6	1.6	NA	0.5
Soil Type A or B		0.5	0.5	0.4	0.3	0.3	0.4	0.3	0.2	0.2	0.3	0.1	0.3	0.2	0.3	0.3	0.1	0.1
Soil Type E (1-3 stories)		0.0	-0.2	-0.4	-0.3	-0.2	-0.2	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	-0.1
Soil Type E (> 3 stories)		-0.4	-0.4	-0.4	-0.3	-0.3	NA	-0.3	-0.1	-0.1	-0.3	-0.1	NA	-0.1	-0.2	-0.2	0.0	NA
Minimum Score, S _{MIN}		0.7	0.7	0.7	0.5	0.5	0.5	0.5	0.5	0.3	0.3	0.3	0.2	0.2	0.3	0.3	0.2	1.0

FINAL LEVEL 1 SCORE, S_{L1} ≥ S_{MIN}: 0.6

EXTENT OF REVIEW

Exterior: Partial All Sides Aerial
Interior: None Visible Entered
Drawings Reviewed: Yes No
Soil Type Source: Vs30
Geologic Hazards Source: Regional data
Contact Person: Mike Brown

LEVEL 2 SCREENING PERFORMED?

Yes, Final Level 2 Score, S_{L2} 0.9 No
Nonstructural hazards? Yes No

OTHER HAZARDS

Are There Hazards That Trigger A Detailed Structural Evaluation?

Pounding potential (unless S_{L2} > cut-off, if known)
 Falling hazards from taller adjacent building
 Geologic hazards or Soil Type F
 Significant damage/deterioration to the structural system

ACTION REQUIRED

Detailed Structural Evaluation Required?

Yes, unknown FEMA building type or other building
 Yes, score less than cut-off
 Yes, other hazards present
 No

Detailed Nonstructural Evaluation Recommended? (check one)

Yes, nonstructural hazards identified that should be evaluated
 No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary
 No, no nonstructural hazards identified DNK

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Rapid Visual Screening of Buildings for Potential Seismic Hazards

FEMA P-154 Data Collection Form

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

Level 2 (Optional)
VERY HIGH Seismicity

Bldg Name: Sikeston High School – Building I	Final Level 1 Score: $S_{L1} = 0.6$	<i>(do not consider S_{MIN})</i>	
Screener: M. Griffin/B. Smith	Level 1 Irregularity Modifiers:	Vertical Irregularity, $V_{L1} = 0$	Plan Irregularity, $P_{L1} = -0.3$
Date/Time: 9-11-15/	ADJUSTED BASELINE SCORE:	$S' = (S_{L1} - V_{L1} - P_{L1}) = 0.9$	

STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

Topic	Statement (If statement is true, circle the "Yes" modifier, otherwise cross out the modifier.)	Yes	Subtotals
Vertical Irregularity, V_{L2}	Sloping Site	W1 building: There is at least a full story grade change from one side of the building to the other.	-0.9
		Non-W1 building: There is at least a full story grade change from one side of the building to the other.	-0.2
	Weak and/or Soft Story (circle one maximum)	W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.	-0.5
		W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum).	-0.9
		W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.	-0.9
		Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.	-0.7
		Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.	-0.4
	Setback	Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.	-0.7
		Vertical elements of the lateral system at upper stories are inboard of those at lower stories.	-0.4
		There is an in-plane offset of the lateral elements that is greater than the length of the elements.	-0.2
	Short Column/ Pier	C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.	-0.4
		C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.	-0.4
	Split Level	There is a split level at one of the floor levels or at the roof.	-0.4
Other Irregularity	There is another observable severe vertical irregularity that obviously affects the building's seismic performance.	-0.7	
	There is another observable moderate vertical irregularity that may affect the building's seismic performance.	-0.4	
Plan Irregularity, P_{L2}	Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.)	-0.5	
	Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.	-0.2	
	Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.	-0.2	
	Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.	-0.2	
	C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.	-0.2	
	Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.	-0.5	
Redundancy	The building has at least two bays of lateral elements on each side of the building in each direction.	+0.2	
Pounding	Building is separated from an adjacent structure by less than 1.5% of the height of the shorter of the building and adjacent structure and:	The floors do not align vertically within 2 feet.	-0.7
		One building is 2 or more stories taller than the other.	-0.7
		The building is at the end of the block.	-0.4
S2 Building	"K" bracing geometry is visible.	-0.7	
C1 Building	Flat plate serves as the beam in the moment frame.	-0.3	
PC1/RM1 Bldg	There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)	+0.2	
PC1/RM1 Bldg	The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).	+0.2	
URM	Gable walls are present.	-0.3	
MH	There is a supplemental seismic bracing system provided between the carriage and the ground.	+0.5	
Retrofit	Comprehensive seismic retrofit is visible or known from drawings.	+1.2	
FINAL LEVEL 2 SCORE, $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$:			0.9
			<i>(Transfer to Level 1 form)</i>

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance: Yes No
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

OBSERVABLE NONSTRUCTURAL HAZARDS

Location	Statement (Check "Yes" or "No")	Yes	No	Comment
Exterior	There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.		X	
	There is heavy cladding or heavy veneer.	X		Brick veneer
	There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported.		X	
	There is an unreinforced masonry appendage over exit doors or pedestrian walkways.		X	
	There is a sign posted on the building that indicates hazardous materials are present.		X	
	There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney.		X	
	Other observed exterior nonstructural falling hazard:		X	
Interior	There are hollow clay tile or brick partitions at any stair or exit corridor.	X		Minimal interior CMU
	Other observed interior nonstructural falling hazard:	X		Overhead fans with no bracing

Estimated Nonstructural Seismic Performance (Check appropriate box and transfer to Level 1 form conclusions)
 Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended
 Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required
 Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

Comments: Overhead HVAC units without bracing. CMU partition walls unreinforced. Parts storage shelving unrestrained.



Address: 200 Pine Street
Sikeston, MO Zip: 63801

Other Identifiers: Sikeston R-6 District

Building Name: Sikeston Senior High School - Field House

Use: K-12 School

Latitude: 36.879228 Longitude: -89.572154

Ss: 2.445g S_r: 0.908g

Screener(s): M. Griffin/B. Smith Date/Time: 9-11-15/

No. Stories: Above Grade: 1 Below Grade: 0 Year Built: 1969 EST

Total Floor Area (sq. ft.): 5 5116 Code Year: Unknown

Additions: None Yes, Year(s) Built: _____

Occupancy: Assembly Commercial Emer. Services Historic Shelter
Industrial Office School Government
Utility Warehouse Residential, # Units: _____

Soil Type: A B C D E F DNK
Hard Avg Dense Stiff Soft Poor DNK
Rock Rock Soil Soil Soil Soil If DNK, assume Type D.

Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf Rupt: Yes/No/DNK

Adjacency: Pounding Falling Hazards from Taller Adjacent Building

Irregularities: Vertical (type/severity) Vertical set-back _____
 Plan (type) _____

Exterior Falling Hazards: Unbraced Chimneys Heavy Cladding or Heavy Veneer
 Parapets Appendages
 Other: _____ Brick veneer

610.021(20)

COMMENTS:

- Concrete frame @ interior
- Perimeter sections are steel bar joists and URM CMU walls
- Tectum roof system
- Boilers unattached
- Chiller unattached
- CMU partitions have no OOP bracing
- Exterior transformer and cooling towers anchored

Additional sketches or comments on separate page

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE, S_{L1}

FEMA BUILDING TYPE	Do Not Know	W1	W1A	W2	S1 (MRF)	S2 (BR)	S3 (LM)	S4 (RC SW)	S5 (URM INF)	C1 (MRF)	C2 (SW)	C3 (URM INF)	PC1 (TU)	PC2	RM1 (FD)	RM2 (RD)	URM	MH
Basic Score		2.1	1.9	1.8	1.5	1.4	1.6	1.4	1.2	1.0	1.2	0.9	1.1	1.0	1.1	1.1	0.9	1.1
Severe Vertical Irregularity, V _{L1}		-0.9	-0.9	-0.9	-0.8	-0.7	-0.8	-0.7	-0.7	-0.7	-0.8	-0.6	-0.7	-0.7	-0.7	-0.7	-0.6	NA
Moderate Vertical Irregularity, V _{L2}		-0.6	-0.5	-0.5	-0.4	-0.4	-0.5	-0.4	-0.3	-0.4	-0.4	-0.3	-0.4	-0.4	-0.4	-0.4	-0.3	NA
Plan Irregularity, P _{L1}		-0.7	-0.7	-0.6	-0.5	-0.5	-0.6	-0.4	-0.4	-0.4	-0.5	-0.3	-0.5	-0.4	-0.4	-0.4	-0.3	NA
Pre-Code		-0.3	-0.3	-0.3	-0.3	-0.2	-0.3	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	0.0
Post-Benchmark		1.9	1.9	2.0	1.0	1.1	1.1	1.5	NA	1.4	1.7	NA	1.5	1.7	1.6	1.6	NA	0.5
Soil Type A or B		0.5	0.5	0.4	0.3	0.3	0.4	0.3	0.2	0.2	0.3	0.1	0.3	0.2	0.3	0.3	0.1	0.1
Soil Type E (1-3 stories)		0.0	-0.2	-0.4	-0.3	-0.2	-0.2	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	-0.1
Soil Type E (> 3 stories)		-0.4	-0.4	-0.4	-0.3	-0.3	NA	-0.3	-0.1	-0.1	-0.3	-0.1	NA	-0.1	-0.2	-0.2	0.0	NA
Minimum Score, S _{MIN}		0.7	0.7	0.7	0.5	0.5	0.5	0.5	0.5	0.3	0.3	0.3	0.2	0.2	0.3	0.3	0.2	1.0

FINAL LEVEL 1 SCORE, S_{L1} ≥ S_{MIN}: 0.3 0.3

<p>EXTENT OF REVIEW</p> <p>Exterior: <input type="checkbox"/> Partial <input checked="" type="checkbox"/> All Sides <input type="checkbox"/> Aerial Interior: <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered</p> <p>Drawings Reviewed: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p> <p>Soil Type Source: Vs30</p> <p>Geologic Hazards Source: Regional data</p> <p>Contact Person: Mike Brown</p>	<p>OTHER HAZARDS</p> <p>Are There Hazards That Trigger A Detailed Structural Evaluation?</p> <p><input type="checkbox"/> Pounding potential (unless S_{L2} > cut-off, if known)</p> <p><input type="checkbox"/> Falling hazards from taller adjacent building</p> <p><input type="checkbox"/> Geologic hazards or Soil Type F</p> <p><input type="checkbox"/> Significant damage/deterioration to the structural system</p>	<p>ACTION REQUIRED</p> <p>Detailed Structural Evaluation Required?</p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building</p> <p><input checked="" type="checkbox"/> Yes, score less than cut-off</p> <p><input type="checkbox"/> Yes, other hazards present</p> <p><input type="checkbox"/> No</p> <p>Detailed Nonstructural Evaluation Recommended? (check one)</p> <p><input checked="" type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated</p> <p><input type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary</p> <p><input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p>
<p>LEVEL 2 SCREENING PERFORMED?</p> <p><input checked="" type="checkbox"/> Yes, Final Level 2 Score, S_{L2} 0.9 <input type="checkbox"/> No</p> <p>Nonstructural hazards? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p>		

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Rapid Visual Screening of Buildings for Potential Seismic Hazards

FEMA P-154 Data Collection Form

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

Level 2 (Optional)
VERY HIGH Seismicity

Bldg Name: Sikeston High School – Field House	Final Level 1 Score: $S_{L1} = 0.3$ (C3)	<i>(do not consider S_{MIN})</i>	
Screener: M. Griffin/B. Smith	Level 1 Irregularity Modifiers:	Vertical Irregularity, $V_{L1} = -0.6$	Plan Irregularity, $P_{L1} = 0$
Date/Time: 9-11-15/	ADJUSTED BASELINE SCORE:	$S' = (S_{L1} - V_{L1} - P_{L1}) = 0.9$	

STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

Topic	Statement (If statement is true, circle the "Yes" modifier, otherwise cross out the modifier.)	Yes	Subtotals
Vertical Irregularity, V_{L2}	Sloping Site	W1 building: There is at least a full story grade change from one side of the building to the other.	-0.9
		Non-W1 building: There is at least a full story grade change from one side of the building to the other.	-0.2
	Weak and/or Soft Story (circle one maximum)	W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.	-0.5
		W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum).	-0.9
		W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.	-0.9
		Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.	-0.7
		Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.	-0.4
	Setback	Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.	-0.7
		Vertical elements of the lateral system at upper stories are inboard of those at lower stories.	-0.4
		There is an in-plane offset of the lateral elements that is greater than the length of the elements.	-0.2
	Short Column/ Pier	C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.	-0.4
		C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.	-0.4
	Split Level	There is a split level at one of the floor levels or at the roof.	-0.4
	Other Irregularity	There is another observable severe vertical irregularity that obviously affects the building's seismic performance.	-0.7
There is another observable moderate vertical irregularity that may affect the building's seismic performance.		-0.4	
Plan Irregularity, P_{L2}	Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.)	-0.5	
	Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.	-0.2	
	Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.	-0.2	
	Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.	-0.2	
	C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.	-0.2	
	Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.	-0.5	
Redundancy	The building has at least two bays of lateral elements on each side of the building in each direction.	+0.2	
Pounding	Building is separated from an adjacent structure by less than 1.5% of the height of the shorter of the building and adjacent structure and:	The floors do not align vertically within 2 feet.	-0.7
		One building is 2 or more stories taller than the other.	-0.7
		The building is at the end of the block.	-0.4
S2 Building	"K" bracing geometry is visible.	-0.7	
C1 Building	Flat plate serves as the beam in the moment frame.	-0.3	
PC1/RM1 Bldg	There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)	+0.2	
PC1/RM1 Bldg	The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).	+0.2	
URM	Gable walls are present.	-0.3	
MH	There is a supplemental seismic bracing system provided between the carriage and the ground.	+0.5	
Retrofit	Comprehensive seismic retrofit is visible or known from drawings.	+1.2	
			$V_{L2} = 0.0$ (Cap at -0.9)
			$P_{L2} = 0.0$ (Cap at -0.7)
			$M = 0.0$

FINAL LEVEL 2 SCORE, $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$: 0.9 *(Transfer to Level 1 form)*

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance: Yes No
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

OBSERVABLE NONSTRUCTURAL HAZARDS

Location	Statement (Check "Yes" or "No")	Yes	No	Comment
Exterior	There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.		X	
	There is heavy cladding or heavy veneer.	X		Brick veneer
	There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported.		X	
	There is an unreinforced masonry appendage over exit doors or pedestrian walkways.		X	
	There is a sign posted on the building that indicates hazardous materials are present.		X	
	There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney.		X	
	Other observed exterior nonstructural falling hazard:		X	
Interior	There are hollow clay tile or brick partitions at any stair or exit corridor.	X		CMU interior partitions
	Other observed interior nonstructural falling hazard:	X		Overhead lights, banners etc.

Estimated Nonstructural Seismic Performance (Check appropriate box and transfer to Level 1 form conclusions)
 Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended
 Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required
 Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

Comments: Overhead suspended lights & duct unbraced. Interior CMU partition walls unbraced, some very tall in arena.

Rapid Visual Screening of Buildings for Potential Seismic Hazards

FEMA P-154 Data Collection Form

Level 1
VERY HIGH Seismicity



Address: 200 Pine Street
Sikeston, MO Zip: 63801

Other Identifiers: Sikeston R-6 District

Building Name: Sikeston Senior High School – Math/Science

Use: K-12 School

Latitude: 36.879228 Longitude: -89.572154

Ss: 2.445g Sr: 0.908g

Screener(s): M. Griffin/B. Smith Date/Time: 9-11-15/

No. Stories: Above Grade: 1 Below Grade: 0 Year Built: 2007 EST

Total Floor Area (sq. ft.): 33,089 Code Year: 2003 IBC

Additions: None Yes, Year(s) Built: _____

Occupancy: Assembly Commercial Emer. Services Historic Shelter
 Industrial Office School Government
 Utility Warehouse Residential, # Units: _____

Soil Type: A B C D E F DNK
 Hard Avg Dense Stiff Soft Poor DNK
 Rock Rock Soil Soil Soil Soil If DNK, assume Type D.

Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK


Adjacency: Pounding Falling Hazards from Taller Adjacent Building

Irregularities: Vertical (type/severity) NONE
 Plan (type) NONE

Exterior Falling Hazards: Unbraced Chimneys Heavy Cladding or Heavy Veneer
 Parapets Appendages
 Other: Brick veneer

COMMENTS:
 - 2003 IBC
 - SE; Tahiliani Assoc., Memphis TN
 - Seismic '96 BOCA
 $A_v = 0.280$ $A_a = 0.264$
 Sheg = Group 1 ; SPC = D
 Soil type = S2
 Concentric steel braced frame
 Brace gussets detailed per buckling criteria

Additional sketches or comments on separate page



SKETCH

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE, S_{L1}

FEMA BUILDING TYPE	Do Not Know	W1	W1A	W2	S1 (MRF)	S2 (BR)	S3 (LM)	S4 (RC SW)	S5 (URM INF)	C1 (MRF)	C2 (SW)	C3 (URM INF)	PC1 (TU)	PC2	RM1 (FD)	RM2 (RD)	URM	MH
Basic Score		2.1	1.9	1.8	1.5	1.4	1.6	1.4	1.2	1.0	1.2	0.9	1.1	1.0	1.1	1.1	0.9	1.1
Severe Vertical Irregularity, V_{L1}		-0.9	-0.9	-0.9	-0.8	-0.7	-0.8	-0.7	-0.7	-0.7	-0.8	-0.6	-0.7	-0.7	-0.7	-0.7	-0.6	NA
Moderate Vertical Irregularity, V_{L1}		-0.6	-0.5	-0.5	-0.4	-0.4	-0.5	-0.4	-0.3	-0.4	-0.4	-0.3	-0.4	-0.4	-0.4	-0.4	-0.3	NA
Plan Irregularity, P_{L1}		-0.7	-0.7	-0.6	-0.5	-0.5	-0.6	-0.4	-0.4	-0.4	-0.5	-0.3	-0.5	-0.4	-0.4	-0.4	-0.3	NA
Pre-Code		-0.3	-0.3	-0.3	-0.3	-0.2	-0.3	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	0.0
Post-Benchmark		1.9	1.9	2.0	1.0	1.1	1.1	1.5	NA	1.4	1.7	NA	1.5	1.7	1.6	1.6	NA	0.5
Soil Type A or B		0.5	0.5	0.4	0.3	0.3	0.4	0.3	0.2	0.2	0.3	0.1	0.3	0.2	0.3	0.3	0.1	0.1
Soil Type E (1-3 stories)		0.0	-0.2	-0.4	-0.3	-0.2	-0.2	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	-0.1
Soil Type E (> 3 stories)		-0.4	-0.4	-0.4	-0.3	-0.3	NA	-0.3	-0.1	-0.1	-0.3	-0.1	NA	-0.1	-0.2	-0.2	0.0	NA
Minimum Score, S_{MIN}		0.7	0.7	0.7	0.5	0.5	0.5	0.5	0.5	0.3	0.3	0.3	0.2	0.2	0.3	0.3	0.2	1.0

FINAL LEVEL 1 SCORE, $S_{L1} \geq S_{MIN}$: **2.5**

EXTENT OF REVIEW

Exterior: Partial All Sides Aerial
 Interior: None Visible Entered
 Drawings Reviewed: Yes No
 Soil Type Source: S2 - Drawings
 Geologic Hazards Source: Regional data
 Contact Person: Mike Brown

OTHER HAZARDS

Are There Hazards That Trigger A Detailed Structural Evaluation?

Pounding potential (unless $S_{L2} >$ cut-off, if known)
 Falling hazards from taller adjacent building
 Geologic hazards or Soil Type F
 Significant damage/deterioration to the structural system

ACTION REQUIRED

Detailed Structural Evaluation Required?

Yes, unknown FEMA building type or other building
 Yes, score less than cut-off
 Yes, other hazards present
 No

Detailed Nonstructural Evaluation Recommended? (check one)

Yes, nonstructural hazards identified that should be evaluated
 No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary
 No, no nonstructural hazards identified DNK

LEVEL 2 SCREENING PERFORMED?

Yes, Final Level 2 Score, S_{L2} 2.7 No
 Nonstructural hazards? Yes No

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Legend: MRF = Moment-resisting frame RC = Reinforced concrete URM INF = Unreinforced masonry infill MH = Manufactured Housing FD = Flexible diaphragm
 BR = Braced frame SW = Shear wall TU = Tilt up LM = Light metal RD = Rigid diaphragm

Rapid Visual Screening of Buildings for Potential Seismic Hazards

FEMA P-154 Data Collection Form

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

Level 2 (Optional)
VERY HIGH Seismicity

Bldg Name: Sikeston High School-Math/Science	Final Level 1 Score: $S_{L1} = 2.5$	<i>(do not consider S_{MIN})</i>	
Screener: M. Griffin/B. Smith	Level 1 Irregularity Modifiers:	Vertical Irregularity, $V_{L1} = 0$	Plan Irregularity, $P_{L1} = 0$
Date/Time: 9-11-15/	ADJUSTED BASELINE SCORE:	$S' = (S_{L1} - V_{L1} - P_{L1}) = 2.5$	

STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

Topic	Statement (If statement is true, circle the "Yes" modifier, otherwise cross out the modifier.)	Yes	Subtotals
Vertical Irregularity, V_{L2}	Sloping Site	W1 building: There is at least a full story grade change from one side of the building to the other.	-0.9
		Non-W1 building: There is at least a full story grade change from one side of the building to the other.	-0.2
	Weak and/or Soft Story (circle one maximum)	W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.	-0.5
		W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum).	-0.9
		W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.	-0.9
		Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.	-0.7
		Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.	-0.4
	Setback	Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.	-0.7
		Vertical elements of the lateral system at upper stories are inboard of those at lower stories.	-0.4
		There is an in-plane offset of the lateral elements that is greater than the length of the elements.	-0.2
	Short Column/Pier	C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.	-0.4
		C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.	-0.4
	Split Level	There is a split level at one of the floor levels or at the roof.	-0.4
	Other Irregularity	There is another observable severe vertical irregularity that obviously affects the building's seismic performance.	-0.7
There is another observable moderate vertical irregularity that may affect the building's seismic performance.		-0.4	
Plan Irregularity, P_{L2}	Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.)	-0.5	
	Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.	-0.2	
	Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.	-0.2	
	Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.	-0.2	
	C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.	-0.2	
	Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.	-0.5	
Redundancy	The building has at least two bays of lateral elements on each side of the building in each direction.	+0.2	
Pounding	Building is separated from an adjacent structure by less than 1.5% of the height of the shorter of the building and adjacent structure and:	The floors do not align vertically within 2 feet.	-0.7
		One building is 2 or more stories taller than the other.	-0.7
		The building is at the end of the block.	-0.4
S2 Building	"K" bracing geometry is visible.	-0.7	
C1 Building	Flat plate serves as the beam in the moment frame.	-0.3	
PC1/RM1 Bldg	There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)	+0.2	
PC1/RM1 Bldg	The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).	+0.2	
URM	Gable walls are present.	-0.3	
MH	There is a supplemental seismic bracing system provided between the carriage and the ground.	+0.5	
Retrofit	Comprehensive seismic retrofit is visible or known from drawings.	+1.2	
FINAL LEVEL 2 SCORE, $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$:			2.7
			<i>(Transfer to Level 1 form)</i>

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance: Yes No
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

OBSERVABLE NONSTRUCTURAL HAZARDS

Location	Statement (Check "Yes" or "No")	Yes	No	Comment
Exterior	There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.		X	
	There is heavy cladding or heavy veneer.	X		Brick veneer
	There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported.		X	
	There is an unreinforced masonry appendage over exit doors or pedestrian walkways.		X	
	There is a sign posted on the building that indicates hazardous materials are present.		X	
	There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney.		X	
	Other observed exterior nonstructural falling hazard:		X	
Interior	There are hollow clay tile or brick partitions at any stair or exit corridor.		X	
	Other observed interior nonstructural falling hazard:		X	

Estimated Nonstructural Seismic Performance (Check appropriate box and transfer to Level 1 form conclusions)
 Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended
 Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required
 Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

Comments: Lights safe-tied. Ceiling unbraced. Metal stud partition walls full height. Sprinkler braces attached to bottom of joist chords OOP. Chemical shelves restrained.



Address: 200 Pine Street
Sikeston, MO Zip: 63801

Other Identifiers: Sikeston R-6 District

Building Name: Sikeston Senior High School - Bus Garage

Use: Vehicle Repair

Latitude: 36.879228 Longitude: -89.572154

Ss: 2.445g S: 0.908g

Screeener(s): M. Griffin/ B. Smith Date/Time: 9-11-15/

No. Stories: Above Grade: 1 Below Grade: 0 Year Built: 1980 EST

Total Floor Area (sq. ft.): 3,900 Code Year: Unknown

Additions: None Yes, Year(s) Built: _____

Occupancy: Assembly Commercial Emer. Services Historic Shelter
Industrial Office School Government
Utility Warehouse Residential, # Units: _____


Soil Type: A B C D E F DNK
Hard Avg Dense Stiff Soft Poor DNK
Rock Rock Soil Soil Soil Soil *If DNK, assume Type D.*

Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

Adjacency: Pounding Falling Hazards from Taller Adjacent Building

Irregularities: Vertical (type/severity) NONE
 Plan (type) NONE

Exterior Falling Hazards: Unbraced Chimneys Heavy Cladding or Heavy Veneer
 Parapets Appendages
 Other: _____



COMMENTS:
- Built-up truss beam/column frames. Old style pre-engineered building system.

Additional sketches or comments on separate page

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE, S_{L1}

FEMA BUILDING TYPE	Do Not Know	W1	W1A	W2	S1 (MRF)	S2 (BR)	S3 (LM)	S4 (RC SW)	S5 (URM INF)	C1 (MRF)	C2 (SW)	C3 (URM INF)	PC1 (TU)	PC2	RM1 (FD)	RM2 (RD)	URM	MH
Basic Score		2.1	1.9	1.8	1.5	1.4	1.6	1.4	1.2	1.0	1.2	0.9	1.1	1.0	1.1	1.1	0.9	1.1
Severe Vertical Irregularity, V_{L1}		-0.9	-0.9	-0.9	-0.8	-0.7	-0.8	-0.7	-0.7	-0.7	-0.8	-0.6	-0.7	-0.7	-0.7	-0.7	-0.6	NA
Moderate Vertical Irregularity, V_{L1}		-0.6	-0.5	-0.5	-0.4	-0.4	-0.5	-0.4	-0.3	-0.4	-0.4	-0.3	-0.4	-0.4	-0.4	-0.4	-0.3	NA
Plan Irregularity, P_{L1}		-0.7	-0.7	-0.6	-0.5	-0.5	-0.6	-0.4	-0.4	-0.4	-0.5	-0.3	-0.5	-0.4	-0.4	-0.4	-0.3	NA
Pre-Code		-0.3	-0.3	-0.3	-0.3	-0.2	-0.3	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	0.0
Post-Benchmark		1.9	1.9	2.0	1.0	1.1	1.1	1.5	NA	1.4	1.7	NA	1.5	1.7	1.6	1.6	NA	0.5
Soil Type A or B		0.5	0.5	0.4	0.3	0.3	0.4	0.3	0.2	0.2	0.3	0.1	0.3	0.2	0.3	0.3	0.1	0.1
Soil Type E (1-3 stories)		0.0	-0.2	-0.4	-0.3	-0.2	-0.2	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	-0.1
Soil Type E (> 3 stories)		-0.4	-0.4	-0.4	-0.3	-0.3	NA	-0.3	-0.1	-0.1	-0.3	-0.1	NA	-0.1	-0.2	-0.2	0.0	NA
Minimum Score, S_{MIN}		0.7	0.7	0.7	0.5	0.5	0.5	0.5	0.5	0.3	0.3	0.3	0.2	0.2	0.3	0.3	0.2	1.0

FINAL LEVEL 1 SCORE, $S_{L1} \geq S_{MIN}$: **1.3**

<p>EXTENT OF REVIEW</p> <p>Exterior: <input type="checkbox"/> Partial <input checked="" type="checkbox"/> All Sides <input type="checkbox"/> Aerial Interior: <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered</p> <p>Drawings Reviewed: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p> <p>Soil Type Source: Vs30</p> <p>Geologic Hazards Source: Regional data</p> <p>Contact Person: Mike Brown</p> <hr/> <p>LEVEL 2 SCREENING PERFORMED?</p> <p><input checked="" type="checkbox"/> Yes, Final Level 2 Score, S_{L2} 1.3 <input type="checkbox"/> No</p> <p>Nonstructural hazards? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p>	<p>OTHER HAZARDS</p> <p>Are There Hazards That Trigger A Detailed Structural Evaluation?</p> <p><input type="checkbox"/> Pounding potential (unless $S_{L2} >$ cut-off, if known)</p> <p><input type="checkbox"/> Falling hazards from taller adjacent building</p> <p><input type="checkbox"/> Geologic hazards or Soil Type F</p> <p><input type="checkbox"/> Significant damage/deterioration to the structural system</p>	<p>ACTION REQUIRED</p> <p>Detailed Structural Evaluation Required?</p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building</p> <p><input checked="" type="checkbox"/> Yes, score less than cut-off</p> <p><input type="checkbox"/> Yes, other hazards present</p> <p><input type="checkbox"/> No</p> <p>Detailed Nonstructural Evaluation Recommended? (check one)</p> <p><input checked="" type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated</p> <p><input type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary</p> <p><input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p>
---	--	--

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Rapid Visual Screening of Buildings for Potential Seismic Hazards

FEMA P-154 Data Collection Form

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

Level 2 (Optional)
VERY HIGH Seismicity

Bldg Name: Sikeston High School-Bus Garage	Final Level 1 Score: $S_{L1} = 1.3$	<i>(do not consider S_{MIN})</i>	
Screener: M. Griffin/B. Smith	Level 1 Irregularity Modifiers:	Vertical Irregularity, $V_{L1} = 0$	Plan Irregularity, $P_{L1} = 0$
Date/Time: 9-11-15/	ADJUSTED BASELINE SCORE:	$S' = (S_{L1} - V_{L1} - P_{L1}) = 1.3$	

STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

Topic	Statement (If statement is true, circle the "Yes" modifier, otherwise cross out the modifier.)	Yes	Subtotals
Vertical Irregularity, V_{L2}	Sloping Site	W1 building: There is at least a full story grade change from one side of the building to the other.	-0.9
		Non-W1 building: There is at least a full story grade change from one side of the building to the other.	-0.2
	Weak and/or Soft Story (circle one maximum)	W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.	-0.5
		W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum).	-0.9
		W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.	-0.9
		Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.	-0.7
		Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.	-0.4
	Setback	Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.	-0.7
		Vertical elements of the lateral system at upper stories are inboard of those at lower stories.	-0.4
		There is an in-plane offset of the lateral elements that is greater than the length of the elements.	-0.2
	Short Column/ Pier	C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.	-0.4
		C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.	-0.4
Split Level	There is a split level at one of the floor levels or at the roof.	-0.4	
Other Irregularity	There is another observable severe vertical irregularity that obviously affects the building's seismic performance.	-0.7	
	There is another observable moderate vertical irregularity that may affect the building's seismic performance.	-0.4	
Plan Irregularity, P_{L2}	Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.)	-0.5	
	Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.	-0.2	
	Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.	-0.2	
	Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.	-0.2	
	C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.	-0.2	
	Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.	-0.5	
Redundancy	The building has at least two bays of lateral elements on each side of the building in each direction.		+0.2
Pounding	Building is separated from an adjacent structure by less than 1.5% of the height of the shorter of the building and adjacent structure and:	The floors do not align vertically within 2 feet.	-0.7
		One building is 2 or more stories taller than the other.	-0.7
		The building is at the end of the block.	-0.4
S2 Building	"K" bracing geometry is visible.		-0.7
C1 Building	Flat plate serves as the beam in the moment frame.		-0.3
PC1/RM1 Bldg	There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)		+0.2
PC1/RM1 Bldg	The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).		+0.2
URM	Gable walls are present.		-0.3
MH	There is a supplemental seismic bracing system provided between the carriage and the ground.		+0.5
Retrofit	Comprehensive seismic retrofit is visible or known from drawings.		+1.2
FINAL LEVEL 2 SCORE, $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$:			1.3
			<i>(Transfer to Level 1 form)</i>

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance: Yes No
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

OBSERVABLE NONSTRUCTURAL HAZARDS

Location	Statement (Check "Yes" or "No")	Yes	No	Comment
Exterior	There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.		X	
	There is heavy cladding or heavy veneer.		X	
	There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported.		X	
	There is an unreinforced masonry appendage over exit doors or pedestrian walkways.		X	
	There is a sign posted on the building that indicates hazardous materials are present.		X	
	There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney.		X	
	Other observed exterior nonstructural falling hazard:		X	
Interior	There are hollow clay tile or brick partitions at any stair or exit corridor.		X	
	Other observed interior nonstructural falling hazard:	X		Minor parts contents

Estimated Nonstructural Seismic Performance (Check appropriate box and transfer to Level 1 form conclusions)
 Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended
 Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required
 Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

Comments: Parts storage shelving unrestrained.



Address: 733 Greer Street
Sikeston, MO Zip: 63801

Other Identifiers: Sikeston R-6 District

Building Name: Adult Basic Education

Use: Office/Classroom

Latitude: 36.878703 Longitude: -89.576256

Ss: 2.439g S_r: 0.905g

Screeener(s): Varnell/Mills Date/Time: 9-11-15/ 2:00 pm

No. Stories: Above Grade: 2 Below Grade: 0 Year Built: 1962 EST

Total Floor Area (sq. ft.): 6,000 Code Year: Unknown

Additions: None Yes, Year(s) Built: _____

Occupancy: Assembly Commercial Emer. Services Historic Shelter
Industrial Office School Government
Utility Warehouse Residential, # Units: _____

Soil Type: A B C D E F DNK
Hard Avg Dense Stiff Soft Poor DNK
Rock Rock Soil Soil Soil Soil If DNK, assume Type D.

Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

Adjacency: NONE Pounding Falling Hazards from Taller Adjacent Building

Irregularities: Vertical (type/severity) Severe
 Plan (type)

Exterior Falling Hazards: Unbraced Chimneys Heavy Cladding or Heavy Veneer
 Parapets Appendages
 Other: NONE

610.021(20)

COMMENTS:

- Out-of-plane set-back
- Unbraced hot water tank with improper flue connection
- Unsafe guard rail at upper level deck

Additional sketches or comments on separate page

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE, S_{L1}

FEMA BUILDING TYPE	Do Not Know	W1	W1A	W2	S1 (MRF)	S2 (BR)	S3 (LM)	S4 (RC SW)	S5 (URM INF)	C1 (MRF)	C2 (SW)	C3 (URM INF)	PC1 (TU)	PC2	RM1 (FD)	RM2 (RD)	URM	MH
Basic Score		2.1	1.9	1.8	1.5	1.4	1.6	1.4	1.2	1.0	1.2	0.9	1.1	1.0	1.1	1.1	0.9	1.1
Severe Vertical Irregularity, V _{L1}		-0.9	-0.9	-0.9	-0.8	-0.7	-0.8	-0.7	-0.7	-0.7	-0.8	-0.6	-0.7	-0.7	-0.7	-0.7	-0.6	NA
Moderate Vertical Irregularity, V _{L1}		-0.6	-0.5	-0.5	-0.4	-0.4	-0.5	-0.4	-0.3	-0.4	-0.4	-0.3	-0.4	-0.4	-0.4	-0.4	-0.3	NA
Plan Irregularity, P _{L1}		-0.7	-0.7	-0.6	-0.5	-0.5	-0.6	-0.4	-0.4	-0.4	-0.5	-0.3	-0.5	-0.4	-0.4	-0.4	-0.3	NA
Pre-Code		-0.3	-0.3	-0.3	-0.3	-0.2	-0.3	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	0.0
Post-Benchmark		1.9	1.9	2.0	1.0	1.1	1.1	1.5	NA	1.4	1.7	NA	1.5	1.7	1.6	1.6	NA	0.5
Soil Type A or B		0.5	0.5	0.4	0.3	0.3	0.4	0.3	0.2	0.2	0.3	0.1	0.3	0.2	0.3	0.3	0.1	0.1
Soil Type E (1-3 stories)		0.0	-0.2	-0.4	-0.3	-0.2	-0.2	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	-0.1
Soil Type E (> 3 stories)		-0.4	-0.4	-0.4	-0.3	-0.3	NA	-0.3	-0.1	-0.1	-0.3	-0.1	NA	-0.1	-0.2	-0.2	0.0	NA
Minimum Score, S _{MIN}		0.7	0.7	0.7	0.5	0.5	0.5	0.5	0.5	0.3	0.3	0.3	0.2	0.2	0.3	0.3	0.2	1.0

FINAL LEVEL 1 SCORE, S_{L1} ≥ S_{MIN}: 0.3(0.2)

<p>EXTENT OF REVIEW</p> <p>Exterior: <input type="checkbox"/> Partial <input type="checkbox"/> All Sides <input checked="" type="checkbox"/> Aerial Interior: <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered</p> <p>Drawings Reviewed: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p> <p>Soil Type Source: Vs30</p> <p>Geologic Hazards Source: Regional Data</p> <p>Contact Person: Mike Brown</p> <p>LEVEL 2 SCREENING PERFORMED?</p> <p><input checked="" type="checkbox"/> Yes, Final Level 2 Score, S_{L2} 0.9 <input type="checkbox"/> No Nonstructural hazards? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p>	<p>OTHER HAZARDS</p> <p>Are There Hazards That Trigger A Detailed Structural Evaluation?</p> <p><input type="checkbox"/> Pounding potential (unless S_{L2} > cut-off, if known)</p> <p><input type="checkbox"/> Falling hazards from taller adjacent building</p> <p><input type="checkbox"/> Geologic hazards or Soil Type F</p> <p><input type="checkbox"/> Significant damage/deterioration to the structural system</p>	<p>ACTION REQUIRED</p> <p>Detailed Structural Evaluation Required?</p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building</p> <p><input type="checkbox"/> Yes, score less than cut-off</p> <p><input checked="" type="checkbox"/> Yes, other hazards present Guard rail</p> <p><input type="checkbox"/> No</p> <p>Detailed Nonstructural Evaluation Recommended? (check one)</p> <p><input checked="" type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated</p> <p><input type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary</p> <p><input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p>
---	---	---

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Rapid Visual Screening of Buildings for Potential Seismic Hazards

FEMA P-154 Data Collection Form

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

Level 2 (Optional)
VERY HIGH Seismicity

Bldg Name: Adult Basic Education	Final Level 1 Score: $S_{L1} =$ 0.2	<i>(do not consider S_{MIN})</i>	
Screener: Varnell/Mills/Griffin	Level 1 Irregularity Modifiers:	Vertical Irregularity, $V_{L1} =$ -0.7	Plan Irregularity, $P_{L1} =$ 0
Date/Time: 9-11-15/ 2:00 pm	ADJUSTED BASELINE SCORE:	$S' = (S_{L1} - V_{L1} - P_{L1}) =$ 0.9	

STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

Topic	Statement (If statement is true, circle the "Yes" modifier, otherwise cross out the modifier.)	Yes	Subtotals
Vertical Irregularity, V_{L2}	Sloping Site	W1 building: There is at least a full story grade change from one side of the building to the other.	-0.9
		Non-W1 building: There is at least a full story grade change from one side of the building to the other.	-0.2
	Weak and/or Soft Story (circle one maximum)	W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.	-0.5
		W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum).	-0.9
		W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.	-0.9
		Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.	Not critical -0.7
		Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.	-0.4
	Setback	Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.	-0.7
		Vertical elements of the lateral system at upper stories are inboard of those at lower stories.	-0.4
		There is an in-plane offset of the lateral elements that is greater than the length of the elements.	-0.2
	Short Column/ Pier	C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.	-0.4
		C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.	-0.4
Split Level	There is a split level at one of the floor levels or at the roof.	-0.4	
Other Irregularity	There is another observable severe vertical irregularity that obviously affects the building's seismic performance.	-0.7	
	There is another observable moderate vertical irregularity that may affect the building's seismic performance.	-0.4	
Plan Irregularity, P_{L2}	Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.)	-0.5	
	Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.	-0.2	
	Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.	-0.2	
	Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.	-0.2	
	C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.	-0.2	
	Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.	-0.5	
Redundancy	The building has at least two bays of lateral elements on each side of the building in each direction.	+0.2	
Pounding	Building is separated from an adjacent structure by less than 1.5% of the height of the shorter of the building and adjacent structure and:	The floors do not align vertically within 2 feet.	(Cap total pounding modifiers at -0.9) -0.7
		One building is 2 or more stories taller than the other.	-0.7
		The building is at the end of the block.	-0.4
S2 Building	"K" bracing geometry is visible.	-0.7	
C1 Building	Flat plate serves as the beam in the moment frame.	-0.3	
PC1/RM1 Bldg	There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)	+0.2	
PC1/RM1 Bldg	The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).	+0.2	
URM	Gable walls are present.	-0.3	
MH	There is a supplemental seismic bracing system provided between the carriage and the ground.	+0.5	
Retrofit	Comprehensive seismic retrofit is visible or known from drawings.	+1.2	
FINAL LEVEL 2 SCORE, $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$:			0.9
			<i>(Transfer to Level 1 form)</i>

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance: Yes No
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

OBSERVABLE NONSTRUCTURAL HAZARDS

Location	Statement (Check "Yes" or "No")	Yes	No	Comment
Exterior	There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.		X	
	There is heavy cladding or heavy veneer.		X	
	There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported.		X	
	There is an unreinforced masonry appendage over exit doors or pedestrian walkways.		X	
	There is a sign posted on the building that indicates hazardous materials are present.		X	
	There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney.		X	
	Other observed exterior nonstructural falling hazard:		X	
Interior	There are hollow clay tile or brick partitions at any stair or exit corridor.	X		CMU partitions
	Other observed interior nonstructural falling hazard:	X		Water heater

Estimated Nonstructural Seismic Performance (Check appropriate box and transfer to Level 1 form conclusions)
 Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended
 Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required
 Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

Comments: Lower level appears to have been a garage, but has been infilled.



Address: 1002 Virginia Street
Sikeston, MO Zip: 63801
Other Identifiers: Sikeston R-6 District
Building Name: SPS Board Office
Use: Office Space
Latitude: 36.874502 Longitude: -89.568097
Ss: 2.472g Sr: 0.921g
Screener(s): CS, JE, DK Date/Time: 9-11-2015/

No. Stories: Above Grade: 1 Below Grade: 1 Year Built: 1975 EST
Total Floor Area (sq. ft.): 8,133 Code Year: Unknown
Additions: None Yes, Year(s) Built:

Occupancy: Assembly Commercial Emer. Services Historic Shelter
Industrial Office School Government
Utility Warehouse Residential, # Units: _____

Soil Type: A B C D E F DNK
Hard Avg Dense Stiff Soft Poor DNK
Rock Rock Soil Soil Soil Soil If DNK, assume Type D.

Geologic Hazards: Liquefaction: Yes/No/DNK Landslide: Yes/No/DNK Surf. Rupt.: Yes/No/DNK

Adjacency: Pounding Falling Hazards from Taller Adjacent Building

Irregularities: Vertical (type/severity) Sloping Site - Severe
 Plan (type)

Exterior Falling Hazards: Unbraced Chimneys Heavy Cladding or Heavy Veneer
 Parapets Appendages
 Other:

COMMENTS:
- Unanchored cabinets & copy machines
- 2x2 lights not secured
- Electric water heater not secured

Additional sketches or comments on separate page

610.021(20)

BASIC SCORE, MODIFIERS, AND FINAL LEVEL 1 SCORE, SL1

FEMA BUILDING TYPE	Do Not Know	W1	W1A	W2	S1 (MRF)	S2 (BR)	S3 (LM)	S4 (RC SW)	S5 (URM INF)	C1 (MRF)	C2 (SW)	C3 (URM INF)	PC1 (TU)	PC2	RM1 (FD)	RM2 (RD)	URM	MH
Basic Score		2.1	1.9	1.8	1.5	1.4	1.6	1.4	1.2	1.0	1.2	0.9	1.1	1.0	1.1	1.1	0.9	1.1
Severe Vertical Irregularity, V _{L1}		-0.9	-0.9	-0.9	-0.8	-0.7	-0.8	-0.7	-0.7	-0.7	-0.8	-0.6	-0.7	-0.7	-0.7	-0.7	-0.6	NA
Moderate Vertical Irregularity, V _{L1}		-0.6	-0.5	-0.5	-0.4	-0.4	-0.5	-0.4	-0.3	-0.4	-0.4	-0.3	-0.4	-0.4	-0.4	-0.4	-0.3	NA
Plan Irregularity, P _{L1}		-0.7	-0.7	-0.6	-0.5	-0.5	-0.6	-0.4	-0.4	-0.4	-0.5	-0.3	-0.5	-0.4	-0.4	-0.4	-0.3	NA
Pre-Code		-0.3	-0.3	-0.3	-0.3	-0.2	-0.3	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	0.0
Post-Benchmark		1.9	1.9	2.0	1.0	1.1	1.1	1.5	NA	1.4	1.7	NA	1.5	1.7	1.6	1.6	NA	0.5
Soil Type A or B		0.5	0.5	0.4	0.3	0.3	0.4	0.3	0.2	0.2	0.3	0.1	0.3	0.2	0.3	0.3	0.1	0.1
Soil Type E (1-3 stories)		0.0	-0.2	-0.4	-0.3	-0.2	-0.2	-0.2	-0.1	-0.1	-0.2	0.0	-0.2	-0.1	-0.2	-0.2	0.0	-0.1
Soil Type E (> 3 stories)		-0.4	-0.4	-0.4	-0.3	-0.3	NA	-0.3	-0.1	-0.1	-0.3	-0.1	NA	-0.1	-0.2	-0.2	0.0	NA
Minimum Score, S _{MIN}		0.7	0.7	0.7	0.5	0.5	0.5	0.5	0.5	0.3	0.3	0.3	0.2	0.2	0.3	0.3	0.2	1.0

FINAL LEVEL 1 SCORE, SL1 ≥ SMN: 0.9

<p>EXTENT OF REVIEW</p> <p>Exterior: <input type="checkbox"/> Partial <input checked="" type="checkbox"/> All Sides <input type="checkbox"/> Aerial Interior: <input type="checkbox"/> None <input type="checkbox"/> Visible <input checked="" type="checkbox"/> Entered Drawings Reviewed: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Soil Type Source: Vs30 Geologic Hazards Source: Regional Data Contact Person: Mike Brown</p> <p>LEVEL 2 SCREENING PERFORMED?</p> <p><input checked="" type="checkbox"/> Yes, Final Level 2 Score, SL2 1.1 <input type="checkbox"/> No Nonstructural hazards? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p>	<p>OTHER HAZARDS</p> <p>Are There Hazards That Trigger A Detailed Structural Evaluation?</p> <p><input type="checkbox"/> Pounding potential (unless SL2 > cut-off, if known) <input type="checkbox"/> Falling hazards from taller adjacent building <input type="checkbox"/> Geologic hazards or Soil Type F <input type="checkbox"/> Significant damage/deterioration to the structural system</p>	<p>ACTION REQUIRED</p> <p>Detailed Structural Evaluation Required?</p> <p><input type="checkbox"/> Yes, unknown FEMA building type or other building <input checked="" type="checkbox"/> Yes, score less than cut-off <input type="checkbox"/> Yes, other hazards present <input type="checkbox"/> No</p> <p>Detailed Nonstructural Evaluation Recommended? (check one)</p> <p><input type="checkbox"/> Yes, nonstructural hazards identified that should be evaluated <input checked="" type="checkbox"/> No, nonstructural hazards exist that may require mitigation, but a detailed evaluation is not necessary <input type="checkbox"/> No, no nonstructural hazards identified <input type="checkbox"/> DNK</p>
--	---	---

Where information cannot be verified, screener shall note the following: EST = Estimated or unreliable data OR DNK = Do Not Know

Rapid Visual Screening of Buildings for Potential Seismic Hazards

FEMA P-154 Data Collection Form

Optional Level 2 data collection to be performed by a civil or structural engineering professional, architect, or graduate student with background in seismic evaluation or design of buildings.

Level 2 (Optional)
VERY HIGH Seismicity

Bldg Name: SPS Board Office	Final Level 1 Score: $S_{L1} = 0.9$	<i>(do not consider S_{MIN})</i>	
Screener: CS, JE, DK	Level 1 Irregularity Modifiers:	Vertical Irregularity, $V_{L1} = -0.9$	Plan Irregularity, $P_{L1} = 0$
Date/Time: 9-11-2015/	ADJUSTED BASELINE SCORE:	$S' = (S_{L1} - V_{L1} - P_{L1}) = 1.8$	

STRUCTURAL MODIFIERS TO ADD TO ADJUSTED BASELINE SCORE

Topic	Statement (If statement is true, circle the "Yes" modifier, otherwise cross out the modifier.)	Yes	Subtotals
Vertical Irregularity, V_{L2}	Sloping Site	W1 building: There is at least a full story grade change from one side of the building to the other.	-0.9
		Non-W1 building: There is at least a full story grade change from one side of the building to the other.	-0.2
	Weak and/or Soft Story (circle one maximum)	W1 building cripple wall: An unbraced cripple wall is visible in the crawl space.	-0.5
		W1 house over garage: Underneath an occupied story, there is a garage opening without a steel moment frame, and there is less than 8' of wall on the same line (for multiple occupied floors above, use 16' of wall minimum).	-0.9
		W1A building open front: There are openings at the ground story (such as for parking) over at least 50% of the length of the building.	-0.9
		Non-W1 building: Length of lateral system at any story is less than 50% of that at story above or height of any story is more than 2.0 times the height of the story above.	-0.7
		Non-W1 building: Length of lateral system at any story is between 50% and 75% of that at story above or height of any story is between 1.3 and 2.0 times the height of the story above.	-0.4
	Setback	Vertical elements of the lateral system at an upper story are outboard of those at the story below causing the diaphragm to cantilever at the offset.	-0.7
		Vertical elements of the lateral system at upper stories are inboard of those at lower stories.	-0.4
		There is an in-plane offset of the lateral elements that is greater than the length of the elements.	-0.2
	Short Column/ Pier	C1,C2,C3,PC1,PC2,RM1,RM2: At least 20% of columns (or piers) along a column line in the lateral system have height/depth ratios less than 50% of the nominal height/depth ratio at that level.	-0.4
		C1,C2,C3,PC1,PC2,RM1,RM2: The column depth (or pier width) is less than one half of the depth of the spandrel, or there are infill walls or adjacent floors that shorten the column.	-0.4
	Split Level	There is a split level at one of the floor levels or at the roof.	-0.4
Other Irregularity	There is another observable severe vertical irregularity that obviously affects the building's seismic performance.	-0.7	
	There is another observable moderate vertical irregularity that may affect the building's seismic performance.	-0.4	
Plan Irregularity, P_{L2}	Torsional irregularity: Lateral system does not appear relatively well distributed in plan in either or both directions. (Do not include the W1A open front irregularity listed above.)	-0.5	
	Non-parallel system: There are one or more major vertical elements of the lateral system that are not orthogonal to each other.	-0.2	
	Reentrant corner: Both projections from an interior corner exceed 25% of the overall plan dimension in that direction.	-0.2	
	Diaphragm opening: There is an opening in the diaphragm with a width over 50% of the total diaphragm width at that level.	-0.2	
	C1, C2 building out-of-plane offset: The exterior beams do not align with the columns in plan.	-0.2	
	Other irregularity: There is another observable plan irregularity that obviously affects the building's seismic performance.	-0.5	
Redundancy	The building has at least two bays of lateral elements on each side of the building in each direction.	+0.2	
Pounding	Building is separated from an adjacent structure by less than 1.5% of the height of the shorter of the building and adjacent structure and:	The floors do not align vertically within 2 feet.	(Cap total pounding modifiers at -0.9) -0.7
		One building is 2 or more stories taller than the other.	-0.7
		The building is at the end of the block.	-0.4
S2 Building	"K" bracing geometry is visible.	-0.7	
C1 Building	Flat plate serves as the beam in the moment frame.	-0.3	
PC1/RM1 Bldg	There are roof-to-wall ties that are visible or known from drawings that do not rely on cross-grain bending. (Do not combine with post-benchmark or retrofit modifier.)	+0.2	
PC1/RM1 Bldg	The building has closely spaced, full height interior walls (rather than an interior space with few walls such as in a warehouse).	+0.2	
URM	Gable walls are present.	-0.3	
MH	There is a supplemental seismic bracing system provided between the carriage and the ground.	+0.5	
Retrofit	Comprehensive seismic retrofit is visible or known from drawings.	+1.2	
FINAL LEVEL 2 SCORE, $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$:			1.1 (Transfer to Level 1 form)
There is observable damage or deterioration or another condition that negatively affects the building's seismic performance: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.			

FINAL LEVEL 2 SCORE, $S_{L2} = (S' + V_{L2} + P_{L2} + M) \geq S_{MIN}$: 1.1 (Transfer to Level 1 form)

There is observable damage or deterioration or another condition that negatively affects the building's seismic performance: Yes No

If yes, describe the condition in the comment box below and indicate on the Level 1 form that detailed evaluation is required independent of the building's score.

OBSERVABLE NONSTRUCTURAL HAZARDS

Location	Statement (Check "Yes" or "No")	Yes	No	Comment
Exterior	There is an unbraced unreinforced masonry parapet or unbraced unreinforced masonry chimney.		X	
	There is heavy cladding or heavy veneer.	X		Brick Veneer
	There is a heavy canopy over exit doors or pedestrian walkways that appears inadequately supported.	X		Porch at front
	There is an unreinforced masonry appendage over exit doors or pedestrian walkways.		X	
	There is a sign posted on the building that indicates hazardous materials are present.		X	
	There is a taller adjacent building with an unanchored URM wall or unbraced URM parapet or chimney.		X	
	Other observed exterior nonstructural falling hazard:		X	
Interior	There are hollow clay tile or brick partitions at any stair or exit corridor.		X	
	Other observed interior nonstructural falling hazard:		X	

Estimated Nonstructural Seismic Performance (Check appropriate box and transfer to Level 1 form conclusions)

Potential nonstructural hazards with significant threat to occupant life safety → Detailed Nonstructural Evaluation recommended

Nonstructural hazards identified with significant threat to occupant life safety → But no Detailed Nonstructural Evaluation required

Low or no nonstructural hazard threat to occupant life safety → No Detailed Nonstructural Evaluation required

Comments: