


# DUKE ENERGY PROPERTY



Stormwater pipe inlet

Approximate location of pipe break

Secondary ash basin

Primary ash basin

48 inch reinforced concrete pipe

Divider dike

Ash basin dam

Stormwater pipe outlet where spill occurred

Dan River

Dan River

Dan River