



Full NFIRS v1.0

NFIRS - 1 Basic

Incident Location Type: 1-Street address

Street Address: 1475 EAST AVE-Avenue

City, State, Zip Code: Chico, CA 95926

Incident Type: 111-Building fire

Alarm Date Time: 04/25/2025 19:44:34
Shifts or Platoon: C Shift

Aid Given or Received: 1-Mutual aid received

Arrival Date Time: 04/25/2025 19:44:35

Aid Received Department(s): Chico Fire Rescue (04010)

Last Unit Cleared Date Time: 04/26/2025 13:40:45

Primary Action Taken: 11-Extinguishment by fire service personnel

Resource Used: Y-Yes

Property Use: 215-High school/junior high school/middle school

Primary Narrative: Chico Fire units, with assistance from Cal Fire Butte Unit, responded to a confirmed commercial structure fire at Pleasant Valley High School (PVHS), Arts Building (D). Fire units had responded to a structure fire at the same location earlier the same day (CFD Incident #250005003).

E15 received a cell phone call from PVHS staff stating there was smoke inside the building. E15 responded immediately from Station 5, arrived and reported priority traffic for a working fire with heavy fire and smoke showing from the street side on Marigold Avenue, with Marigold being the A side of the structure. E15 assumed Marigold Command and began securing a water supply and stretching a hose line for fire attack. E15 requested a full structure fire response.

B1 responded from Station 5. E15 provided a follow-up 360 report, noting the structure was single-story from the C side, with no basement, and requested the response continue.

B1 and T1 arrived at scene. B1 assumed Marigold Command, with the Incident Command Post (ICP) established at the B1 truck, located in the Loma Vista School parking lot across the street.

B1 directed T1 to position near the A/D corner of the building on Marigold to set up for vertical ventilation. B1 requested a second alarm and priority response from PG&E Gas and Electric. Second alarm resources were to stage at the Marigold Elementary parking lot.

E15 provided a CAN report, stating conditions were tenable inside the classroom on the A side but there was a well-involved attic fire. E15 was engaged in fire attack with a 2 1/2-inch hose line and requested an additional 2 1/2-inch hose line and a crew to force entry on multiple doors on the A, B, and D sides of the structure.

At this point, the fire had self-vented through the center of the roof, closer to the A/B section of the building. Fire and heavy smoke were pushing out of the gable end on the A side. B1 changed T1's assignment to split the crew: setting up water tower operations and assisting E15 with forcible entry and stretching the initial hose line.

E2 arrived at scene and was assigned to stretch a second 2 1/2-inch hose line from E15 to assist with fire attack through the A side. T1 reported heavy fire coming from the gable end of the C side of the roof, with exposure threats to trees and an adjoining classroom building.

E44 arrived and was assigned to pull past T1 and stretch an attack line down the D side to the C side of the structure to protect exposures. E44 secured its own water supply.

E4 arrived and was assigned to position on Marigold near the A/B corner to set up for deck gun operations.

B2107 arrived and was assigned Division C, with E44 assigned to him. Division C's priorities were to protect exposures and assess fire attack opportunities on the C side.

E6 arrived and was assigned to Division C.

E15 provided another CAN report, stating there was still heavy fire in the attic and requesting another crew with an additional hose line and long tools to assist. E15 confirmed conditions inside remained tenable, but the attic was well involved. From the command post, heavy fire was observed from the center of the roof and both gable ends, and conditions were not showing good smoke conversion or progress.

E12 arrived and was assigned to Division A.

At 2009 hours, Command activated emergency tones to announce a strategic shift from offensive to defensive operations. All units were ordered to exit the building and report a PAR upon exit. All units working in the hazard zone confirmed the order.

The T1 aerial was repositioned for defensive water tower operations, and E4 was ordered to get their deck gun in service.

Crews in Divisions A and C attacked the fire from exterior positions.

E41 arrived and was assigned to Division C.

Command received a request from the PVHS principal to salvage computer hard drives from the computer lab located in the classroom at the A/D corner. E2 was reassigned from Division A to assess the D side for the salvage operation. E2 advised Command that the computer lab was in a safe location and proceeded with the operation. E2 successfully removed all computer hard drives and relocated them to another classroom building. Once finished, E2 returned to Division A.

Master streams from T1 and E4 were shut down to reassess fire conditions after heavy water flow.

Multiple smoke/hot spots remained in areas difficult to access with master streams. Divisions A and D proposed a plan to ladder and access stable sides of the roof on the A and C sides with 1 3/4-inch hose lines for continued fire attack from roof positions. Division C also proposed a defensive strip cut in the roof to protect the immediate exposure classroom building off the C/D corner.

Command reviewed and approved the plan.

E45 arrived and was assigned to stretch a hose line to the D side for fire attack and exposure protection.

E81, E2164, and E2184 arrived and were held in staging. T74 was canceled.

E81, E2164, and E2184 were later released.

Crews in Divisions A, C, and D made good progress with hose lines on the roof. A defensive strip cut was placed at the midpoint of the roof along the B, C, and D sides to assist with water application.

E45 was released.

C1 arrived with dinner for all units. Divisions were notified that food was ready, and personnel were directed to the ICP to get food. Crews took time to rehab and eat before continuing overhaul operations.

Division A requested that hose lines and personnel exit the roof and that fire attack continue with master streams from T1 and E4. Command approved the request, and the change was made.

Water was flowed from T1 and E4 until no more smoke was visible from the structure.

E44 and E41 were released.

Once water flow ceased, unused hose lines were rolled up and apparatus placed back in service.

E12, E4, E2, and E6 were released.

E15 remained at scene overnight to monitor the building. At 0237, B1 transitioned command to E15 and reassumed the duty coverage for the city.

At 0730 the next morning B1 relieved E15 from the scene so they could return to quarters for shift change.

Prev. 1 arrived at scene to begin the origin and cause fire investigation. Photos were taken. Prev. 1 and FIT team members planned to continue the investigation on 4/27/25. A supplemental origin and cause investigation report will be attached to this report.

At 1340 hrs. on 4/26/25, the building was turned over to PVHS staff. All units were available and command was terminated.

Officer In Charge: 3435 Public Interest Chief Officer 04/26/2025
 Member Making Report: 3435 Public Interest Chief Officer 04/26/2025

NFIRS - 2 Fire

Area of Fire Origin: 70-Structural area, other
Heat Source: Undetermined
Item First Ignited: Undetermined
Type of Material First Ignited: Undetermined

Cause of Ignition: U-Cause undetermined after investigation
Factors Contributing to Ignition: Undetermined
Human Factors Contributing to Ignition: None

NFIRS - 3 Structure Fire

Structure Type: 1-Enclosed building
Building Status: 2-In normal use
Story of Fire Origin: 1
Fire Spread: 4-Confined to building of origin
Presence of Detectors: 1-Present
Detector Type: 3-Combination smoke and heat in a single unit
Presence of Automatic Extinguishing System: N-None Present

Total Number of Stories at or Above Grade: 1
Total Number of Stories Below Grade: 0
Length and Width: 90 By 90

Detector Power Supply: Undetermined
Detector Operation: Undetermined

NFRIS - 9 Apparatus or Resource

Apparatus or Resource ID	Apparatus or Resource Type	<u>Apparatus</u>				Apparatus Action
		Apparatus or Resource Dispatch Date Time	Apparatus or Resource Arrival Date Time	Apparatus or Resource Clear Date Time		
B1	92-Chief officer car	04/25/2025 19:44:35	04/25/2025 19:46:46	04/26/2025 03:30:00		
BMED2	76-ALS unit	04/25/2025 19:44:37	04/25/2025 20:28:23	04/26/2025 04:15:24		
BMED3	76-ALS unit	04/25/2025 19:57:15	04/25/2025 20:35:14	04/25/2025 21:01:11		
BMED4	76-ALS unit	04/25/2025 19:57:11		04/25/2025 19:57:51		
BSUP2	62-Light and air unit	04/25/2025 19:44:34	04/25/2025 20:30:00	04/26/2025 00:09:00	11-Extinguishment by fire service personnel	

Apparatus or Resource ID	Apparatus or Resource Type	Apparatus or Resource Dispatch Date Time	Apparatus or Resource Arrival Date Time	Apparatus or Resource Clear Date Time	Apparatus Action
CPNY1	99-Privately owned vehicle	04/25/2025 19:44:35		04/26/2025 00:09:09	
E12	11-Engine	04/25/2025 19:44:35	04/25/2025 19:51:26	04/25/2025 23:43:24	
E15	11-Engine	04/25/2025 19:44:34	04/25/2025 19:44:35	04/26/2025 07:39:10	
E2	11-Engine	04/25/2025 19:45:12	04/25/2025 20:06:41	04/25/2025 23:46:23	
E2164	11-Engine	04/25/2025 19:53:54	04/25/2025 20:19:41	04/25/2025 21:11:26	
E2184	11-Engine	04/25/2025 19:53:56	04/25/2025 21:09:40	04/25/2025 21:18:06	
E4	11-Engine	04/25/2025 19:44:35	04/25/2025 19:53:39	04/26/2025 00:41:57	
E41 (Mutual Aid Vehicle)	11-Engine	04/25/2025 19:53:49	04/25/2025 19:57:23	04/25/2025 23:11:55	
E44 (Mutual Aid Vehicle)	11-Engine	04/25/2025 19:44:54	04/25/2025 19:52:48	04/26/2025 00:09:06	
E45 (Mutual Aid Vehicle)	11-Engine	04/25/2025 19:53:52	04/25/2025 20:09:28	04/25/2025 21:28:16	
E6	11-Engine	04/25/2025 19:44:34	04/25/2025 19:55:37	04/26/2025 00:05:50	
E81	11-Engine	04/25/2025 19:53:53	04/25/2025 20:13:48	04/25/2025 21:10:46	
P1	92-Chief officer car	04/25/2025 19:44:34	04/25/2025 20:03:00	04/26/2025 00:09:00	86-Investigate
T1	12-Truck or aerial	04/25/2025 19:44:35	04/25/2025 19:59:15	04/26/2025 01:28:27	
T74	12-Truck or aerial	04/25/2025 19:53:47	04/25/2025 20:28:07	04/25/2025 20:36:11	

NFIRS - 10 Personnel

Apparatus or Resource ID	Apparatus or Resource Type	Apparatus Action	Apparatus						
			Apparatus or Resource Number of People	Apparatus or Resource Response Mode to Scene	Apparatus or Resource Dispatch Date Time	Apparatus or Resource Enroute Date Time	Apparatus or Resource Arrival Date Time	Apparatus or Resource Clear Date Time	Apparatus or Resource In Service Date Time
B1	92-Chief officer car		1		04/25/2025 19:44:35	04/25/2025 19:45:00	04/25/2025 19:46:46	04/26/2025 03:30:00	04/25/2025 03:30:00
BMED2	76-ALS unit				04/25/2025 19:44:37	04/25/2025 19:58:14	04/25/2025 20:28:23	04/26/2025 04:15:24	04/26/2025 04:15:24
BMED3	76-ALS unit				04/25/2025 19:57:15	04/25/2025 19:58:17	04/25/2025 20:35:14	04/25/2025 21:01:11	04/25/2025 21:01:11
BMED4	76-ALS unit				04/25/2025 19:57:11			04/25/2025 19:57:51	04/25/2025 19:57:51
BSUP2	62-Light and air unit	11-Extinguishment by fire service personnel	1		04/25/2025 19:44:34		04/25/2025 20:30:00	04/26/2025 00:09:00	04/26/2025 00:09:00
CPNY1	99-Privately owned vehicle		1		04/25/2025 19:44:35			04/26/2025 00:09:09	04/26/2025 00:09:09
E12	11-Engine		3		04/25/2025 19:44:35	04/25/2025 19:45:44	04/25/2025 19:51:26	04/25/2025 23:43:24	04/25/2025 23:43:24

Apparatus or Resource ID	Apparatus or Resource Type	Apparatus Action	Apparatus or Resource Number of People	Apparatus or Resource Response Mode to Scene	Apparatus or Resource Dispatch Date Time	Apparatus or Resource Enroute Date Time	Apparatus or Resource Arrival Date Time	Apparatus or Resource Clear Date Time	Apparatus or Resource In Service Date Time
E15	11-Engine		4		04/25/2025 19:44:34		04/25/2025 19:44:35	04/26/2025 07:39:10	04/26/2025 07:39:10
E2	11-Engine		3		04/25/2025 19:45:12	04/25/2025 19:45:12	04/25/2025 20:06:41	04/25/2025 23:46:23	04/25/2025 23:46:23
E2164	11-Engine		2		04/25/2025 19:53:54	04/25/2025 19:59:24	04/25/2025 20:19:41	04/25/2025 21:11:26	04/25/2025 21:11:26
E2184	11-Engine		2		04/25/2025 19:53:56	04/25/2025 19:59:24	04/25/2025 21:09:40	04/25/2025 21:18:06	04/25/2025 21:18:06
E4	11-Engine		3		04/25/2025 19:44:35	04/25/2025 19:49:28	04/25/2025 19:53:39	04/26/2025 00:41:57	04/26/2025 00:41:57
E41 (Mutual Aid Vehicle)	11-Engine		2		04/25/2025 19:53:49	04/25/2025 19:54:00	04/25/2025 19:57:23	04/25/2025 23:11:55	04/25/2025 23:11:55
E44 (Mutual Aid Vehicle)	11-Engine		2		04/25/2025 19:44:54	04/25/2025 19:45:33	04/25/2025 19:52:48	04/26/2025 00:09:06	04/26/2025 00:09:06
E45 (Mutual Aid Vehicle)	11-Engine		2		04/25/2025 19:53:52	04/25/2025 19:55:32	04/25/2025 20:09:28	04/25/2025 21:28:16	04/25/2025 21:28:16
E6	11-Engine		3		04/25/2025 19:44:34	04/25/2025 19:49:29	04/25/2025 19:55:37	04/26/2025 00:05:50	04/26/2025 00:05:50
E81	11-Engine		3		04/25/2025 19:53:53	04/25/2025 19:55:19	04/25/2025 20:13:48	04/25/2025 21:10:46	04/25/2025 21:10:46
P1	92-Chief officer car	86- Investigate	1	Non-Emergency	04/25/2025 19:44:34		04/25/2025 20:03:00	04/26/2025 00:09:00	
T1	12-Truck or aerial		4		04/25/2025 19:44:35	04/25/2025 19:45:59	04/25/2025 19:59:15	04/26/2025 01:28:27	04/26/2025 01:28:27
T74	12-Truck or aerial		3		04/25/2025 19:53:47	04/25/2025 19:55:01	04/25/2025 20:28:07	04/25/2025 20:36:11	04/25/2025 20:36:11

NFIRS - 1S Supplemental

Primary Narrative: Chico Fire units, with assistance from Cal Fire Butte Unit, responded to a confirmed commercial structure fire at Pleasant Valley High School (PVHS), Arts Building (D). Fire units had responded to a structure fire at the same location earlier the same day (CFD Incident #250005003).

E15 received a cell phone call from PVHS staff stating there was smoke inside the building. E15 responded immediately from Station 5, arrived and reported priority traffic for a working fire with heavy fire and smoke showing from the street side on Marigold Avenue, with Marigold being the A side of the structure. E15 assumed Marigold Command and began securing a water supply and stretching a hose line for fire attack. E15 requested a full structure fire response.

B1 responded from Station 5. E15 provided a follow-up 360 report, noting the structure was single-story from the C side, with no basement, and requested the response continue.

B1 and T1 arrived at scene. B1 assumed Marigold Command, with the Incident Command Post (ICP) established at the B1 truck, located in the Loma Vista School parking lot across the street.

B1 directed T1 to position near the A/D corner of the building on Marigold to set up for vertical ventilation. B1 requested a second alarm and priority response from PG&E Gas and Electric. Second alarm resources were to stage at the Marigold Elementary parking lot.

E15 provided a CAN report, stating conditions were tenable inside the classroom on the A side but there was a well-involved attic fire. E15 was engaged in fire attack with a 2 1/2-inch hose line and requested an additional 2 1/2-inch hose line and a crew to force entry on multiple doors on the A, B, and D sides of the structure.

At this point, the fire had self-vented through the center of the roof, closer to the A/B section of the building. Fire and heavy smoke were pushing out of the gable end on the A side. B1 changed T1's assignment to split the crew: setting up water tower operations and assisting E15 with forcible entry and stretching the initial hose line.

E2 arrived at scene and was assigned to stretch a second 2 1/2-inch hose line from E15 to assist with fire attack through the A side. T1 reported heavy fire coming from the gable end of the C side of the roof, with exposure threats to trees and an adjoining classroom building.

E44 arrived and was assigned to pull past T1 and stretch an attack line down the D side to the C side of the structure to protect exposures. E44 secured its own water supply.

E4 arrived and was assigned to position on Marigold near the A/B corner to set up for deck gun operations.

B2107 arrived and was assigned Division C, with E44 assigned to him. Division C's priorities were to protect exposures and assess fire attack opportunities on the C side.

E6 arrived and was assigned to Division C.

E15 provided another CAN report, stating there was still heavy fire in the attic and requesting another crew with an additional hose line and long tools to assist. E15 confirmed conditions inside remained tenable, but the attic was well involved. From the command post, heavy fire was observed from the center of the roof and both gable ends, and conditions were not showing good smoke conversion or progress.

E12 arrived and was assigned to Division A.

At 2009 hours, Command activated emergency tones to announce a strategic shift from offensive to defensive operations. All units were ordered to exit the building and report a PAR upon exit. All units working in the hazard zone confirmed the order.

The T1 aerial was repositioned for defensive water tower operations, and E4 was ordered to get their deck gun in service.

Crews in Divisions A and C attacked the fire from exterior positions.

E41 arrived and was assigned to Division C.

Command received a request from the PVHS principal to salvage computer hard drives from the computer lab located in the classroom at the A/D corner. E2 was reassigned from Division A to assess the D side for the salvage operation. E2 advised Command that the computer lab was in a safe location and proceeded with the operation. E2 successfully removed all computer hard drives and relocated them to another classroom building. Once finished, E2 returned to Division A.

Master streams from T1 and E4 were shut down to reassess fire conditions after heavy water flow.

Multiple smoke/hot spots remained in areas difficult to access with master streams. Divisions A and D proposed a plan to ladder and access stable sides of the roof on the A and C sides with 1 3/4-inch hose lines for continued fire attack from roof positions. Division C also proposed a defensive strip cut in the roof to protect the immediate exposure classroom building off the C/D corner.

Command reviewed and approved the plan.

E45 arrived and was assigned to stretch a hose line to the D side for fire attack and exposure protection.

E81, E2164, and E2184 arrived and were held in staging. T74 was canceled.

E81, E2164, and E2184 were later released.

Crews in Divisions A, C, and D made good progress with hose lines on the roof. A defensive strip cut was placed at the midpoint of the roof along the B, C, and D sides to assist with water application.

E45 was released.

C1 arrived with dinner for all units. Divisions were notified that food was ready, and personnel were directed to the ICP to get food. Crews took time to rehab and eat before continuing overhaul operations.

Division A requested that hose lines and personnel exit the roof and that fire attack continue with master streams from T1 and E4. Command approved the request, and the change was made.

Water was flowed from T1 and E4 until no more smoke was visible from the structure.

E44 and E41 were released.

Once water flow ceased, unused hose lines were rolled up and apparatus placed back in service.

E12, E4, E2, and E6 were released.

E15 remained at scene overnight to monitor the building. At 0237, B1 transitioned command to E15 and reassumed the duty coverage for the city.

At 0730 the next morning B1 relieved E15 from the scene so they could return to quarters for shift change.

Prev. 1 arrived at scene to begin the origin and cause fire investigation. Photos were taken. Prev. 1 and FIT team members planned to continue the investigation on 4/27/25. A supplemental origin and cause investigation report will be attached to this report.

At 1340 hrs. on 4/26/25, the building was turned over to PVHS staff. All units were available and command was terminated.

Additional Narratives

Additional Narratives

[04/25/2025 19:44:34 : Unit: E15]
DISP. Pleasant Valley High School, 1475 East Ave, Chico, CA

[04/25/2025 19:44:35 : Unit: E15]
Fire Inc # 25-0005016 (CFD) assigned to 02504250329

[04/25/2025 19:44:34 : Unit: E6]
DISP. Pleasant Valley High School, 1475 East Ave, Chico, CA

[04/25/2025 19:44:35 : Unit: E12]
DISP. Pleasant Valley High School, 1475 East Ave, Chico, CA

[04/25/2025 19:44:35 : Unit: E4]
DISP. Pleasant Valley High School, 1475 East Ave, Chico, CA

[04/25/2025 19:44:35 : Unit: E44]
REQ. Pleasant Valley High School, 1475 East Ave, Chico, CA

[04/25/2025 19:44:35 : Unit: T1]
DISP. Pleasant Valley High School, 1475 East Ave, Chico, CA

[04/25/2025 19:44:35 : Unit: B1]
DISP. Pleasant Valley High School, 1475 East Ave, Chico, CA

[04/25/2025 19:44:35 : Unit: E44]
RIMS Request for E44

[04/25/2025 19:44:35 : Unit: CPNY1]
DISP. Pleasant Valley High School, 1475 East Ave, Chico, CA

[04/25/2025 19:44:36 : Unit: E15]
Sending Incident to E15 Pager

[04/25/2025 19:44:37 : Unit: BMED2]
DISP. Pleasant Valley High School, 1475 East Ave, Chico, CA

[04/25/2025 19:44:37 : Unit: E15]
Sending Incident to E15 Pager

[04/25/2025 19:44:38 : Unit: BMED2]
Printed Initial Fire Run Sheet to Station 98 for Unit(s) BMED2

[04/25/2025 19:44:38 : Unit: E6]
Sending Incident to E6 Pager

[04/25/2025 19:44:39 : Unit: E6]
Sending Incident to E6 Pager

[04/25/2025 19:44:40 : Unit: E12]
Sending Incident to E12 Pager

[04/25/2025 19:44:41 : Unit: E12]
Sending Incident to E12 Pager

[04/25/2025 19:44:41 : Unit: E4]
Sending Incident to E4 Pager

[04/25/2025 19:44:42 : Unit: E4]
Sending Incident to E4 Pager

[04/25/2025 19:44:43 : Unit: T1]
Sending Incident to T1 Pager

[04/25/2025 19:44:44 : Unit: T1]
Sending Incident to T1 Pager

[04/25/2025 19:44:45 : Unit: B1]
Sending Incident to B1 Pager

[04/25/2025 19:44:46 : Unit: B1]
10-49.

Additional Narratives

[04/25/2025 19:44:46 : Unit: B1]
Sending Incident to B1 Pager

[04/25/2025 19:44:47 : Unit: CPNY1]
Sending Incident to CPNY1 Pager

[04/25/2025 19:44:41 : Unit:]
Request for E44(BTU-E44) from CHI 2000 2000.

[04/25/2025 19:44:54 : Unit: E44]
CALFD Approved Request for E44

[04/25/2025 19:44:54 : Unit: E44]
DISP.

[04/25/2025 19:44:54 : Unit: E44]
Sending Incident to E44 Pager

[04/25/2025 19:44:54 : Unit: E44]
CALFD Approved Request for E44

[04/25/2025 19:45:09 : Unit:]
BOLO'D TO PD

[04/25/2025 19:45:12 : Unit: E2]
10-49.

[04/25/2025 19:45:12 : Unit: E2]
Sending Incident to E2 Pager

[04/25/2025 19:45:12 : Unit: E2]
Sending Incident to E2 Pager

[04/25/2025 19:45:13 : Unit: E2]
Sending Incident to E2 Pager

[04/25/2025 19:45:13 : Unit: E2]
Sending Incident to E2 Pager

[04/25/2025 19:45:33 : Unit: E44]
10-49.

[04/25/2025 19:45:35 : Unit:]
E15 REQUESTING

[04/25/2025 19:45:35 : Unit:]
FULL RESPONSE

[04/25/2025 19:45:35 : Unit:]
AT SCENE WORKING

[04/25/2025 19:45:35 : Unit:]
SHOWING FROM ALPHA

[04/25/2025 19:45:35 : Unit:]
3/4 LINES FROM FRONT DOOR

[04/25/2025 19:45:44 : Unit: E12]
10-49.

[04/25/2025 19:45:59 : Unit: T1]
10-49.

[04/25/2025 19:46:46 : Unit:]
AT SCENE

Additional Narratives

[04/25/2025 19:46:46 : Unit:]
WORKING FIRE

[04/25/2025 19:46:46 : Unit:]
HEAVY FIRE FROM ROOF

[04/25/2025 19:46:46 : Unit:]
2ND ALARM

[04/25/2025 19:46:46 : Unit:]
STAGING AT MARIGOLD ACCROS ST

[04/25/2025 19:47:54 : Unit:]
Public Interest / ADTL CALLER

[04/25/2025 19:48:01 : Unit:]
2ND ALARM

[04/25/2025 19:48:01 : Unit:]
PGE REQUESTED

[04/25/2025 19:48:01 : Unit:]
OFFENSIVE STRAG

[04/25/2025 19:48:47 : Unit:]
STRECH LINE FOR FIRE ATTACK

[04/25/2025 19:49:28 : Unit: E4]
10-49.

[04/25/2025 19:49:29 : Unit: E6]
10-49.

[04/25/2025 19:49:29 : Unit:]
CAL FIRE CALLING BC AND WILL CALL BACK WITH THE UNITS RESPONDING

[04/25/2025 19:51:02 : Unit:]
PGE REQUESTED PRIORITY

[04/25/2025 19:51:24 : Unit:]
PGE CALLING BACK WITH ETA

[04/25/2025 19:51:26 : Unit: E12]
10-97.

[04/25/2025 19:52:48 : Unit: E44]
10-97.

[04/25/2025 19:53:38 : Unit: T74]
REQ. Pleasant Valley High School, 1475 East Ave, Chico, CA

[04/25/2025 19:53:38 : Unit: E41]
REQ. Pleasant Valley High School, 1475 East Ave, Chico, CA

[04/25/2025 19:53:38 : Unit: T74]
RIMS Request for T74

[04/25/2025 19:53:38 : Unit: E45]
REQ. Pleasant Valley High School, 1475 East Ave, Chico, CA

[04/25/2025 19:53:38 : Unit: E81]
REQ. Pleasant Valley High School, 1475 East Ave, Chico, CA

[04/25/2025 19:53:38 : Unit: E2164]
REQ. Pleasant Valley High School, 1475 East Ave, Chico, CA

Additional Narratives

[04/25/2025 19:53:38 : Unit: E2184]
REQ. Pleasant Valley High School, 1475 East Ave, Chico, CA

[04/25/2025 19:53:39 : Unit: E4]
10-97.

[04/25/2025 19:53:39 : Unit: E41]
RIMS Request for E41

[04/25/2025 19:53:41 : Unit: E45]
RIMS Request for E45

[04/25/2025 19:53:42 : Unit: E81]
RIMS Request for E81

[04/25/2025 19:53:43 : Unit: E2164]
RIMS Request for E2164

[04/25/2025 19:53:44 : Unit: E2184]
RIMS Request for E2184

[04/25/2025 19:53:45 : Unit: B2107]
RIMS Request for B2107

[04/25/2025 19:53:42 : Unit:]
Request for T74(BTU-T74) from CHI 2000 2000.

[04/25/2025 19:53:47 : Unit: T74]
CALFD Approved Request for T74

[04/25/2025 19:53:47 : Unit: T74]
DISP.

[04/25/2025 19:53:48 : Unit: T74]
CALFD Approved Request for T74

[04/25/2025 19:53:44 : Unit:]
Request for E41(BTU-E41) from CHI 2000 2000.

[04/25/2025 19:53:48 : Unit: E41]
CALFD Approved Request for E41

[04/25/2025 19:53:49 : Unit: E41]
DISP.

[04/25/2025 19:53:52 : Unit: E41]
Sending Incident to E41 Pager

[04/25/2025 19:53:52 : Unit: E41]
CALFD Approved Request for E41

[04/25/2025 19:53:45 : Unit:]
Request for E45(BTU-E45) from CHI 2000 2000.

[04/25/2025 19:53:52 : Unit: E45]
CALFD Approved Request for E45

[04/25/2025 19:53:52 : Unit: E45]
DISP.

[04/25/2025 19:53:53 : Unit: E45]
CALFD Approved Request for E45

[04/25/2025 19:53:46 : Unit:]
Request for E81(BTU-E81) from CHI 2000 2000.

[04/25/2025 19:53:53 : Unit: E81]
CALFD Approved Request for E81

[04/25/2025 19:53:53 : Unit: E81]

Additional Narratives

DISP.

[04/25/2025 19:53:54 : Unit: E81]
CALFD Approved Request for E81

[04/25/2025 19:53:47 : Unit:]
Request for E2164(BTU-E2164) from CHI 2000 2000.

[04/25/2025 19:53:54 : Unit: E2164]
CALFD Approved Request for E2164

[04/25/2025 19:53:54 : Unit: E2164]
DISP.

[04/25/2025 19:53:55 : Unit: E2164]
CALFD Approved Request for E2164

[04/25/2025 19:53:49 : Unit:]
Request for E2184(BTU-E2184) from CHI 2000 2000.

[04/25/2025 19:53:56 : Unit: E2184]
CALFD Approved Request for E2184

[04/25/2025 19:53:56 : Unit: E2184]
DISP.

[04/25/2025 19:53:58 : Unit: E2184]
CALFD Approved Request for E2184

[04/25/2025 19:54:00 : Unit: E41]
10-49.

[04/25/2025 19:54:42 : Unit:]
ACCIDENTAL EMERG BUTTON PRESSED / ALL UNITS CODE 4

[04/25/2025 19:55:01 : Unit: T74]
10-49.

[04/25/2025 19:55:19 : Unit: E81]
10-49.

[04/25/2025 19:55:32 : Unit: E45]
10-49.

[04/25/2025 19:55:37 : Unit: E6]
10-97.

[04/25/2025 19:57:11 : Unit: BMED4]
DISP. Pleasant Valley High School, 1475 East Ave, Chico, CA

[04/25/2025 19:57:12 : Unit: BMED4]
Printed Initial Fire Run Sheet to Station 98 for Unit(s) BMED4

[04/25/2025 19:57:15 : Unit: BMED3]
DISP. Pleasant Valley High School, 1475 East Ave, Chico, CA

[04/25/2025 19:57:15 : Unit: BMED3]
Printed Initial Fire Run Sheet to Station 98 for Unit(s) BMED3

[04/25/2025 19:57:23 : Unit: E41]
10-97.

[04/25/2025 19:57:51 : Unit: BMED4]
10-8. . Disposition CF

[04/25/2025 19:57:55 : Unit: BMED4]
Exported BMED4 Unit Record to IMAGETREND

[04/25/2025 19:58:14 : Unit: BMED2]
10-49.

Additional Narratives

[04/25/2025 19:58:17 : Unit: BMED3]
10-49.

[04/25/2025 19:58:34 : Unit: E15]
10-97.

[04/25/2025 19:59:15 : Unit: T1]
10-97.

[04/25/2025 19:59:24 : Unit: E2184]
10-49.

[04/25/2025 19:59:24 : Unit: E2164]
10-49.

[04/25/2025 19:59:42 : Unit: B2107]
RIMS Request for B2107

[04/25/2025 19:59:47 : Unit:]
PGE ETA 30 MINT

[04/25/2025 20:02:47 : Unit:]
PER CAL FIRE - E2107 AT SCENE, T74 ENROUTE

[04/25/2025 20:06:29 : Unit: B1]
10-97.

[04/25/2025 20:06:41 : Unit: E2]
10-97.

[04/25/2025 20:09:28 : Unit: E45]
10-97.

[04/25/2025 20:09:34 : Unit: B1]
TIME CHECK --

[04/25/2025 20:09:34 : Unit: B1]
DEFENSIVE STRAG

[04/25/2025 20:09:34 : Unit: B1]
BRACKETING THE BUILDING

[04/25/2025 20:10:49 : Unit:]
C1- REQ PD OFFICER TO N/S OF EAST AND MARIGOLD

[04/25/2025 20:13:48 : Unit: E81]
10-97.

[04/25/2025 20:14:55 : Unit:]
E81 AT SCENE

[04/25/2025 20:16:58 : Unit:]
EN2164 AT A SCENE

[04/25/2025 20:19:30 : Unit:]
E2174 AT STAGING

[04/25/2025 20:19:41 : Unit: E2164]
10-97.

[04/25/2025 20:20:52 : Unit: B1]
BATTALTON 2 HAS CITY COVERAGE

[04/25/2025 20:21:16 : Unit:]
2ND TIME CHECK

[04/25/2025 20:28:02 : Unit: B1]
CANCEL TRUCK 74 AND CAN HANDLE WITH RESOURCES AT SCENE

Additional Narratives

[04/25/2025 20:28:02 : Unit: B1]
EN 2184 CAN CANCEL AS WELL IF STILL ENRT

[04/25/2025 20:28:07 : Unit: T74]
10-97.

[04/25/2025 20:28:23 : Unit: BMED2]
10-97.

[04/25/2025 20:28:49 : Unit:]
SECOND MEDIC UNIT ON SCENE

[04/25/2025 20:29:59 : Unit:]
RELEASE 2184 AND KEEP 2164

[04/25/2025 20:30:59 : Unit:]
T74 ADVISED OVER RADIO CAN RELEASE

[04/25/2025 20:31:48 : Unit:]
RELEASED/CANCELLED WITH CAL FIRE - T74, E2164, E2184

[04/25/2025 20:34:09 : Unit: B1]
3RD TIME CHECK

[04/25/2025 20:34:09 : Unit: B1]
KNOCKED DOWN FIRE

[04/25/2025 20:34:09 : Unit: B1]
CREWS ARE CURRENTLY WORKING ON OPERATION

[04/25/2025 20:34:09 : Unit: B1]
DEFENSIVE STRAG

[04/25/2025 20:35:14 : Unit: BMED3]
10-97.

[04/25/2025 20:36:11 : Unit: T74]
10-8. . Disposition CF

[04/25/2025 20:36:13 : Unit: T74]
Exported T74 Unit Record to IMAGETREND

[04/25/2025 20:42:14 : Unit:]
4TH TIME CHECK

[04/25/2025 20:54:51 : Unit:]
5TH TIME CHECK

[04/25/2025 21:01:09 : Unit: B1]
10-8. Freed

[04/25/2025 21:01:11 : Unit: BMED3]
10-8. Freed

[04/25/2025 21:03:34 : Unit: B1]
DISP. Pleasant Valley High School, 1475 East Ave, Chico, CA

[04/25/2025 21:03:36 : Unit: B1]
Sending Incident to B1 Pager

[04/25/2025 21:03:38 : Unit: B1]
Sending Incident to B1 Pager

[04/25/2025 21:03:42 : Unit: B1]
10-97.

[04/25/2025 21:08:42 : Unit:]

Additional Narratives

6TH TIME CHECK

[04/25/2025 21:09:40 : Unit: E2184]
10-97.

[04/25/2025 21:10:31 : Unit: B1]
E81 RELEASED AVAILABLE

[04/25/2025 21:10:46 : Unit: E81]
10-8. . Disposition CF

[04/25/2025 21:10:49 : Unit: E81]
Exported E81 Unit Record to IMAGETREND

[04/25/2025 21:11:06 : Unit:]
E2164 RELEASED

[04/25/2025 21:11:26 : Unit: E2164]
10-8. . Disposition CF

[04/25/2025 21:11:27 : Unit: E2164]
Exported E2164 Unit Record to IMAGETREND

[04/25/2025 21:18:06 : Unit: E2184]
10-8. . Disposition CF

[04/25/2025 21:18:08 : Unit: E2184]
Exported E2184 Unit Record to IMAGETREND

[04/25/2025 21:25:57 : Unit:]
TIME CHECK - DISCONTINUE

[04/25/2025 21:28:16 : Unit: E45]
10-8. . Disposition CF

[04/25/2025 21:28:17 : Unit: E45]
Exported E45 Unit Record to IMAGETREND

[04/25/2025 23:11:55 : Unit: E41]
10-8. . Disposition CF

[04/25/2025 23:11:57 : Unit: E41]
Exported E41 Unit Record to IMAGETREND

[04/25/2025 23:43:24 : Unit: E12]
10-8. . Disposition CF

[04/25/2025 23:43:27 : Unit: E12]
Exported E12 Unit Record to IMAGETREND

[04/25/2025 23:46:23 : Unit: E2]
10-8. . Disposition CF

[04/25/2025 23:46:27 : Unit: E2]
Exported E2 Unit Record to IMAGETREND

[04/26/2025 00:05:50 : Unit: E6]
10-8. . Disposition CF

[04/26/2025 00:05:53 : Unit: E6]
Exported E6 Unit Record to IMAGETREND

[04/26/2025 00:09:06 : Unit: E44]
10-8. . Disposition CF

[04/26/2025 00:09:09 : Unit: CPNY1]
10-8. . Disposition CF

[04/26/2025 00:09:11 : Unit: E44]
Exported E44 Unit Record to IMAGETREND

Additional Narratives

[04/26/2025 00:09:14 : Unit: CPNY1]

Exported CPNY1 Unit Record to IMAGETREND

[04/26/2025 00:41:57 : Unit: E4]

10-8. . Disposition CF

[04/26/2025 00:41:59 : Unit: E4]

Exported E4 Unit Record to IMAGETREND

[04/26/2025 01:28:27 : Unit: T1]

10-8. . Disposition CF

[04/26/2025 01:28:29 : Unit: T1]

Exported T1 Unit Record to IMAGETREND

[04/26/2025 01:37:04 : Unit:]

KRCR Public Interest Public Interest REQ CALL BACK ON FIRE

[04/26/2025 02:37:44 : Unit: B1]

E15 MARIGOLD COMMAND

[04/26/2025 02:37:47 : Unit: B1]

10-8. . Disposition CF

[04/26/2025 02:37:49 : Unit: B1]

Exported B1 Unit Record to IMAGETREND

[04/26/2025 04:15:24 : Unit: BMED2]

10-8. . Disposition CF

[04/26/2025 04:15:27 : Unit: BMED2]

Exported BMED2 Unit Record to IMAGETREND

[04/26/2025 07:21:39 : Unit: B1]

10-49.

[04/26/2025 07:21:40 : Unit: B1]

Sending Incident to B1 Pager

[04/26/2025 07:21:40 : Unit: B1]

Sending Incident to B1 Pager

[04/26/2025 07:21:40 : Unit: B1]

Sending Incident to B1 Pager

[04/26/2025 07:21:40 : Unit: B1]

Sending Incident to B1 Pager

[04/26/2025 07:22:01 : Unit: B1]

10-97.

[04/26/2025 07:39:10 : Unit: E15]

10-8. . Disposition CF

[04/26/2025 07:39:15 : Unit: E15]

Exported E15 Unit Record to IMAGETREND

[04/26/2025 07:39:20 : Unit: E15]

10-8. . Disposition CF

[04/26/2025 09:31:00 : Unit: B1]

CD4.

[04/26/2025 13:40:38 : Unit:]

PROP TURNED OVER TO SCHOOL MARIGOLD COMMAND TERMINATED

[04/26/2025 13:40:45 : Unit: B1]

10-8.

Apparatus Narratives

Apparatus or Resource ID

B1
BMED2
BMED3
BMED4
BSUP2
CPNY1
E12
E15
E2
E2164
E2184
E4
E41 (Mutual Aid Vehicle)
E44 (Mutual Aid Vehicle)
E45 (Mutual Aid Vehicle)
E6
E81
P1
T1
T74

Was this incident related to transient/homeless population: No

Was this incident related to the University student population: No

Medics were on a delayed response:

Station Assignment: 1

Incident District: 5

COVID 19 was a factor in this incident: 3 - No, COVID 19 was not a factor

Preliminary Fire Investigation Report Narrative

Incident No: 250005016

Address: 1475 East Avenue, Chico, CA

Date: 4/25/2025

By: Ricketts, Paul

On April 25th, 2025, I arrived at 1475 East Avenue, Chico, at approximately 8:03 p.m. for a confirmed structure fire. Upon my arrival, suppression crews were extinguishing a fire at the Art Building of Pleasant Valley High School. The building was a wood-framed, single-story, Type V structure with stucco siding and composite roofing, used for classrooms.

This was the second fire in this building on this day. Chico Fire Department responded to a fire in classroom D4 at approximately 4:40 p.m. Fire crews extinguished the first fire, completed overhaul, checked for fire extension, and left the scene at approximately 6:36 p.m. School staff contacted the Company Officer of Engine 15 at approximately 7:40 p.m. and indicated that smoke was seen from the Art Building. Engine 15 returned to the scene at approximately 7:44 p.m. to find smoke and flames coming from the east gable of the building.

Witness Information

I contacted [REDACTED] Public Interest and was able to view video footage of the school. The camera was located on the Marigold Elementary School campus, pointing at the east side of the art building. The camera is motion-activated, resulting in gaps in video coverage; therefore, all times are approximate. The first visible smoke is seen from the south side of the roof ridge at approximately 7:06 p.m. Consistent smoke is not seen until 7:30 p.m., and heavy smoke is seen at 7:41 p.m. Flames are first seen coming from the east gable end of the building at 7:43 p.m.

Preliminary Fire Investigation Report Narrative

Incident No: 250005016

Address: 1475 East Avenue, Chico, CA

Date: 4/25/2025

By: Ricketts, Paul

Investigation

Upon investigation, I found fire damage to the attic area of the Art Building. Severe fire damage was seen throughout the attic, with fire penetrating the roof in several areas.

Complete mass loss to the roof was found at the entire ridge and down the north and south roof slopes. An area west of the wall that separates classrooms D3 and D4 had a distinctive area where the roof had mass loss between each of the roof beams. This wall that separates classrooms D3 and D4 shall be referred to in the report as "D3/D4 wall."

Due to fire damage to the roof beams and trusses, access to the attic space was limited due to safety concerns. Most observations of the attic were made from ladder access points.

The attic space was divided into two areas by a glue-lam beam at the roof level, which extended from the east to the west side of the building. Below this beam was a framed-in wall, which divided the attic space north and south of this beam into two separate compartments. There was at least one door on this wall, and based on fire effects observed, this door was closed at the time of the second fire.

Based on observations of increased charring on one side and a protected area on the other side, at several locations on the south side of this beam and wall, it appears that the fire originated on the south side of the beam and subsequently spread to the north side. Truss members approximately fourteen feet south of the D3/D4 wall also exhibited increased charring on one side of the vertical member, with a protected area on the other side. These fire

Preliminary Fire Investigation Report Narrative

Incident No: 250005016

Address: 1475 East Avenue, Chico, CA

Date: 4/25/2025

By: Ricketts, Paul

effects indicate that the fire originated near the D3/D4 wall and then moved west away from the wall.

The ceiling joist from the D3/D4 wall to approximately fourteen feet west of this wall had charring from the top of the ceiling joist down to the ceiling level. The ceiling joists west of this area had charring that was limited to the top portion of the joist.

The roof had an area of complete mass loss between the roof beams, which was approximately fourteen feet wide by ten feet long. This area extended north to south, from approximately two feet south of the glue-lam beam, south down the roof slope approximately ten feet, and east to west, from the D3/D4 wall to approximately fourteen feet west of this wall.

These fire effects indicate that the area of origin for the second fire was west of the D3/D4 wall and south of the glue-lam beam.

Based on the fire damage, it appears that the fire developed in the area of origin and moved north up the roof slope to the ridgeline. Once the fire reached the ridge line, the openings in the west and east side dormers supplied increased ventilation to the fire. The fire rapidly spread across the ridgeline and down the north and south slopes.

The gypsum board in the area of the first fire had been removed during overhaul, exposing unburnt wall studs and ceiling studs in this area. I was unable to find a direct conductive heat transfer path from the area of the first fire to the attic area where the second fire occurred.

Preliminary Fire Investigation Report Narrative

Incident No: 250005016

Address: 1475 East Avenue, Chico, CA

Date: 4/25/2025

By: Ricketts, Paul

Several ignition sources were found in the area of origin, including electrical conduits and electrical boxes. In addition, a conduit that originated at the electrical receptacle, which was a possible ignition source of the first fire, led to the top plate of the D3/D4 wall where the second fire's origin was located.

In the stud bay of the D3/D4 wall, where the conduit penetrates the top plate, there was an increase in charring above this top plate. The amount of charring decreased in the stud bays to the north and the south of this location. In addition, the plywood deck covering the ceiling joist adjacent to this stud bay was burned in a semicircle shape, with the centroid being the conduit that penetrates the top plate. These fire effects suggest that the point of origin of the second fire was likely the stud bay, where the conduit penetrates the top plate. However, due to the severe fire damage in the area, the point of origin cannot be definitively determined.

Conclusion

Based on witness information, fire effects, and fire dynamics, the area of origin was west of the D3/D4 wall and south of the glue-lam roof beam (see Figure 2). Based on the fire effects, the possible point of origin was in the stud bay on the D3/D4 wall, directly above the top plate where the conduit penetrates it (see Figures 2 & 3).

The cause of the fire remains undetermined, as multiple electrical ignition sources were present in the area of origin. Additionally, a fire occurred near this area three hours prior to this fire.

Preliminary Fire Investigation Report Narrative

Incident No: 250005016

Address: 1475 East Avenue, Chico, CA

Date: 4/25/2025

By: Ricketts, Paul

Fire crews performed an extensive overhaul of the first fire area. The gypsum board was removed from the walls and ceilings surrounding the original fire location, exposing the wood framing. There was no fire damage connecting the first fire area and the second fire area.

Two hypotheses of the cause of the fire cannot be ruled out. The first being that the conduit leading from the receptacle in the first fire's area of origin, to the top plate in the second fire's area of origin was energized by an electrical failure. This electrical event possibly caused both fires; however, the origin of the second fire was a smoldering fire that took more time to develop. This would require that the second fire was slow-developed and not apparent to firefighters during overhaul. Additionally, the fire was not sufficiently developed for the firefighters' thermal imaging cameras to detect the infrared radiation during the overhaul of the first fire.

The second hypothesis is that heat or an ember from the first fire transferred through the HVAC vent in the D3/D4 wall to the attic space. This hypothesis would also include that the second fire was a smoldering, slow-developing fire that was not detectable by firefighters during the overhaul of the first fire.

Based on the information obtained during my investigation, the cause of the fire classification remains undetermined.

Paul Ricketts, Fire Marshal of the Chico Fire Department, completed this fire investigation and report.

Preliminary Fire Investigation Report Narrative

Incident No: 250005016

Address: 1475 East Avenue, Chico, CA

Date: 4/25/2025

By: Ricketts, Paul

FIGURE 1 - SITE PLAN



Preliminary Fire Investigation Report Narrative


Incident No: 250005016

Address: 1475 East Avenue, Chico, CA

Date: 4/25/2025

By: Ricketts, Paul

FIGURE 2 - BUILDING PLAN



Preliminary Fire Investigation Report Narrative

Incident No: 250005016

Address: 1475 East Avenue, Chico, CA

Date: 4/25/2025

By: Ricketts, Paul


FIGURE 3 – POSSIBLE POINT OF ORIGIN



END OF REPORT










26.04.2025 12:45






26.04.2025 12:45




































26.04.2025 12:50



26.04.2025 12:50
















26.04.2025 12:51













26.04.2025 12:52



26.04.2025 12:52



26.04.2025 12:52




26.04.2025 12:52




































26.04.2025 12:54



26.04.2025 12:55



















































27.04.2025 13:05



27.04.2025 13:05













27.04.2025 13:05



27.04.2025 13:06













DP-H1K

DP-HG1

Building
E HS2

Panel D
B Building

CAUTION
Do Not Operate
[Handwritten notes]

M BLDG

Com
HS-4
d CS
Rated


[Small text and logo]


































































































































WOODEN MODELING TOOLS


Wooden Modeling Tools

Used to:

- Smooth out the clay
- Pinch together the clay where it is joined by slip and scoring
- Carve into the clay







WOODEN MODELING TOOLS

Wooden Modeling Tools

- Used to:
- Smooth out the clay
 - Pinch together the clay where it is joined by slip and scoring
 - Carve into the clay
 - Create texture



ing Tools
ring Tool
ed to:
Create grooves in the clay body in the
shape of a hash mark
Rough up the clay body so two separate
pieces of clay can be added together
with slip

WOODEN MODELING TOOLS

- Used to:
- Smooth out the clay
 - Pinch together the clay
 - Joined by slip and score
 - Carve into the clay
 - Create texture





N-31

Wooden Modeling Tools

Wooden Modeling Tools

Useful for:

- Smooth out the clay
- Press together the clay where it is joined by wire and scoring
- Score the clay
- Create texture





































































































Redaction Log

Reason	Page (# of occurrences)	Description
Public Interest	3 (1) 11 (1) 17 (2) 19 (1)	Gov. Code Sec. 7922.000 based on the facts of the particular case the public interest served by not disclosing the record clearly outweighs the public interest served by disclosure of the record.