Hazen, Liam; DNR, MEERTS Complaints NERO; DNR, EER Responders - NERO Initial Email - EER Incident, 221213-0757-LDH, Boone, Improper Disposal

Subject: Date:

Tuesday, December 13, 2022 9:59:36 AM

This information contained in this Environmental Emergency Response (EER) Incident Report has not undergone review and may contain grammatical and/or factual errors. It is intended to provide local officials with timely information of reported incidents. If you have any questions please contact the EER Spill-Line at 573-634-2436.

Incident Summary

The anonymous caller was reporting that an area that is currently inhabited by approximately 30 homeless people is full of solid waste and trash. The trash covers most of the inhabited area and has begun to be released into a creek that runs through the area and surrounding neighborhoods. This concern is being referred to the Department's Northeast Regional Office for further investigation.

Field Observation

Incident Information

Incident Number:

LDH

221213-0757- County:

Boone

Call Date:

12/13/2022

Call Time:

07:57

Job Code:

12/13/2022

Discovery Date:

12/13/2022

Incident Date: Incident Time:

07:57

Discovery Time: 07:57

Duty Officer:

Liam Hazen

Primary State On-Scene Coordinator:

No Responder

Location Description

Address:

Intersection of Highway 63 and Interstate 70

To the north of the intersection in the wooded area

Columbia, MO 65202

Latitude:

38.96768483

Longitude:

-92.29229179

Site Description

Property Use:

Public Property

Incident Cause:

Improper Disposal

Cleanup Actions:

Cleanup Contractor:

Threat Description

Chemical Name

Quantity Released

Tank #:

Solid Waste and Trash

Solid Waste-

Material

Referred

Other

Unknown Unknown

Medium Affected

River/Creek

Road/Highway/ROW

Special Cases Concern:

Yes

Continuous Air Release:

No

Fish Kill:

No

Petroleum Storage Tanks:

No

PSTIF Site:

Responsible Party Information

Name:

Unknown Unknown

Contact Telephone:

Company:

Unknown

Company Telephone:

Address:

United States

Email:

Caller Information

Name:

Anonymous

Contact Telephone:

Company:

Company Telephone:

Address:

Email:

Persons Notified Directly by Duty Officer

Name: /Company:

Date:

Time:

Telephone:

Additional Information Sources

24-hour Emergency Spill Line:

573-634-2436

Emergency Response Office:

573-526-3348

None.

https://dnr.mo.gov/env/esp/esp-eer.htm

Emails will be sent to: [Liam.Hazen@dnr.mo.gov, DNR.MEERTS_Complaints_NERO@dnr.mo.gov, DNR.EER_Responders_-_NERO@dnr.mo.gov]

DISCLAIMER: This email address is not monitored, please do not reply to this address. If you have questions, contact 573-634-2436.

Attachment #1 - Photographs City of Columbia December 13, 2022

Page 1 of 2



Photograph: #1.

Taken By: Steve Boone and Josh Hufford

Date Taken: December 13, 2022

Program: Solid Waste Management/Water

Pollution

Entity: City of Columbia **Permit:** No Permit

Location: N. of I-70 and Highway 63

intersection.

Description: View of property owned by City of Columbia from Highway 63 connector.

SMB



Photograph: #2.

Taken By: Steve Boone and Josh Hufford

Date Taken: December 13, 2022

Program: Solid Waste Management/Water

Pollution

Entity: City of Columbia **Permit:** No Permit

Location: N. of I-70 and Highway 63

intersection.

Description: View of litter and trash adjacent to

stream.

SMB



Photograph: #3.

Taken By: Steve Boone and Josh Hufford

Date Taken: December 13, 2022

Program: Solid Waste Management/Water

Pollution

Entity: City of Columbia

Permit: No Permit

Location: N. of I-70 and Highway 63

intersection.

Description: Shopping carts and other waste in

the stream.

SMB

Attachment #1 - Photographs City of Columbia December 13, 2022

Page 2 of 2



Photograph: #4.

Taken By: Steve Boone and Josh Hufford

Date Taken: December 13, 2022

Program: Solid Waste Management/Water

Pollution

Entity: City of Columbia

Permit: No Permit

Location: N. of I-70 and Highway 63

intersection.

Description: View from stream looking up at a

homeless encampment.

SMB



Photograph: #5.

Taken By: Steve Boone and Josh Hufford

Date Taken: December 13, 2022

Program: Solid Waste Management/Water

Pollution

Entity: City of Columbia **Permit:** No Permit

Location: N. of I-70 and Highway 63

intersection.

Description: A dryer found at the edge of a

stream.

SMB



Photograph: # 6.

Taken By: Steve Boone and Josh Hufford

Date Taken: December 13, 2022

Program: Solid Waste Management/Water

Pollution

Entity: City of Columbia

Permit: No Permit

Location: N. of I-70 and Highway 63

intersection.

Description: A view downstream of trash. At

least 3 shopping carts and other trash.

SMB