

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	2015029395	Report to All Drivers:	NO	At Intersection with:	"N/A"
Date of Acc:	05/31/15	Legal Intervention:	NO	Div HWay Trvl Dir:	"N/A"
Time of Acc:	15:25 Hrs.	Private Property:	NO	Distance 1:	"N/A"
Name of Agency:	IOWA STATE PATROL - DIST 16	County:	MARSHALL - 64	Direction 1:	"N/A"
Officer:	CORNWELL I	Acc Loc City:	MARSHALLTOWN - 4797	Distance 2:	"N/A"
Badge #:	045	Acc Dir From City:	"N/A"	Direction 2:	"N/A"
Report Date:	05/31/2015	Closest City:	"N/A"	X-Coordinate:	00499880
Officer Notified:	15:45 Hrs.	Miles From City:	"N/A"	Y-Coordinate:	04669378
Officer Arrived:	16:23 Hrs.	Road, Street, HWay:	"N/A"	Location Literal:	S075/MARSH AVE
Scene Investigated:	YES	Definable Location:	"N/A"	Description:	
		Milepost Number:	"N/A"		

Unit 001

Driver Name - Last:	GLENN	Bus Use:		Transported to:	MITCHELL FUNERAL HOME
First:	FRANK	Drvr Distractions:	02 - NOT DISTRACTED	Transported by:	MITCHELL FUNERAL HOME
Middle:	ABLERT	Traffic Controls:	01 - NO CONTROLS PRESENT	Special Veh Func:	01 - NO SPECIAL FUNCTION
Address:	2412 SAND RD	Point of Init Impact:	11 - FRONT DRIVER SIDE CORNER	Emergency Status:	01 - NOT APPLICABLE
City:	MARSHALLTOWN	Most Damaged Area:	11 - FRONT DRIVER SIDE CORNER	Cont. Circum., Drvr:	06 - LOST CONTROL, 16 - FAILED TO KEEP IN PROPER LANE
State:	IA	Undrrid/Ovrid:	4 - UNDERRIDE, COMPARTMENT INTENSION	Carrier Name:	
Zip:	50158-9558	Rpr/Rplc Cost:	\$10,000.00	Carrier Address:	
Suffix:	JR	Ext of Damage:	5 - SEVERE, VEHICLE TOTALED	Carrier City:	
Gender:	Male	First Event:	04 - CROSSED CENTERLINE (UNDIVIDED)	Carrier State:	
Age:	50	Second Event:	33 - VEHICLE IN TRAFFIC	Carrier Zip:	
CDL:	NO	Third Event:	70 - FIRE/EXPLOSION	Cargo Body Type:	01 - NOT APPLICABLE
License State:	IA	Fourth Event:		Number of Axles:	
License Class:	C	Most Harmful Event:	33 - VEHICLE IN TRAFFIC	HazMat Involvement:	
License Endorsmnt:	NONE	Abg Switch Stat:		HazMat Placard:	
License Restrictions:	NONE	Abg Deploy:	04 - DEPLOYED FRONT OF PERSON	Placard #:	
Speed Limit:	55	Trapped:	3 - EXTRICATED BY MECHANICAL	HazMat Released?:	
Seating Position:	01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Ejection:	2 - NOT EJECTED	Converter Dolly:	
Driver Condition:	01 - APPARENTLY NORMAL	Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE	GVWR:	
Alcohol Test Given:	YES	Occpnt Protect:	02 - NONE USED	Cit Chrg Code 1:	
Drug Test Given:	2 - BLOOD	Injury Status:	1 - FATAL	Citation Charge 1:	
Total Occupants:	1	Source of Trans:	07 - TO FUNERAL HOME/MORGUE	Cit Chrg Code 2:	
Vehicle Year:	2000	Died at Scene:	02 - DIED AT SCENE	Citation Charge 2:	
Vehicle Make:	FORD - FORD			Cit Chrg Code 3:	
Vehicle Model:	F-150			Citation Charge 3:	
Vehicle Style:	PICK UP			Cit Chrg Code 4:	
Vehicle Color:	BLUE - BLU			Citation Charge 4:	
Vehicle Config:	02 - FOUR-TIRE TRUCK (PICK-UP)				
Vehicle Defect:	01 - NONE				
Vehicle Action:	01 - MOVEMENT ESSENTIALLY STRAIGHT				
Tow:					
Tow #:					
Initial Trvl Dir:	01 - NORTH				
Vision Obscured:	01 - NOT OBSCURED				

Unit 002

Driver Name - Last: AKERS	Bus Use:	Transported to:
First: DAVID		
Middle: EUGENE	Drvr Distractions: 01 - NOT APPLICABLE/NO DRIVER	Transported by: EMS
Address: 2453 DOLE DR		
City: ELDORA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
State: IA		
Zip: 50627	Point of Init Impact: 11 - FRONT DRIVER SIDE CORNER	Emergency Status: 01 - NOT APPLICABLE
Suffix:	Most Damaged Area: 11 - FRONT DRIVER SIDE CORNER	Cont. Circum., Drvr: 88 - NO IMPROPER ACTION
Gender: Male	Undrriid/Ovrid: 4 - UNDERRIDE, COMPARTMENT INTRUSION	
Age: 39	Rpr/Rplc Cost: \$10,000.00	
CDL: NO	Ext of Damage: 5 - SEVERE, VEHICLE TOTALED	
License State: IA	First Event: 33 - VEHICLE IN TRAFFIC	
License Class: C		Carrier Name:
License Endorsmnt: NONE		Carrier Address:
License Restrictions: NONE	Second Event:	Carrier City:
Speed Limit: 55	Third Event:	Carrier State:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Fourth Event:	Carrier Zip:
Driver Condition: 01 - APPARENTLY NORMAL		Cargo Body Type: 01 - NOT APPLICABLE
Alcohol Test Given: NO	Most Harmful Event: 33 - VEHICLE IN TRAFFIC	Number of Axles:
Drug Test Given: 1 - NONE	Abg Switch Stat: 04 - DEPLOYED FRONT OF PERSON	HazMat Involvement:
Total Occupants: 4	Abg Deploy:	HazMat Placard:
Vehicle Year: 2011	Trapped: 3 - EXTRICATED BY MECHANICAL	Placard #:
Vehicle Make: FORD - FORD	Ejection: 2 - NOT EJECTED	HazMat Released?:
Vehicle Model: EXPEDITION	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Converter Dolly:
Vehicle Style: SUV	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	GVWR:
Vehicle Color: BLACK - BLK	Injury Status: 2 - SUSPECTED SERIOUS/INCAPACITATING	Cit Chrg Code 1:
Vehicle Config: 03 - SPORT UTILITY VEHICLE	Source of Trans: 03 - EMS GROUND	Citation Charge 1:
Vehicle Defect: 01 - NONE	Died at Scene: 01 - NOT APPLICABLE	Cit Chrg Code 2:
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT		Cit Chrg Code 3:
Tow:		Citation Charge 3:
Tow #:		Cit Chrg Code 4:
Initial Trvl Dir: 03 - SOUTH		Citation Charge 4:
Vision Obscured: 01 - NOT OBSCURED		

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 02 - HEAD-ON (FRONT TO FRONT)	Environment: 01 - NONE APPARENT
Light Conditions: 1 - DAYLIGHT	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	
	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions: 01 - DRY	
	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 33 - VEHICLE IN TRAFFIC
Type:	
Workers Present:	

Injured Person

Name - Last: BUCHANAN	Airbag Deployment: 04 - DEPLOYED FRONT OF PERSON
First: GEOFFREY	
Middle: ALLEN	Airbag Switch Status:
Suffix:	Trapped: 1 - NOT TRAPPED/APPLICABLE
Address: 101 E CHESTNUT	Injury Status: 3 - SUSPECTED MINOR/NON-INCAPACITATING
City: HUBBARD	Ejection: 2 - NOT EJECTED
State: IA	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE
Zip Code: 50122	Alcohol Test Given:
Age: 35	Drug Test Given:
Sex: MALE	Source of Transport: 03 - EMS GROUND
Unit No.: 001	Died at Scene/Enroute: 01 - NOT APPLICABLE
Seating Position: 03 - 1ST ROW: RIGHT SIDE	Transported to: CENTRAL IOWA HEALTH CARE
Occupant Protection: 03 - SHOULDER AND LAP BELT USED	Transported by: EMS

Injured Person

Name - Last:	LAWRENCE	Airbag Deployment:	05 - DEPLOYED SIDE OF PERSON
First:	HALEY	Airbag Switch Status:	
Middle:	ANN	Trapped:	1 - NOT TRAPPED/APPLICABLE
Suffix:		Injury Status:	3 - SUSPECTED MINOR/NON-INCAPACITATING
Address:	22379 220TH ST	Ejection:	2 - NOT EJECTED
City:	ELDORA	Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE
State:	IA	Alcohol Test Given:	
Zip Code:	50627	Drug Test Given:	
Age:	18	Source of Transport:	03 - EMS GROUND
Sex:	FEMALE	Died at Scene/Enroute:	01 - NOT APPLICABLE
Unit No.:	002	Transported to:	CENTRAL IOWA HEALTH CARE
Seating Position:	06 - 2ND ROW: RIGHT SIDE	Transported by:	EMS
Occupant Protection:	03 - SHOULDER AND LAP BELT USED		

Injured Person

Name - Last:	DILLEY	Airbag Deployment:	05 - DEPLOYED SIDE OF PERSON
First:	HALEY	Airbag Switch Status:	
Middle:	KAY	Trapped:	1 - NOT TRAPPED/APPLICABLE
Suffix:		Injury Status:	3 - SUSPECTED MINOR/NON-INCAPACITATING
Address:	205 MAY ST	Ejection:	2 - NOT EJECTED
City:	RADCLIFFE	Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE
State:	IA	Alcohol Test Given:	
Zip Code:	50230	Drug Test Given:	
Age:	18	Source of Transport:	03 - EMS GROUND
Sex:	FEMALE	Died at Scene/Enroute:	01 - NOT APPLICABLE
Unit No.:	02	Transported to:	CENTRAL IOWA HEALTH CARE
Seating Position:	04 - 2ND ROW: LEFT SIDE	Transported by:	EMS
Occupant Protection:	03 - SHOULDER AND LAP BELT USED		

Narrative

Unit 1 was traveling north bound on marsh ave when it crossed the center line and struck unit 2. Initial contact was made on the front drivers side corners of both unit 1 and unit 2. After the vehicles made contact they spun counter clockwise from the force of the impact and unit 2 ended up in the ditch on the west side of the street. While unit 2 stayed on the east side of the road and caught fire.

Diagram

