

Water Quality Noncompliance Notification

Unauthorized Discharge

Reportable Effluent Violation

Other

General Information

Entity Name: City of Victoria.

Telephone No: (361-485-3263)

Permittee Subscriber

TCEQ Region: 14

County: Victoria

Permit Number*: WQ0010466002

Noncompliance Summary

Description of Noncompliance (include location, discharge route, and estimated volume if an unauthorized discharge):

The Primary treatment structure bar screen faulted and caused an overflow of approximately 1500 gallons of raw sewage. The spill was contained within the plant property.

Cause of Noncompliance:

Bar screen faulted and allowed the rags to build up on the screen causing and overflow of the channel.

Duration:

Start Date and Time: Unknown

End Date and Time: 9-10-22 0915

Or Date Expected to be Corrected:

Potential Danger to Human Health and Safety or the Environment:

Minimal.

Actions Taken

Monitoring Data: Data should be attached or submitted to TCEQ when available.

Yes No Field Measurements

Yes No Laboratory Samples

Yes No Fish Kill If yes, estimated number killed:

Actions Taken to Mitigate Adverse Effects:

The Operator immediately reset the screen and washed as much as possible back into the channel. The operator picked up any trash that was accumulated. Any liquid that had ran off the structure was treated with calcium hypochlorite granules.

Actions Taken to Correct the Problem and Prevent Recurrence:

I will have the Instrumentation tech determine why the screen faulted and repair as needed.

I will also generate a memo to Operations staff to monitor this area more frequently.

Verification Information

Information Reported By (Name/Title):